

**COMFORTDELGRO
ENGINEERING**

Our Job Ref No : 305523065
Date 25.07.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr TAUFIKH
Vehicle Reg No. SH 8094J Date of Accident : 17.07.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SKP9978E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,009.28
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost \$1,639.28**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : *taufikh*
Name : TAUFIKH
Date : 5/9/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305523605
REGN NO : SH 8094J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 18.07.2022 13:00
ACCIDENT DATE : 17.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16
0004 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0005 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00
0006 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	0.20	50.00

SUB-TOTAL : 1,009.28

JOB NATURE

0000 L	PANEL BEAT (SH 8094J)TP	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 630.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305523605
REGN NO : SH 8094J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 18.07.2022 13:0
ACCIDENT DATE : 17.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,639.28

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO