

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTOMOTIVE EN	GRG. & MGT. DIVISION (TP)	Re	f: CS/SPF22006862/Kcy3e2	
	ACCIDENT CLAIM (SPORE POLICE F POLICE LOGISTIC 1 HEMMANT ROA	FORCE)	Da	te: 19/09/2022	
	ATTN: HAFIZUL F	ARHAN	Co	de: SPF	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	QX 469D	Veh. Inspected	SMK 9244S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	ACS/105/009/2022/044	Excess (\$)	0.00	
	Assign From	HAFIZUL FARHAN	Assign Date	19/07/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA JAZZ (A)	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JHMGK5850KS204634	Colour	METALLIC GREY	
	Odometer	23225 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/55 R16	DUNLOP	7 mm	
	L/H Front Tyre	185/55 R16	DUNLOP	7 mm	
	R/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
	L/H Rear Tyre	185/55 R16	YOKOHAMA	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	18/07/2022	Inspection Date	10/08/2022	
	Survey held at	Survey held at LIM YEW BOO SPRAY PAINT CO			
		BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: