

ASS. REC. BY: thuanREF: CS/TMI 22006879/Vg³

ASSIGNMENT

CDB March 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH654SM Yr Regn: March 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai 540 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp.Reading: 865373 T/Radio: Insured / Std / NI / NAEng/No: D4FDHU723180C/No: KMHLD41UMG085566

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WootakeFront 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 19/07/2022 D.O.I. 20/07/2022Survey held at CDGB

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

To Lio PD 109KUS \$ 2800, 2 days chd to 988.16, 26%

Date/Time, File Pass to?

11/4/23 thuan

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: NER-TPLump Sum / I.B.A. (\$) 2800

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jul 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH6545M/19/07/2022 15:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH	20.00	0.00	DT / *2,707.70 FL
2	1		*WING MIRROR RH	20.00	0.00	Br / *670.00 FL
3	1		*FRONT DOOR ADVERTISEMENT STICKER RH	0.00	0.00	nc / *100.00 F
4	1		*FRONT DOOR COMFORTDELGRO RH	0.00	0.00	nc / *75.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,552.70
- List Item Discount on L Items (S\$)	675.54

Total Parts (S\$)	2,877.16
-------------------	----------

ComfortDelGro Engineering Pte Ltd/SH6545M/19/07/2022 15:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

SH 6545M

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

280 400.00

2 SPRAY PAINTING

New

300 ~~280~~ 400.00

3 TUFF KOTE

New

30 60.00

4 CHECK WIRING

New

30 40.00

Gross Labour Cost (S\$)

900.00

ComfortDelGro Engineering Pte Ltd/SH6545M/19/07/2022 15:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Therun

82235769

20/8/22

1600

L/S 2 dayswp

L/S 28001,

2 dgt