

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA3499A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Jul 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU397951
Chassis No.:	KMHC851CVLU186585
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,695.00
Original Registration Date:	22 Oct 2019
First Registration Date:	22 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$12,973.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2027
PARF Rebate Amount:	\$9,729.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,460.00
COE Rebate Amount:	\$16,068.00
Total Rebate Amount:	\$25,797.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Jul 2022

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/07/2022 16:16 (SGT)
Reported by	Driver
Date of Accident	16/07/2022 07:45 (SGT)
Exact Location of Accident	Upper Jurong Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3499A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-86985508
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2419138

DRIVER

Name of Driver	TAN KENG GUAN
NRIC No	SXXXX615E
Date Of Birth	15/01/1963
Occupation	Outdoor



Date Of Driving Pass	12/02/1981
Driving experience	41 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86985508
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 407 SEMBAWANG DRIVE #09-806
Address complement	-
Postcode	750407
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF DRIVER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Sembawang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005549999
Police Station Address	4 Sembawang Crescent Singapore 757633
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE POLICE REPORT T/20220716/2029

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM9027S
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJR42R
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	GBC5484P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TAN KENG GUAN
Gender	Male
Phone No	(Phone) +65-86985508
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SUFFER INJURY ON THE LEFT KHEE
Injured person in which vehicle?	SHA3499A



Were seat belts worn?

Yes

Was this injured conveyed to hospital by ambulance?

Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

A-SHA3499A

B-SMM9027S

C-SJR42R

D-GBC5484P


Driver's Signature (if driver is not the policyholder) / Date & Time

18-07-2022

1410HRS

Witnessed by Reporting Centre Personnel

Ky - Young



Describe Circumstances of the Accident

REFER TO POLICE
REPORT
T/20220716/2029

Declaration

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

18-07-2022 1415HRS

Witnessed by Reporting Centre
Personnel



Ryan Wong



SINGAPORE POLICE FORCE



T/20220716/2029

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20220716/2029

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/07/2022 12:02	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN KENG GUAN			Address: APT BLK 407 SEMBAWANG DRIVE #09-806 SINGAPORE 750407	
ID Type / ID No.: NRIC NO / S1592615E			Contact No.: Home/Office: Mobile: 86985508	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 59	Date of Birth: 15/01/1963	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Taxi Driver			Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/07/2022 07:45	Type of Location: Straight Road
Location: UPPER JURONG ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC5484P	Van	TOYOTA		White		0
SHA3499A	Car	HYUNDAI		Blue	Seriously Damaged	1
SJR42R	Car	HONDA		White		0
SMM9027S	Car	TOYOTA		Silver		0



SINGAPORE POLICE FORCE



T/20220716/2029

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

2 of 3

Report No. T/20220716/2029

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN KENG GUAN	ID No.	S1592615E
Related Vehicle	SHA3499A (Car)	Contact No.	86985508
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	16/07/2022	Date Discharge	16/07/2022
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the 16/07/2022 at about 0745hrs, I was driving my blue Hyundai Ioniq taxi bearing plate SHA3499A on the left most lane of Upper Jurong Road queuing to turn into SAFTI MI. At that point of time, there was a long queue of vehicle waiting to turn into SAFTI MI. Out of the sudden, I felt an impact on the rear of my vehicle which caused my vehicle to knock into the vehicle n front of me.

I went down to take a look and took some photos. A White Toyota bearing GBC5484P have rear ended my vehicle and caused my vehicle to rear end a White Honda Civic bearing plate SJR42R in front of me, it also caused the Honda Civic to rear end a Silver Toyota bearing plate SMM9027S. Shortly after, ambulance came over and conveyed me to Ng Teng Fong Hospital. I was discharged on the same day and was given 05 days of MC from 16/07/2022 to 20/07/2022. After which, I was contacted by TP to inform me that my vehicle has been towed back to TP compound and told me to lodge a traffic report regarding the accident.

I would like to state that I suffer injury such as pain on my left knee. My vehicle suffer dents on the rear boot and bumper area and dents on the front bumper area.



**SINGAPORE
POLICE FORCE**



T/20220716/2029

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20220716/2029

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

L /

SGT 3 WU JUNRONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

16/07/2022 12:02

Officer In Charge Of Case:

TP / GIT /

INSP (1) THABAGESH JEYATHESH

Contact No.: 65476178

Classification Of Case:

NP168

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 25-Jul-22

INSURANCE: First Capital

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3499 A

Description	Qty	List Price	Amount
Radiator Grille NEW MODEL <i>broken</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>mounty broken</i>	2	\$ 824.60	\$ 1,649.20
Speaker Assy-VESS <i>mounty broken</i>	1	\$ 554.40	\$ 554.40
Unit Assy-SMART CRU (Radar Sensor) <i>HH</i>	1	\$ 3,061.40	\$ 3,061.40
Front Number Plate garnish <i>crack/damaged</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>turn</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>turn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>Dambl</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>bt</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>svc</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>mounty broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>2 HH</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>HH</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>damaged / broken</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>damaged / cut</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HH</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>HH</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>HH</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HH</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH/RH) <i>Size 0 / 5 cut H/HH</i>	2	\$ 186.90	\$ 373.80
Front bumper air duct (LH/RH) <i>HH</i>	2	\$ 153.80	\$ 307.60
Day Light ,LH <i>HH</i>	1	\$ 642.50	\$ 642.50
Day Light , RH <i>mounty broken</i>	1	\$ 642.50	\$ 642.50
BUZZER ASSY - PIEZO (LH) <i>HH</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>broken / crack</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH/RH) <i>broken / crack 2110-30 x 2</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>HH</i>	2	\$ 72.80	\$ 145.60
Radiator Inverter <i>bt</i>	1	\$ 884.80	\$ 884.80
Radiator <i>bt</i>	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy <i>broken</i>	1	\$ 1,459.60	\$ 1,459.60
Radiator Air Guard (LH/RH) <i>HH</i>	2	\$ 76.40	\$ 152.80
Radiator Air Guard, Upr (LH/RH) <i>HH</i>	2	\$ 127.50	\$ 255.00
Aircon Condenser <i>bt</i>	1	\$ 663.60	\$ 663.60
Wiper Container ASSY <i>HH</i>	1	\$ 385.40	\$ 385.40
Boot Lid <i>Buc</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>damaged</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>legu</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>Dam</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00

[illegible]

4,220.60

✓ 2480.40

✓ 19,851.90

Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30
Rear Spoiler <i>broken</i>	1	\$ 665.40	\$ 665.40
Third Brake Light <i>broken</i>	1	\$ 385.60	\$ 385.60
BOOT HANDLE <i>S/L</i>	1	\$31.80	\$31.80
Boot Lid Lamp(LH/RH) <i>broken</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>mostly broken</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>Hec</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>mostly broken</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>damaged / mostly broken</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>Hec</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass, Upper <i>shattered</i>	1	\$ 907.20	\$ 907.20
Boot Lid Glass, Lower <i>shattered</i>	1	\$ 584.90	\$ 584.90
Rear Bumper <i>Buc</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>Dent</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>broken</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>mostly broken</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>broken</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>Hec</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>o/s broken n/s H/H</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>mostly broken</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>broken / damaged</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>Hec</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>o/s destroyed n/s H/H</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>destroyed</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>broken</i> <i>broken</i>	1	\$ 193.53	\$ 193.53
Licence Lamp WIRE <i>socket broken</i>	1	\$ 135.80	\$ 135.80
Tail Lamp(LH/RH) <i>broken</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>o/s Dent n/s H/H</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>Buc</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>mostly broken</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>damaged</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>st / broken</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>Hec</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>Buc</i>	1	\$ 892.50	\$ 892.50
Member Assy-Rear Floor Centre <i>leg</i>	1	\$ 863.50	\$ 863.50
Panel Assy-Rear Floor Side (LH/RH) <i>o/s Dent n/s H/H</i>	2	\$ 39.40	\$ 78.80
Rear tray tools box RH <i>broken</i>	1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>broken</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>broken</i>	1	\$ 354.20	\$ 354.20
Exhaust Pipe Insulator <i>st / broken</i>	1	\$ 235.00	\$ 235.00
Exhaust Silencer <i>Dent</i>	1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>Hec</i>	1	\$ 29.20	\$ 29.20
Rear Fender(LH/RH) <i>o/s Dent n/s leg</i>	2	\$ 1,768.30	\$ 3,536.60
Rear Fender SHIELD REAR PIECE (LH/RH) <i>Hec</i>	2	\$ 173.60	\$ 347.20
Rear Fender SHIELD Frt Piece (LH/RH) <i>Hec</i>	2	\$ 165.50	\$ 331.00
Rear Fender Corner inner upper garnish (LH/RH) <i>Hec</i>	2	\$ 486.70	\$ 973.40
Rear Fender Air-Duct (LH/RH) <i>o/s damaged n/s H/H</i>	2	\$ 87.30	\$ 174.60
Rear Fender Trim Board (LH/RH) <i>st / damaged</i>	2	\$788.75	\$ 1,577.50
REAR FENDER TRIM BOARD TOP GARNISH (LH/RH) <i>n/s H/H</i>	2	\$167.90	\$ 335.80
Assy BSD Blind Spot Radar (LH/RH) <i>mostly st o/s damaged</i>	2	\$ 1,784.40	\$ 3,568.80

H/S H/H o/s mostly st

21,791.23

SUB TOTAL				\$ 59,731.33
LESS 20%				\$ 11,946.27
DISCOUNTED TOTAL				\$ 47,785.06
Front Number Plate <i>white</i>	SN	1	\$ 25.00	\$ 25.00
Front No Plate Trim Cover <i>white</i>	SN	1	\$ 30.00	\$ 30.00
COOLANT <i>4m</i>	SN	1	\$ 45.00	\$ 45.00
Reverse camera ASSY <i>Done 4m</i>	SN	1	\$983.20	\$983.20
Boot Lid Comfort Cablink Tel No. Sticker <i>huc</i>	SN	1	\$ 30.00	\$ 30.00
Boot Lid Advertisement Logo <i>huc</i>	SN	1	\$ 100.00	\$ 100.00
Rear No. Plate + Trim Cover <i>dislodged broken</i>	SN	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>huc</i>	SN	2	\$ 46.00	\$ 92.00
Rear Bumper Advertisement Logo <i>huc</i>	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat <i>dislodged</i>	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>Done</i>	SN	1	\$ 180.00	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON <i>huc</i>	SN	1	\$ 250.00	\$ 250.00
Rear Fender Advertisement Logo (LH/RH) <i>huc</i>	SN	2	\$ 100.00	\$ 200.00
SUB TOTAL				\$ 2,080.20
Labour Charge				
Panel Beating	1	\$2,600.00	\$2,600.00	
Spray Painting Charge	1	\$2,400.00	\$2,400.00	
Wiring Charge	1	\$100.00	\$100.00	
Tuff Kote	1	\$100.00	\$100.00	
Towing Charge	1	\$80.00	\$80.00	
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00	
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	
Remove/Refix Radiator	1	\$90.00	\$90.00	
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	\$550.00	
TOTAL LABOUR				\$7,270.00
ESTIMATE TOTAL				\$57,135.26

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_itr@bifrostauto.com

Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

41,643.13

33,314.50

451-

X

X

✓

✓

✓

✓

✓

✓

✓

✓

✓

872.00

=

1400/-

1400/-

30/-

40/-

4m

80/-

80/-

40/-

4m

60/-

50/-

80/-

120/-

3410.00

=

25/07/2022 < 1100m

Not Answered

4/sum 16 days

9 ym

2cc Auto

37,596.50

Supp 4,824.16

42,420.66

4/5 33,900/-

BIFROST AUTO PTE LTD

SUPPLEMENTARY

DATE: 28-Jul-22

INSURANCE: First Capital

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3499 A (S)

Description	Qty	List Price	Amount
Electronic Clutch Pump <i>crank</i>	1	\$ 4,386.50	\$ 4,386.50
Spare Tyre Panel UNDER CENTRE PANEL <i>rm</i>	1	\$ 338.80	\$ 338.80
Spare Tyre Panel UNDER SIDE PANEL (LH/RH) <i>rm</i>	2	\$ 239.80	\$ 479.60
Rear Crossmember <i>rt</i>	1	\$ 1,468.70	\$ 1,468.70
SUB TOTAL			\$ 6,673.60
LESS 20%			\$ 1,334.72
DISCOUNTED TOTAL			\$ 5,338.88
Clutch Fluid <i>rm</i> SN	1	\$ 85.00	\$ 85.00
SUB TOTAL			\$ 85.00
Labour Charge			
Replace rear cross member	1	\$400.00	\$400.00
Four Wheel Alignment	1	\$120.00	\$120.00
TOTAL LABOUR			\$520.00
ESTIMATE TOTAL			\$5,943.88

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

28/07/2022 e 1000m

HA Subur

[Signature]

2kk dub

4824.46

5855.20
4,684.16

80/-
60/-

140.00