

ASS. REC. BY: TaufikREF: CS/CT122006897/7cy3**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$20K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 9BB 43635Yr Regn: 21.4, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350c.c. 2488Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 26025

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SM/MC/2670002552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/RTR: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habibead

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 21/7/22Survey held at Yong Sing

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16.08.2022 Taufik confirmed LS \$1,600.00 ; 5 days with Ms Lau thru email.
(Red. \$9,033.71 ; 82%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Rep. Format: TP

Lump Sum

L.B. /

\$1,600.00

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL


Yong Sing Estimate Repair

Section A - To be completed by Claims Advisor

Vehicle Registration Number : GBB4363S
Make / Model : NISSAN NV350 PANEL VAN 2.5
Chassis No : JN1MC2E26Z0002552
Year of Manufacture : 2014
Registration Date : 14-Jul-14
Type of Repair (TP/OD/VS) : THIRD-PARTY
Date/Time of Accident : 11/07/2022 14:50:00 PM
Rental Vehicle : Yes / No
Remark :

Case Ref. No. :

The damages on the vehicle are as indicated in the following diagram :



	Yong Sing estimate breakdown cost		Adjusted by Surveyor, if applicable	
Total Labour Cost	\$	2,150.00	\$	-
Total Spray Painting Cost	\$	1,280.00	\$	-
Total Spare Parts Cost	\$	6,506.47	\$	-
Other Charges	\$	350.00	\$	-
TOTAL	\$	10,266.47	\$	-
		Lump Sum Repair, if any :	\$	-
No. of Repair Days	[12]	days	[]	days

Part 4 - Spare Parts / Material Usage

[illegible]

Surveyor Remark:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
REPAIR AND REPLACE REAR RH PORTION DAMAGE PARTS DUE TO ACCIDENT	\$2,000.00	600
REMOVE AND REFIT REAR INNER TRIM TO FACILITATE THE REPAIR	\$150.00	60
Total Labour Cost	\$2,150.00	

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
PUTTY AND RESPRAY REAR RH PORTION	\$1,200.00	200
APPLY ANTI - COROSION SEALANT	\$80.00	30
Total Spray Painting Cost	\$1,280.00	

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
WHEEL ALIGNMENT	\$100.00	80
REMOVE REFIT REAR RH UNDERCARRIAGE	\$250.00	
Total Other Costs	\$350.00	

Tanpin 97495749 / 62583550
WP 21/7/22 @ 1130
Tanpin@lkkauto.com
5 days
1/3 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: