

ASSIGNMENT

From: PRS Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YR 45231 Yr Regn: 1
 Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mitsubishi Fighter c.c. 7505
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 4535 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: F-M65FMAA0101
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 295/80R 175
 R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 15/7/22 D.O.I. 3/8/22
 Survey held at LYS
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear LH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

06.09.2022 Submit PRS, repair range \$1,000.00 - \$2,000.00 ; 4 days

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

2)

Report Format: PRS

Lump Sum / I.B.R. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)