



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                        |  |           |
|--|---|------------------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |   |                        | Ref: CS/AGI22006907/Any3e2<br>Date: 12/10/2022 | Code: AGI |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                        |  |           |
| <b>Insured Veh.</b>  | SMF 1928G   | <b>Veh. Inspected</b>  | GR 76D   |           |
| <b>Policy No.</b>  | P10468458R01  | <b>Coverage (\$)</b>   | 0.00   |           |
| <b>Claim No.</b>   | C10016404/JY  | <b>Excess (\$)</b>     | 0.00   |           |
| <b>Assign From</b>   | SALIZAWATI HAIZAR   | <b>Assign Date</b>     | 20/07/2022                                     |           |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                        |  |           |
| <b>Make &amp; Model</b>  | NISSAN NV350  | <b>c.c</b>             | 2488   |           |
| <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>    | 2017   |           |
| <b>Chassis No.</b>   | JN1MC2E26Z0008535   | <b>Colour</b>          | BLACK  |           |
| <b>Odometer</b>  | 96231 KM  | <b>Steering</b>        | IN ORDER                                       |           |
| <b>Brakes</b>  | IN ORDER  | <b>Modification</b>    | NIL  |           |
| <b>General</b>   | GOOD  |                        |  |           |
| <b>3. Conditions of Tyres</b>  |   |                        |  |           |
|  | <b>Size</b>   | <b>Make</b>            | <b>Balance</b>                                 |           |
| <b>R/H Front Tyre</b>  | 195/80 R15  | DUNLOP                 | 6 mm   |           |
| <b>L/H Front Tyre</b>  | 195/80 R15  | DUNLOP                 | 6 mm   |           |
| <b>R/H Rear Tyre</b>   | 195/80 R15  | DUNLOP                 | 6 mm   |           |
| <b>L/H Rear Tyre</b>   | 195/80 R15  | DUNLOP                 | 6 mm   |           |
| <b>4. Description of Damages</b>   |   |                        |  |           |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                        |  |           |
| <b>5. General Information</b>  |   |                        |  |           |
| <b>Accident Date</b>   | 17/07/2022  | <b>Inspection Date</b> | 21/07/2022                                     |           |
| <b>Survey held at</b>  | SIN HWEE MOTOR PTE LTD<br>BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717 |                        |  |           |
| <b>5a. Remarks</b>   |   |                        |  |           |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |   |                        |  |           |
| <b>5b. Estimate Days of Repair</b>   |   |                        |  |           |
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>   |   |                        | <b>5 Working Days</b>                          |           |