

Your Ref: 19/19/19/VC01/297598

Date: 03rd August 2022

Our Ref: CS1/LPM22006909/Uqy3m4

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKS 3137P

INSURED VEHICLE: BJX 6042

ACCIDENT DATE: 05/11/2019

We thank you for your instruction on 18/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKS 3137P from M/s Constant Appraiser Services.
- b) Polis Diraja Malaysia Report of Vehicle SKS 3137P.
- c) Colour damaged vehicle photographs of SKS 3137P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKS 3137P
Make & Model	: Honda City 1.5 SV CVT
Chassis Number	: MRHGM6660EP000341
Year of Registration	: 2015
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.