



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                                                              |            |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|--------------------------------------------------------------|------------|
| HSBC LIFE (SINGAPORE) PTE LTD<br>10 MARINA BOULEVARD<br>#48-01 MARINA BAY FINANCIAL CENTRE TOWER<br>2SINGAPORE 018983<br>ATTN:GARNET   |                                                                                           | Ref: CC4/ASM22006916/Apa3q2<br>Date: 18/05/2023<br>Code: HSB |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                                                              |            |
| Insured Veh.                                                                                                                           | SHA 6931Z                                                                                 | Veh. Inspected                                               | SKC 1258X  |
| Policy No.                                                                                                                             | P2465679                                                                                  | Coverage (\$)                                                | 0.00       |
| Claim No.                                                                                                                              | S2M04DSE                                                                                  | Excess (\$)                                                  | 0.00       |
| Assign From                                                                                                                            |                                                                                           | Assign Date                                                  | 20/07/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                                                              |            |
| Make & Model                                                                                                                           | KIA CERATO                                                                                | c.c                                                          | 1591       |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.                                                 | 2019       |
| Chassis No.                                                                                                                            | KNAF3416MK5023102                                                                         | Colour                                                       | BLACK      |
| Odometer                                                                                                                               | 31816 KM                                                                                  | Steering                                                     | IN ORDER   |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification                                                 | SPORTS RIM |
| General                                                                                                                                | GOOD                                                                                      |                                                              |            |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                                                              |            |
|                                                                                                                                        | Size                                                                                      | Make                                                         | Balance    |
| R/H Front Tyre                                                                                                                         | 225/45 R17                                                                                | KUMHO                                                        | 6 mm       |
| L/H Front Tyre                                                                                                                         | 225/45 R17                                                                                | KUMHO                                                        | 6 mm       |
| R/H Rear Tyre                                                                                                                          | 225/45 R17                                                                                | KUMHO                                                        | 6 mm       |
| L/H Rear Tyre                                                                                                                          | 225/45 R17                                                                                | KUMHO                                                        | 6 mm       |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                                                              |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                           |                                                              |            |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                                                              |            |
| Accident Date                                                                                                                          | 13/07/2022                                                                                | Inspection Date                                              | 21/07/2022 |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                                                              |            |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                                                              |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                                                              |            |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                                                              |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           | 5 Working Days                                               |            |