

ASS. REC. BY:

REF:

C72/22006918/KG

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

01/24

Person Contacted:

Vehicle: IN / OUT

Ken

Veh No:

SMG 7512C

Yr Regn:

01, 0.9

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Crosroad

c.c

1997

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

187824

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RT 3

1005407

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

19/7/22

D.O.I.

21/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/9 11pm @ 2800d Cash (Red. 6251, 6920)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

\$2800d

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 207E

### Vehicle Details

Vehicle No.: SMG7512C  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 19 Jul 2022  
Vehicle Make: HONDA  
Vehicle Model: CROSSROAD 2.0X A  
Primary Colour: Blue  
Manufacturing Year: 2008  
Engine No.: R20A3008050  
Chassis No.: RT31005407  
Maximum Power Output: 110.0 kW (147 bhp)  
Open Market Value: \$19,982.00  
Original Registration Date: 06 Jan 2009  
First Registration Date: 06 Jan 2009  
Transfer Count: 3  
Actual ARF Paid: \$19,982.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 05 Jan 2024  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$15,668.00  
COE Rebate Amount: \$4,582.00  
**Total Rebate Amount: \$4,582.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jul 2022

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	19/07/2022 16:48 (SGT)
Reported by	Both
Date of Accident	19/07/2022 13:30 (SGT)
Exact Location of Accident	Woodlands Ave 12, Singapore
Additional Location Information	WOODLANDS AVENUE 12
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG7512C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	OO AIK TUAN
NRIC No	SXXXX207E
Email Address	aiktuan@gmail.com
Mobile Phone No	(Phone) +65-98227380
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Crossroad
Variant	1.8A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1800

### INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10491396R01

### DRIVER

Name of Driver	OO AIK TUAN
NRIC No	SXXXX207E
Date Of Birth	19/10/1978
Occupation	Outdoor



Date Of Driving Pass	09/12/2015
Driving experience	6 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98227380
Alt. Phone Number	-
Email Address	aiktuan@gmail.com
Address	317 SEMBAWANG VISTA #07-215
Address complement	-
Postcode	750317
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL5265P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

Describe Circumstance of the Accident

On 19/07/2022 around 1330hrs, I was driving along  
Woodlands Avenue 12 suddenly a car (SL 5265P) Rear ended my  
car when I stop at the traffic light.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-378

DATE : 19-Jul-2022

POLICY NO. : P10491396R01

VEHICLE REG. NO. : SMG7512C

VEHICLE MAKE : HONDA CROSSROAD 2.0X A

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Bumper <i>1134</i>	<i>Buolcm</i> 1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips	<i>nn</i> 10	\$ 5.00	\$ 50.00
3	Rear Bumper Upper Retainer RH	<i>nn</i> 1	\$ 40.00	\$ 40.00
4	Rear Bumper Upper Retainer LH	<i>nn</i> 1	\$ 40.00	\$ 40.00
5	Rear Bumper Lower Retainer RH	<i>nn</i> 1	\$ 38.00	\$ 38.00
6	Rear Bumper Lower Retainer LH	<i>nn</i> 1	\$ 38.00	\$ 38.00
7	Rear Bumper Side Cover RH	<i>nn</i> 1	\$ 250.00	\$ 250.00
8	Rear Bumper Side Cover LH	<i>nn</i> 1	\$ 250.00	\$ 250.00
9	Rear Bumper Reflector RH	<i>nn</i> 1	\$ 100.00	\$ 100.00
10	Rear Bumper Reflector LH	<i>nn</i> 1	\$ 100.00	\$ 100.00
11	Rear Tow Eye Cover	<i>nn</i> 1	\$ 80.00	\$ 80.00
12	Rear Emblem	<i>nn</i> 1	\$ 60.00	\$ 60.00
13	Tailgate	<i>nn</i> 1	\$ 1,300.00	\$ 1,300.00
14	Tailgate Outer Cover <i>691</i>	<i>cm</i> 1	\$ 750.00	\$ 750.00
15	Tailgate Lock Assy	1	\$ <i>nn</i> 170.00	\$ 170.00
16	Rear Windscreen Moulding Assy	<i>nn</i> 1	\$ 150.00	\$ 150.00
17	End Panel Top Garnish	<i>nn</i> 1	\$ 260.00	\$ 260.00
18	End Panel Assy <i>208</i>	<i>nn</i> 1	\$ 635.00	\$ 635.00
Total Spare Parts				\$ 5,561.00
<b>SPECIAL NETT</b>				
19	Rear License Plate with Casing	<i>cm</i> 1	\$ 40.00	\$ 40.00
20	Rear Bumper Lower Diffuser	<i>nn</i> 1	\$ 380.00	\$ 380.00
21	Rear Windscreen Sealant	1	\$ <i>nn</i> 40.00	\$ 40.00
22	Reverse Sensor	<i>nn</i> 1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 660.00
<b>LABOUR</b>				
23	Spray Paint ( Rear Bumper, Rear Bumper Cover RH/LH, Tailgate, Tailgate Cover & Inner Panels )	1	\$ 1,000.00	\$ 1,000.00
24	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00
25	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 350.00	\$ <i>nn</i> 350.00
26	Repair, Re-Align & Panel Beat End Panel & Spare Tyre Sink	1	\$ 150.00	\$ <i>nn</i> 150.00



**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-378

DATE : 19-Jul-2022

POLICY NO. : P10491396R01

VEHICLE REG. NO. : SMG7512C

VEHICLE MAKE : HONDA CROSSROAD 2.0X A

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
27	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
28	Remove and Refit Rear Windscreen	1	\$ <del>120.00</del> 120.00	\$ 120.00
29	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ <del>100.00</del> 100.00	\$ 100.00
30	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,830.00
Amount Before Excess				\$ 9,051.00
Add GST @ 7%				633.57
Total Amount Payable				\$ 9,684.57

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: