

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 19/07/2022

User ID : JeongCH

**Section A - Accident Details**

Registration Number	SMB322G
Case Reference Number	BUS/07/22/5008
Registration Date	10/16/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Yong Min
Type of Accident	Head To Side
Accident Date and Time	7/6/2022 10:52 PM
Accident Reported Date and Time	7/19/2022 10:12 AM
Is Surveyor Required?	No
Surveyed by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB322G - rear left panel dented FL9881E (TP) - INSURED WITH NTUC
Prepared Date and Time	7/19/2022 10:43 AM
Chassis Number	WMAA22ZZ8C7001455
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$2,411.78	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$4,617.78</b>	<b>\$0.00</b>
<b>Jump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	2 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	19/07/2022 10:54 AM	
Signature		
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/07/2022

User ID : JeongCH

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	795
<b>total Labour</b>	<b>\$1,590.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	432
<b>total Spray Painting &amp; Panel Beating</b>	<b>\$616.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010005	BODY LH	A01001-CW561	PANEL, SIDE:L11,FOR MAN A22 BUS	1.00	\$1,092.50	10.00	\$983.25	Replace	bt
010411			GAS SPRING 22N	2.00	\$94.90	10.00	\$170.82	Replace	bt
010316	Body	4001A06-LOCK2555	LOCK,CAM:SQUARE,35 MM,FOR MAN A22 BUS	2.00	\$47.50	10.00	\$85.50	Replace	X
010317	Body	4000F06-HING732	HINGE:LH,SIDE FLAP,FOR MAN A22 BUS	1.00	\$163.08	10.00	\$146.77	Replace	bt
010318	Body	4000F06-HING733	HINGE:RH,SIDE FLAP,FOR MAN A22 BUS	1.00	\$163.08	10.00	\$146.77	Replace	bt
010315	BODY LH	S06006-CW576	PANEL,FRAME SIDE:L11,FOR MAN A22 BUS	1.00	\$1,610.00	10.00	\$1,449.00	Replace	bt
<b>total</b>					<b>\$3,207.30</b>		<b>\$3,014.73</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>total</b>									

Reful  
Hh 90010068  
3 days  
L/S  
19/07/22 @ 1550  
Res after repv