



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/10/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB322G
Case Reference Number	BUS/07/22/5008
Registration Date	16/10/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Yong Min
Type of Accident	Head To Side
Accident Date and Time	6/7/2022 10:52 PM
Accident Reported Date and Time	19/7/2022 10:12 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115655
Special Instruction to ARC,if any	SMB322G - rear left panel dented FL9881E (TP) - INSURED WITH NTUC
Prepared Date and Time	19/7/2022 10:43 AM
Chassis Number	WMAA22ZZ8C7001455
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$795.00
Total Spray Cost	\$616.00	\$432.00
Total Spare Part Cost	\$4,240.61	\$4,172.21
Total Other Cost	\$0.00	(\$245.40)
TOTAL COST	\$6,446.61	\$5,153.81
Lump Sum Total	\$0.00	\$5,150.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	21/07/2022 5:46 PM	21/07/2022 7:08 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/10/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$795.00		
Total Labour			\$1,590.00				\$795.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00				\$432.00		
Total Spray Painting & Panel Beating			\$616.00				\$432.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$245.40)		
Total Other Costs			\$0.00				(\$245.40)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010005	BODY LH	A01001-CW561	PANEL,SIDE:L11,FOR MAN A22 BUS	1.00	\$1,092.50	10.00	\$983.25	Replace	Replace
6010411			GAS SPRING 22N	1.00	\$94.90	10.00	\$85.41	Replace	Replace
6010316	Body	4001A06-LOCK2555	LOCK,CAM:SQUARE,35 MM,FOR MAN A22 BUS	0.00	\$47.50	0.00	\$0.00	Replace	Not Given
6010317	Body	4000F06-HING732	HINGE:LH,SIDE FLAP,FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	Replace
6010318	Body	4000F06-HING733	HINGE:RH,SIDE FLAP,FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	Replace
6010315	BODY LH	S06006-CW576	PANEL,FRAME SIDE:L11,FOR MAN A22 BUS	1.00	\$1,610.00	10.00	\$1,449.00	Replace	Replace
Total					\$3,207.30		\$2,843.82		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		51-08101-5204	Exhaust Elbow insulated	1.00	\$2,511.60	10.00	\$2,260.44	Replace	Replace
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	3.00	\$37.00	0.00	\$111.00	Replace	Replace
Total					2,548.60		2,371.44		