

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/07/2022

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB322G
Case Reference Number	BUS/07/22/5008
Registration Date	10/16/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Chong Yong Min
Type of Accident	Head To Side
Accident Date and Time	7/6/2022 10:52 PM
Accident Reported Date and Time	7/19/2022 10:12 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB322G - rear left panel dented FL9881E (TP) - INSURED WITH NTUC
Prepared Date and Time	7/19/2022 10:43 AM
Chassis Number	WMAA22ZZ8C7001455
Allegance	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$2,411.78	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,617.78	\$0.00
ump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2 days
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	19/07/2022 10:54 AM	
Signature		*
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/07/2022

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	795
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	432
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010005	BODY LH	A01001-CW561	PANEL, SIDE L11, FOR MAN A22 BUS	1.00	\$1,092.50	10.00	\$983.25	Replace	bt
010411			GAS SPRING 22N	2.00	\$94.90	10.00	\$170.82	Replace	bt
010316	Body	4001A06-LOCK2555	LOCK, CAM, SQUARE, 35 MM, FOR MAN A22 BUS	2.00	\$47.50	10.00	\$85.50	Replace	X NN
010317	Body	4000F06-HING732	HINGE, LH, SIDE FLAP, FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	bt
010318	Body	4000F06-HING733	HINGE, RH, SIDE FLAP, FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	bt
010315	BODY LH	S06006-CW576	PANEL, FRAME SIDE L11, FOR MAN A22 BUS	1.00	\$1,610.00	10.00	\$1,449.00	Replace	bt
Total					\$3,207.30		\$3,014.73		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Reful
H9 90010068
3 days
L/S
19/07/22 @ 1550
Res after repair

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte
60 Woodlands Industrial Park E4
FAX Number : 63685592
Estimator Telephone Number : 63685592
Accident Reporting Number : 63685592

Date Generated : 17/10/2022

User ID : CatherineL

Section D - Details of Repair Estimates

Items	Quotation from AR	Adjusted by Surveyor, if applicable
ALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AREAS.	\$1,590.00	\$795.00
	\$1,590.00	\$795.00

Painting & Panel Beating Related Works	Quotation from ARC	Adjusted by Surveyor, if applicable
PRIMER AND MATERIAL TO PUTTY AND RESPRAY ABOVE	\$616.00	\$432.00
Painting & Panel Beating	\$616.00	\$432.00

Painting & Panel Beating Related Expense	Quotation from ARC	Adjusted by Surveyor, if applicable
Adjusted by Surveyor	\$0.00	(\$245.40)
	\$0.00	(\$245.40)

Parts / Material Usage								
Item	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
DRY LH	A01001-CW561	PANEL, SIDE: L11, FOR MAN A22 BUS	1.00	\$1,092.50	10.00	\$983.25	Replace	Replace
		GAS SPRING 22N	1.00	\$94.90	10.00	\$85.41	Replace	Replace
y	4001A06- LOCK2555	LOCK, CAM: SQUARE, 35 MM, FOR MAN A22 BUS	0.00	\$47.50	0.00	\$0.00	Replace	Not Given
y	4000F06- HING732	HINGE: LH, SIDE FLAP, FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	Replace
y	4000F06- HING733	HINGE: RH, SIDE FLAP, FOR MAN A22 BUS	1.00	\$181.20	10.00	\$163.08	Replace	Replace
DRY LH	S06006-CW576	PANEL, FRAME SIDE: L11, FOR MAN A22 BUS	1.00	\$1,610.00	10.00	\$1,449.00	Replace	Replace
				\$3,207.30		\$2,843.82		

Parts / Material Usage After Surveyor Signed off								
Item	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
	51-08101-5204	Exhaust Elbow insulated	1.00	\$2,511.60	10.00	\$2,260.44	Replace	Replace
CONSUMABLE		ADHESIVE: DIRECT GLAZING	3.00	\$37.00	0.00	\$111.00	Replace	Replace
				2,548.60		2,371.44		

SU
SU