

Kenneth

ASS. REC. BY:

REF:

HLA/ CS/HLA22006938/Kqy3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

MPC03556/WE

Sum Insured: _____

Excess: _____

30d

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

894/c

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/07/22 @ 2.18pm revert to HLA via Merimen.

26/07/22 @ 4.27pm Wee Fu informed C/A via Merimen.

27/07/22 @ 11.19am Informed wksp C/A & ex: \$300 by email.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Fees: _____

Others: _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

Veh No: _____

SLG 1196E

Yr Regn: _____

061 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Wagon

Make: _____

BMW

2160

c.c

1496

Colour: _____

N. Black

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

58131

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WBA2E320205149580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size: _____

F: _____

R: _____

205/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

7

mm

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

17/7/22

D.O.I. _____

21/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR MS & UIC

The U/C / Chassis frame / Body Structure affected due to collision.

ASS. R

Kenne

From

Est

OD

To



INSURER: HL Assurance Pte Ltd (HQ)

PARTICULARS OF CLAIM		Ref. No:
Claim Type:	OD (Own Damage)	Date of Loss: 11/01/22
Policy No:	MP307483	Driveable?
Vehicle Reg. No.:	SLQ1196E	Party At Fault: UNKNOWN
Driver Age/Info:	46 / MALE	Third Party Involved:
TP Injury Involved?	NO	Contact No: +6598222832
Insured/Claimant:	Sharon Wee Hsu Oon	
Driver:	Lim Meng Liang Gabriel	
Make/Model:	BMW 216D, 1.5 (A)	Vehicle Reg. Date: 28/06/2017
Vehicle Colour:	Metallic Black	Chassis No: WBA2E320205H45960
Engine No:	33159813B37C15A	
Odometer:	58131 KM	
Paint Type:		
Total Loss?	NO	
Est. Duration of Repair (day)	4 days	
Description of Accident/Loss	REFER ATTACHED R	
Present Location:	S & AMP; H MOTOR PTE LTD (SIN MING)	

*Not Notified
11/01/22
Repair After Paint
Ex 8300/-*

COST OF CLAIMS	Amount
Parts	5,454.75
Miscellaneous Items	220.00
Labour	860.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,534.75
+ GST 7.00% (S\$)	457.43
Nett Amount (S\$)	6,992.18

This claim is handled by: LUM WEE KEAT

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 20 Jul 2022)

Parts: 143

BMW 216D 1.5 (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SLQ1196E/20/07/2022 16:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH front wheel rim	0.00	0.00	*900.00 F
2	1		*LH front knuckle arm	0.00	0.00	*620.00 F
3	1		*LH front wheel bearing	0.00	0.00	*280.00 F
4	1		*LH front lower arm	0.00	0.00	*185.00 F
5	1		*LH front lower arm bush	0.00	0.00	*160.00 F
6	1		*LH front shock absorber	0.00	0.00	*380.00 F
7	1		*LH front shock absorber top mounting	0.00	0.00	*180.00 F
8	1		*LH steering tie rod	0.00	0.00	*160.00 F
9	1		*LH steering tie rod end	0.00	0.00	*230.00 F
10	1		*LH drive shaft	0.00	0.00	*2,100.00 F

F=Franchise part.

Sub Total (\$\$) 5,195.00
+ Margin on L,N Items 5.00% (\$\$) 259.75

Total Parts (\$\$) 5,454.75

S & H Motor Pte Ltd/SLQ1196E/20/07/2022 16:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 LH front tyre

Amount

220.00

Sub Total (S\$)

220.00

Estimates on Labour

No Particulars

Labour Items

Lab.Type

Amount

1	To remove and refit front bumper, and adjust body panel alignment	New	150.00	100
2	To remove and check LH front suspension system and replace damaged parts	New	240.00	200
3	To perform computerised wheel alignment	New	60.00	✓
4	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality	New	60.00	7
5	To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes	New	150.00	7
6	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	200.00	✓

Gross Labour Cost (S\$)

860.00

S & H Motor Pte Ltd/SLQ1196E/20/07/2022 16:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 458F

Vehicle Details

Vehicle No.: SLQ1196E
Vehicle to be Exported: Yes
Intended Deregistration Date: 19 Jul 2022
Vehicle Make: B.M.W.
Vehicle Model: 216D GRAN TOURER LED NAV 7 SEATER
Primary Colour: Black
Manufacturing Year: 2017
Engine No.: 33159813B37C15A
Chassis No.: WBA2E320205H45960
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$31,478.00
Original Registration Date: 28 Jun 2017
First Registration Date: 28 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$26,070.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Jun 2027
PARF Rebate Amount: \$18,249.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$21,138.00
Total Rebate Amount: \$39,387.00

The information contained herein is correct as at 19 Jul 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/07/2022 17:01 (SGT)
Reported by	Driver
Date of Accident	17/07/2022 13:30 (SGT)
Exact Location of Accident	Eng Neo Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ1196E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Sharon Wee Hsu Oon
NRIC No	SXXXX458F
Email Address	sharonwee@gmail.com
Mobile Phone No	(Phone) +65-98222832
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	216d
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Policy Number / Cover Note Number	MP307483

DRIVER

Name of Driver	Lim Meng Liang Gabriel
NRIC No	SXXXX362H
Date Of Birth	24/12/1975
Occupation	Indoor

Describe Circumstance of the Accident

Driving along Vanda Road and turning right into Eng Neo Avenue. Driver was in the car with wife (owner of car). Driver swerved to avoid dog and hit kerb on left side (front wheel).

Declaration

I/We declare the foregoing particulars are true in every respect.

Erin Lee

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

19/17

[Signature]

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)