

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |       |                       |  |
|---|--|--|-----------------|-------|-----------------------|--|
|   | STRIDES AUTOM  | OTIVE SERVICES PTE LTD                 |                 | Ref:  | CS/SMR22006952/Eqy3e2 |  |
|   | 60 WOODLANDS I<br>E4SINGAPORE 75   | NDUSTRIAL PARK<br>37705                |                 | Date: | 06/09/2022            |  |
|   |  |  |                 | Code: | SMR                   |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |  |                 |       |                       |  |
|   | Insured Veh.   | SMB 5050H                              | Veh. Inspected  |       | SJY 5216L             |  |
|   | Policy No.   |  | Coverage (\$)   |       | 0.00                  |  |
|   | Claim No.  | BUS/07/22/5005                         | Excess (\$)     |       | 0.00                  |  |
|   | Assign From  | HUA YEN                                | Assign Date     |       | 21/07/2022            |  |
| 2.  | Vehicle Particulars & Condition  |  |                 |       |                       |  |
|   | Make & Model   | SKODA KODIAQ                           | c.c             |       | 1395                  |  |
|   | Engine No.   | HIDDEN                                 | Year of Reg.    |       | 2019                  |  |
|   | Chassis No.  | TMBKC7NS3K8503108                      | Colour          |       | GREY                  |  |
|   | Odometer   | 56961 KM                               | Steering        |       | IN ORDER              |  |
|   | Brakes   | IN ORDER                               | Modification    |       | SPORTS RIM            |  |
|   | General  | GOOD                                   |                 |       |                       |  |
| 3.  | 3. Conditions of Tyres   |  |                 |       |                       |  |
|   |  | Size                                   | Make            |       | Balance               |  |
|   | R/H Front Tyre   | 235/55 R18                             | BRIDGESTONE     |       | 5 mm                  |  |
|   | L/H Front Tyre   | 235/55 R18                             | BRIDGESTONE     |       | 5 mm                  |  |
|   | R/H Rear Tyre  | 235/55 R18                             | BRIDGESTONE     |       | 5 mm                  |  |
|   | L/H Rear Tyre  | 235/55 R18                             | BRIDGESTONE     |       | 5 mm                  |  |
| 4.  | Description of Damages   |  |                 |       |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.   |  |                 |       |                       |  |
|   | DAMAGES SEE DETAILS.   |  |                 |       |                       |  |
| 5.  | General Information  |  |                 |       |                       |  |
|   | Accident Date  | 09/07/2022                             | Inspection Date | е     | 01/08/2022            |  |
|   | Survey held at   | VOLKSWAGEN GROUP SINGA                 | PORE PTE LTD    |       |                       |  |
|   |  | 247 ALEXANDRA ROAD<br>SINGAPORE 159934 |                 |       |                       |  |
| 5a.   | Remarks  |  |                 |       |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |       |                       |  |
| 5b.   | Estimate Days of Repair  |  |                 |       |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days   |  |                 |       |                       |  |
|   | •  |  |                 |       |                       |  |