

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS3/AGI22006954/Kcy3e2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Date:	28/04/2023	
			Code:		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJT 6469T	Veh. Inspected	SLZ 363Z	
	Policy No.	P10444543R01	Coverage (\$)	0.00	
	Claim No.	C10016476/JT	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	21/07/2022	
2. Vehicle Particulars & Condition					
	Make & Model	AUDI A3 (A)	c.c	999	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WAUZZZ8VXJ1047241	Colour	WHITE	
	Odometer	122944 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	MICHELIN	7 mm	
	L/H Front Tyre	205/55 R16	MICHELIN	7 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5. General Information					
	Accident Date	19/07/2022	Inspect Date / Time	25/07/2022 (01:36 PM)	
	Survey held at	LIM YEW BOO SPRAY PAINT C	0		
		BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE,#01-10 SINGAPORE 575645.			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			

Report Ref No. CS3/AGI22006954/Kcy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser