

REF:

ASSIGNMENT

Veh No: SMS1450Z. Yr Regn: 2020/ Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta C.C. 1496.

Colour Silver A/C: Insured / Std / Nil / NA

Sp. Reading 100/35 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NSP1707206889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15.

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO DT

Front		Rear	
R/Bal. 06	mm	R/Bal. 06	mm

L/Bal. 06. mm L/Bal. 06. mm

D.O.A. _____ D.O.I. 21/07/22

Survey held at Imperium

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

	
N/S	O/S

Date / Time	Action / Instruction
	T9 Ching.
	MV :
	PV :
	Nett:
	076A.

☐: Prel. Report

□: Final Report

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Add Fee: : Site Insp (\$

□ Interview (\$

Tech. Invs (3)

Survey Fee:

Transportation:

Photos

Others