

ASS. REC. BY:

REF:

0721 2200-69661Kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLM 17146 Yr Regn: 03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy ALPIS c.c 1598

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

92892

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104581450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/45 ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

19/7/22

D.O.A.

21/7/2022

Survey held at

Des. of Damages: PFI Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / G1A & E1 not ready

26/7 11PM @ 5200d Carhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com . H.P 90030857

*Not Withheld
618y @ 5200h
Resurvey After Claim
4 days*

Date : 22 Jul 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

CLAIM : THIRD PARTY CLAIM

VEH. No : SLM 1714 G / TOYOTA ALTIS

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : AUTO GENERAL INS.

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : GBG 3074 G			
1	FRONT BUMPER <i>539.30</i>	\$ Bu 680.00	✓
1	FRONT BUMPER REINFORCEMENT	\$ R 580.00	X
1	FRONT BUMPER SPONGE <i>133.50</i>	\$ CM 348.00	✓
1	FRONT BUMPER BRACKET RH	\$ R 220.00	X
1	FRONT BUMPER SIDE RETAINER RH	\$ R 180.00	X
1	FRONT BUMPER LOWER COVER	\$ R 480.00	X
1	RADIATOR PANEL <i>525.10</i>	\$ Bu 850.00	✓
2	HEADLAMPS <i>@ 2816.70</i>	\$ Mhcm 6,580.00	✓
1	HEADLAMP PANEL RH	\$ R 325.00	X
1	HEADLAMP LOWER BRACKETS	\$ R 168.00	X
1	FRONT FENDER RH	\$ R 580.00	X
1	FRONT FENDER UNDERSHIELD RH	\$ R 343.50	X
1	FOG LAMP GARNISH RH	\$ R 298.00	X
1	FRONT GRILLE <i>466.10</i>	\$ CM 620.00	✓
1	BONNET	REPAIR	
TOTAL PARTS :		\$ 12,252.50	
LESS 25%		\$ 3,063.13	
TOTAL LIST PARTS :		\$ 9,189.38	
SPECIAL / NETT PARTS			
10	FRONT BUMPER CLIPS	\$ M 45.00	✓
1	FRONT BUMPER LOWER SPOILER RH	\$ R 600.00	X
TOTAL S/N PARTS :		\$ 645.00	
TOTAL PARTS PRICE :		\$ 9,834.38	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE . SIN MING AUTOCITY

06-15 SINGAPORE 575722

EMAIL : tsrteamworks2022@gmail.com . H.P 90030857 .

Date : 22 Jul 2022

QUOTATION - THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

CLAIM : THIRD PARTY CLAIM

VEH. No : SLM 1714 G / TOYOTA ALTIS

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : AUTO GENERAL INS.

LABOUR CHARGES	AMOUNT	CONDITION
Labour charge to repair, replace , align adjust , remove & refix accident affected area	\$ 800.00	5001
To do anti rust	\$ 90.00	301
To check wiring system, forcus headlamps etc	\$ 120.00	201
To do spray painting on bonnet, bumper , support panel, radiator panel, lamps panels, front fenders etc (inner and outer)	\$ 1,000.00	5001
Labour to remove refix radiator, A/C condenser , fill gas & refill radiator coolant, so as to replace radiator top panel and repair support panel	\$ ~ 240.00	X
To do computer setting , diganose delete fault code after repair	\$ ~ 250.00	X
TOTAL LABOUR :	\$ 2,500.00	
GRAND TOTAL PARTS & LABOUR :	\$ 12,334.38	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/07/2022 17:56 (SGT)
Reported by	Both
Date of Accident	19/07/2022 17:30 (SGT)
Exact Location of Accident	888 Woodlands Drive 50, Singapore 730888
Additional Location Information	plaza 888 woodland drive 50 mscp car park lot 19
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM1714G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHAN YEW PING
NRIC No	SXXXX976D
Email Address	FREDCYP@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97302941
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	ALTIS
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1596

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10512709R01

DRIVER

Name of Driver	CHAN YEW PING
NRIC No	SXXXX976D
Date Of Birth	03/08/1973
Occupation	Indoor

Date Of Driving Pass	14/06/2002
Driving experience	20 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-97302941
Alt. Phone Number	-
Email Address	FREDCYP@HOTMAIL.COM
Address	BLK 681A WOODLANDS DRIVE 62 #08-11
Address complement	-
Postcode	731681
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG3074G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	TING KIM HOCK
NRIC No	SXXXX603J

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 976D

Vehicle Details

Vehicle No.: SLM1714G
Vehicle to be Exported: Yes
Intended Deregistration Date: 20 Jul 2022
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 1ZRY343455
Chassis No.: MR053REH104561450
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,990.00
Original Registration Date: 23 Mar 2017
First Registration Date: 23 Mar 2017
Transfer Count: 0
Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Mar 2027
PARF Rebate Amount: \$13,993.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$49,430.00
COE Rebate Amount: \$23,093.00
Total Rebate Amount: \$37,086.00

The information contained herein is correct as at 20 Jul 2022

OK