

ASSIGNMENT

INVENT

Veh No: GBG 3895G Yr Regn: 9/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 1100 Doble c.c 1598

Colour: Gray A/C: Insured / Std / Nil / NA

Sp. Reading 164549 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: 2FA963000P6692612

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 11

N/S	O/S
22	

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI
TOYO/YOKO or.

Front 4 mm R/Bal. 4 mm
L/Bal. 4 mm U/Bal. 4 mm
D.O.A. 19/7/22 D.O.I. 2/8/22
Survey held at Wah Hong
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Prelim. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.F. (\$) .)

Add Fee:

☐: Site Insp (\$

☐: Interview (\$

	Tech. Invs (\$)
--	-----------------

☐ : Weekend (5)

Transportation:

Transportation:

$$) \quad S + RS.$$

1) Photos

Others

31

1	TOTAL
---	-------

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	339R
Vehicle Details	
Vehicle No.:	GBG3825G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Jul 2022
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ 6MT GLAZE
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	198A30008093574
Chassis No.:	ZFA26300006G92612
Maximum Power Output:	-
Open Market Value:	\$18,776.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$939.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,879.00
COE Rebate Amount:	\$18,508.00
Total Rebate Amount:	\$18,508.00

The information contained herein is correct as at 19 Jul 2022

OK



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. GBG3825G FIAT DOBLO CARGO MAXI 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear door LH / <i>OD</i>		2640.00	
1	Rear door lower hinge LH / <i>OT</i>		154.00	
1	Rear door RH / <i>OD</i>		2090.00	
1	Rear door lower hinge RH / <i>OT</i>		154.00	
1	Rear door car plate base garnish LH / <i>CR4</i>		440.00	
1	Rear door logo base garnish RH / <i>CR4</i>		420.00	
1	Rear door RH emblem "DOBLO max" / <i>NR</i>		264.00	
1	Rear door RH emblem "10S multijet2" / <i>NR</i>		308.00	
1	Rear door LH emblem "PROFESSIONAL" / <i>NR</i>		330.00	
1	Rear door LH logo badge "Fiat" / <i>NR</i>		264.00	
1	Rear bumper / <i>CR4</i>		616.00	
2	Rear bumper side retainer LH/RH @2*66 / <i>?</i>		132.00	
1	Rear reinforcement		484.00	
1	End panel / <i>?</i>		1056.00	
1	End panel top garnish / <i>?</i>		660.00	
1	Boot lid weatherstrip / <i>CR4</i>		440.00	
1	Rear bumper reflector RH / <i>BR</i>		39.60	
Part Items Total:			10491.60	
			-10%	-1049.16
				9442.44
SPECIAL NETT ITEMS				
1	Rear bumper clips / <i>NR</i>		35.00	
1	Rear carplate with holder / <i>X</i>		35.00	
1	Rear reverse sensor / <i>Shd</i>		200.00	
1	Rear door windscreen sealant LH / <i>NR</i>		60.00	
1	Rear door windscreen sealant RH / <i>NR</i>		60.00	
1	6 Pax sticker / <i>NR</i>		25.00	
1	70km/H sticker / <i>NR</i>		25.00	
1	End panel sealant / <i>?</i>		60.00	
SN Items Total:			500.00	
Total Parts			9942.44	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBG3825G FIAT DOBLO CARGO MAXI 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To perform anti-rust treatment on affected areas	90.00	30
5	To remove and refit/replace rear compartment fitting, timming, garnish, rear spare tyre with bracket and etc	100.00	
6	To remove and replace rear windscreen LH	120.00	80
7	To remove and replace rear windscreen RH	120.00	80
8	To remove and replace rear reverse sensor	100.00	30
Labour Total :		2820.00	
TOTAL (PARTS & LABOUR):		12762.44	

5ter (LKK) m n
2/8/22, 1.1pm
L/S
by AL
6/8/22

- LKK Auto Con
- the Repairer of
- To resurvey before
 - To display damaged parts during survey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/07/2022 16:20 (SGT)
Reported by	Both
Date of Accident	19/07/2022 14:35 (SGT)
Exact Location of Accident	Near Jurong Town Hall Rd, Singapore
Additional Location Information	JURONG TOWN HALL RD TOWARDS BOON LAY WAY (BEFORE SCIENCE CENTRE RD EXIT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBG3825G

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	VICTORY PTE LTD
Company Reg No	1XXXXX339R
Email Address	ACCOUNTS@VPT.COM.SG
Mobile Phone No	(Phone) +65-96476553
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Fiat
Model	Doblo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1598

INSURANCE COMPANY

Name of Insurance Company	EQ Insurance Company Ltd
Policy Number / Cover Note Number	DMCPHQ21-002722

DRIVER

Name of Driver	TOH SZE CHIN
NRIC No	SXXXX313G
Date Of Birth	13/03/1974

Occupation	Outdoor
Date Of Driving Pass	17/03/1994
Driving experience	28 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96785895
Alt. Phone Number	-
Email Address	SCTOHSC@GMAIL.COM
Address	BLK 124 TECK WHYE LANE
Address complement	#09-876
Postcode	680124
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT (T/20220720/7011)

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO TOO LARGE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBL2376R
Vehicle Manufacturer	-

Vehicle Model	*
Vehicle Variant	*
Vehicle Colour	*
Vehicle Category	Commercial vehicle
Name of Driver	*
Contact Number	(Phone) +65-97512650
Address	*
Address complement	*
Postcode	*
Insurance Company Name	*
Nature Of Damage	*
Details of property damaged in accident	*
No. Of Passenger (Including Driver)	*

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YN445E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TOH SZE CHIN
Gender	Male
Phone No	(Phone) +65-96785895
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	GBG3825G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

I WAS DRIVING MY VEH A (GBG3825G)
ON 19/07/2022 AT ABOUT 2 35PM ALONG JURONG TOWN HALL RD
TOWARDS BOON LAY WAY (BEFORE SCIENCE CENTRE RD EXIT).

I WAS AT JURONG TOWN HALL RD WAITING FOR THE TRAFFIC LIGHT,
SUDDENLY I FELT A STRONG IMPACT FROM MY VEH A (GBG3825G).
AFTER THE ACCIDENT, I FELT GIDDY AND SIT IN THE CAR FOR
AWHILE. AFTER RESTING, I ALIGHT FROM MY VEH A (GBG3825G)
AND SAW VEH B (GBL2376R) HAD COLLIDED ONTO MY VEH A
(GBG3825G)'S REAR AND SAW VEH B (GBL2376R) DRIVER
RESTING IN HIS CAR.

AFTER A FEW MINS, I STARTED TO TAKE PICTURES AND
EXCHANGE PARTICULARS.

AFTER TAKING PICTURES, I REALISE IT WAS VEH C (YN445E)
HAD COLLIDED ONTO VEH B (GBL2376R)'S REAR AND
VEH B (GBL2376R)'S FRONT HAD COLLIDED ONTO MY
VEH A (GBG3825G)'S REAR.

Declaration


We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



SINGAPORE POLICE FORCE



T/20220720/T011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20220720/T011

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2022 11:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TOH SZE CHIN			Address: 124 TECK WHYE LANE #09-876 SINGAPORE 680124		
ID Type / ID No.: NRIC NO / S7408313G			Contact No.: Home/Office: Mobile: 96785895		
Nationality: SINGAPORE CITIZEN			Email: SCTOHSC@GMAIL.COM		
Sex: Male	Age: 48	Date of Birth: 13/03/1974	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SUPERINTENDENT MARINE ENGINEERING			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/07/2022 14:35	Type of Location: Straight Road
Location: JURONG TOWN HALL ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume:	
Type of Collision: CHAIN COLLISION				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBG3825G	Van	FIAT	DOBLO MAX			0
GBL2376R	Van	TOYOTA	HIACE			0
YN445E	Lorry					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBG3825G	EQ INSURANCE COMPANY LTD.			
GBL2376R	CHINA TAIPING			

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TOH SZE CHIN	ID No.	S7408313G
Related Vehicle	GBG3825G (Van)	Contact No.	96785895
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Slight

Brief Details.

ON 19/07/2022 AT ABOUT 2:35PM, I WAS DRIVING MY VEH A (GBG3825G) ALONG JURONG TOWN HALL RD TOWARDS BOON LAY WAY (BEFORE SCIENCE CENTRE RD EXIT).

I WAS AT JURONG TOWN HALL RD WAITING FOR THE TRAFFICE LIGHT, SUDDENLY I FELT A STRONG IMPACT FROM MY VEH A (GBG3825G)'S REAR. AFTER THE ACCIDENT, I FELT GIDDY AND SIT IN THE CAR FOR AWHILE. AFTER RESTING, I ALIGHT FROM MY VEH A (GBG3825G) AND SAW VEH B (GBL2376R) HAD COLLIDED ONTO MY VEH A (GBG3825G)'S REAR AND SAW VEH B (GBL2376R) DRIVER RESTING IN HIS CAR.

AFTER A FEW MINS, I STARTED TO TAKE PICTURE AND EXCHANGE PARTICULARS.

AFTER TAKING PICTURES, I REALISE IT WAS VEH C (YN445E) HAD COLLIDED ONTO VEH B (GBL2376R)'S REAR AND VEH B (GBL2376R)'S FRONT HAD COLLIDED ONTO MY VEH A (GBG3825G)'S REAR.



**SINGAPORE
POLICE FORCE**



T/20220720/7011

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20220720/7011

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
20/07/2022 11:43

Classification Of Case:

NP168