

ASS. FEO. BY:

REP:

08/MEG22006986/AGay3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKG32215 Yr Regn: 2012, May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i c.c. 1997

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 157226 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAX612090DX49317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R19

R: 245/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 22/07/22

Survey held at Xin Hng.

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP MS16.
5/1/23	Confirmed LS \$6300; 5 days with Alan. (Red 12,827.39, 67%)
	MV:
	PV:
	Nett:

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

\$ + RS. \$1

Picks

Others

Add Fee:



Site Insp (\$



Interview (\$



Techn. Insp (\$

Report Formed:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 426I

### Vehicle Details

Vehicle No.: SKG3221S  
Vehicle to be Exported: No  
Intended Deregistration Date: 24 Nov 2022  
Vehicle Make: B.M.W.  
Vehicle Model: 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV  
Primary Colour: Brown  
Manufacturing Year: 2012  
Engine No.: B3170175N20B20B  
Chassis No.: WBAXG12090DX49317  
Maximum Power Output: 135.0 kW (181 bhp)  
Open Market Value: \$42,240.00  
Original Registration Date: 31 May 2012  
First Registration Date: 31 May 2012  
Transfer Count: 1  
Actual ARF Paid: \$42,240.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 May 2027  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$46,822.00  
COE Rebate Amount: \$42,290.00  
**Total Rebate Amount: \$42,290.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Nov 2022

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	13/07/2022 15:42 (SGT)
Reported by	Both
Date of Accident	11/07/2022 13:00 (SGT)
Exact Location of Accident	153 Serangoon North Ave 1, Singapore 550153
Additional Location Information	CARPARK OF 153 SERANGOON NORTH AVENUE 1
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG3221S
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	GOH LIONG FOH
NRIC No	SXXXX426I
Email Address	goh3221@gmail.com
Mobile Phone No	(Phone) +65-90063221
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	520i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

#### INSURANCE COMPANY

Name of Insurance Company	EQ Insurance Company Ltd
Policy Number / Cover Note Number	DMPPHQ22-003926

#### DRIVER

Name of Driver	GOH LIONG FOH
NRIC No	SXXXX426I
Date Of Birth	27/03/1966
Occupation	Indoor

Date Of Driving Pass	16/12/1992
Driving experience	29 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90063221
Alt. Phone Number	-
Email Address	goh3221@gmail.com
Address	BLK 522C TAMPINES CENTRAL 7
Address complement	#03-27
Postcode	523522
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Serangoon North Neighbourhood Police Post
Police Station Address	Blk 108 Serangoon North Avenue 1 #01-709 Singapore 550108
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN ATTACHED.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2376M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### WITNESS DETAILS

##### WITNESS 1

Name	UNKNOWN
Phone	(Phone) +65-98258448
Email	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reduce the policy benefit.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will from time to time be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

(a) my insurer, my workshop and the General Insurance Association of Singapore (GIA) is/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or received by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurance(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices forms which could involve disclosure of certain personal data about me to bring about delivery of the same as well as to the external cover of envelopes and/or packages); and/or


(v) complying with applicable law or administrative processing, handling and/or dealing with my claims (collectively the "Purposes");

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/in be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if different from the policyholder) / Date & Time

  
Witness by Recording Centre Personnel  
(Name in BLOCK CAPITALS)

Sketch Plan

Vehicle 1: St6 2015

Vehicle 2: 2015 2015

Vehicle 3: 2015 2015

Vehicle 4: 2015 2015

Vehicle 5: 2015 2015

Vehicle 6: 2015 2015

Vehicle 7: 2015 2015

Vehicle 8: 2015 2015

Vehicle 9: 2015 2015

Vehicle 10: 2015 2015

Vehicle 11: 2015 2015

Vehicle 12: 2015 2015

Vehicle 13: 2015 2015

Vehicle 14: 2015 2015

Vehicle 15: 2015 2015

Vehicle 16: 2015 2015

Vehicle 17: 2015 2015

Vehicle 18: 2015 2015

Vehicle 19: 2015 2015

Vehicle 20: 2015 2015

Vehicle 21: 2015 2015

Vehicle 22: 2015 2015

Vehicle 23: 2015 2015

Vehicle 24: 2015 2015

Vehicle 25: 2015 2015

Vehicle 26: 2015 2015

Vehicle 27: 2015 2015

Vehicle 28: 2015 2015

Vehicle 29: 2015 2015

Vehicle 30: 2015 2015

Vehicle 31: 2015 2015

Vehicle 32: 2015 2015

Vehicle 33: 2015 2015

Vehicle 34: 2015 2015

Vehicle 35: 2015 2015

Vehicle 36: 2015 2015

Vehicle 37: 2015 2015

Vehicle 38: 2015 2015

Vehicle 39: 2015 2015

Vehicle 40: 2015 2015

Vehicle 41: 2015 2015

Vehicle 42: 2015 2015

Vehicle 43: 2015 2015

Vehicle 44: 2015 2015

Vehicle 45: 2015 2015

Vehicle 46: 2015 2015

Vehicle 47: 2015 2015

Vehicle 48: 2015 2015

Vehicle 49: 2015 2015

Vehicle 50: 2015 2015

Vehicle 51: 2015 2015

Vehicle 52: 2015 2015

Vehicle 53: 2015 2015

Vehicle 54: 2015 2015

Vehicle 55: 2015 2015

Vehicle 56: 2015 2015

Vehicle 57: 2015 2015

Vehicle 58: 2015 2015

Vehicle 59: 2015 2015

Vehicle 60: 2015 2015

Vehicle 61: 2015 2015

Vehicle 62: 2015 2015

Vehicle 63: 2015 2015

Vehicle 64: 2015 2015

Vehicle 65: 2015 2015

Vehicle 66: 2015 2015

Vehicle 67: 2015 2015

Vehicle 68: 2015 2015

Vehicle 69: 2015 2015

Vehicle 70: 2015 2015

Vehicle 71: 2015 2015

Vehicle 72: 2015 2015

Vehicle 73: 2015 2015

Vehicle 74: 2015 2015

Vehicle 75: 2015 2015

Vehicle 76: 2015 2015

Vehicle 77: 2015 2015

Vehicle 78: 2015 2015

Vehicle 79: 2015 2015

Vehicle 80: 2015 2015

Vehicle 81: 2015 2015

Vehicle 82: 2015 2015

Vehicle 83: 2015 2015

Vehicle 84: 2015 2015

Vehicle 85: 2015 2015

Vehicle 86: 2015 2015

Vehicle 87: 2015 2015

Vehicle 88: 2015 2015

Vehicle 89: 2015 2015

Vehicle 90: 2015 2015

Vehicle 91: 2015 2015

Vehicle 92: 2015 2015

Vehicle 93: 2015 2015

Vehicle 94: 2015 2015

Vehicle 95: 2015 2015

Vehicle 96: 2015 2015

Vehicle 97: 2015 2015

Vehicle 98: 2015 2015

Vehicle 99: 2015 2015

Vehicle 100: 2015 2015

Describe Circumstances of the Accident

Refer to Police Report T/20220711/2022

Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name in NPCCAD card)





# SINGAPORE POLICE FORCE



T/20220711/2022

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

Report No. T/20220711/2022

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/07/2022 14:38	Vide Report No.: F/20220711/0135	Station Diary No.: 17
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: GOH LIONG FOH	Address: APT BLK 522C TAMPINES CENTRAL 7 #03-27 SINGAPORE 523522		
ID Type / ID No.: NRIC NO / S26794261	Contact No.: Home/Office: Mobile: 90063221		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 56	Date of Birth: 27/03/1966	Type of Informant: Driver
Race: Chinese	Language:	Institution / School Name:	
Occupation: Contractor	Driving Licence Information: Class: 2B,3	Date of Expiry:	

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 11/07/2022 13:00	Type of Location: Car Park
Location: SERANGOON NORTH AVENUE 1			
Weather: Clear	Road Surface: Dry	Road Speed Limit	
Traffic Flow:	Traffic Control:	Traffic Volume:	
Type of Collision:	Anyone conveyed by ambulance: No		

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC2376M	Lorry					0
SKG3221S	Car	BMW	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV	Brown		0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------





# SINGAPORE POLICE FORCE

Police Station Of Origin  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No 1800-2849999



T/20220711/2022

2 of 3

Report No. T/20220711/2022

## CONTINUATION OF REPORT

Details of Vehicle Insurance		Insurance No	Effective	Expiry Date
Vehicle No.	Insurance Company			
SKG3221S	EQ INSURANCE COMPANY LTD.	DMPPHQ22-003926	01/06/2022	31/05/2023

### Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver		ID No.	
Name	GOH LIONG FOH		S26794261
Related Vehicle	SKG3221S (Car)	Contact No.	90063221
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B.3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 11/7/2022 at about 1200hrs, I parked my vehicle SKG3221S at Blk 153 Serangoon North Ave 1 and left for lunch.

At about 1300hrs, I came back to my vehicle together with my daughter and discovered that my vehicle has dent and scratches on the right frontal side of my car. Therefore, my daughter called for the police.

While waiting for the police to arrive, 2 passerby approached me and informed me that they witnessed a lorry car plate number GBC2376M colliding onto my car and left the place. The 2 passerby's contact details are 98258448 and 82492291.

I do not have any in car camera installed in my car.

I am lodging this report for police assistance.

RE  
RCE



SINGAPORE  
POLICE FORCE



T/20220711/2022

3 of 3

Report No. T/20220711/2022

Police Station Of Origin  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No. 1800-2849999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

F /  
SGT 3 CHO JUN XIONG

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
11/07/2022 14:38

Officer In Charge Of Case:  
TP / HRT /  
Other KASMAWATI BTE SAMIAN  
Contact No.: 65476368

Classification Of Case:

**XIN HUA WORKSHOP PTE LTD**

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SKG3221S

Vehicle Model : BMW 520I

Accident Date : 11.07.2022

Original Reg Date : 31.05.2012

Date : 21.07.2022

Chassis : WBAXG12090DX49317

TP Ins. MSIG

TP MSIG.

Celine.

1	1 pc	Front Bumper <i>del</i>		1,548.90	✓
2	1 pc	Front Bumper Side Retainers <i>new</i>		98.60	+
3	1 pc	Front Bumper Top Rubber		78.20	+
4	1 pc	Front Bumper Reinforcement <i>2 pc</i>		650.00	+
5	1 pc	Front Bumper Reinforcement Bracket <i>1 pc</i>	119.00	238.00	+
6	1 pc	Front Bumper Sponge <i>new</i>		195.80	+
7	1 pc	Front Bumper Lower Grille <i>2 pc</i>		185.60	+
8	1 pc	Front Bumper Fog Lamps <i>1 pc</i>		260.80	+
9	1 pc	Front Bumper Fog Lamps Cover <i>2</i>		98.50	+
10	1 pc	Front Bumper Spray Nozzle Motor <i>1 pc</i>	142.00	145.80	+
11	1 pc	Front Bumper Spray Nozzle Cover <i>1 pc</i>	50.00	58.30	+
12	2 pcs	Front Bumper Sensor (Original)	345.00	690.00	+
13	2 pcs	Front Bumper Sensor Holder	35.80	71.60	+
14	1 pc	Front Grille <i>new</i>		168.90	+
15	1 pc	Headlamp <i>cracked</i>		2,458.90	✓
16	1 pc	Headlamps Bottom Retainers <i>new</i>		85.20	+
17	1 pc	Support Panel <i>new</i>		685.90	+
18	1 pc	Front fender <i>Dented</i>		925.70	✓
19	1 pc	Front fender signal indicator <i>del</i>		145.80	✓
20	1 pc	Front fender inner cowling <i>1 pc</i>		245.80	✓
21	1 pc	Side mirror Assy <i>new</i>		845.20	+
22	1 pc	Front door RH <i>Dented</i>		1,548.60	✓
23	1 pc	Front door inner trim <i>new</i>		698.70	+
24	1 pc	Front sideskirt Rh <i>new</i>		725.80	+
25	1 pc	Front Bonnet <i>new</i>		1,985.60	+
26	1 pc	Front Rim <i>new</i> <i>125 del</i>		1,256.90	+

1pc wiper washer Tank ~~#242.4~~

subtotal 16,097.10

parts disc 10% 5% 14,487.39

1pc Front Fender bracket RH \$112.8 Best ✓

7111.50

6755.92

### Special Nett

1	1 set	Front fender inner cowling clips <i>HE m</i>		30.00	✓
2	1 set	Front bumper clips <i>HE m</i>		30.00	✓
3	1 set	Front Grille clips <i>HE m</i>		30.00	+
4	1 set	Headlamp Clips <i>HE m</i>		30.00	+
5	1 pc	Front Number Plate with Cover <i>HE m</i>		70.00	+

### Labour charge

Panel Beating		2,000.00	<del>750</del> 700
Spray painting		2,000.00	<del>750</del> 700
Check Wiring on headlamp		120.00	30
Anti rust		180.00	60
Remove and install front sensor.		150.00	50

total \$ 19,127.39

*Adrian Lj*  
*h/s 22/07/22.*

*total: 8355.92*  
*h/s: 6.6k*  
*05 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*6.6k*