ASS. RECABY: STEVE CS/C712	2006997 [EC43]
ASSI	GNMENT"
From: Date:	Veh No: SMY 5541C Yr Regn: 26/7/13
Estimaled Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD I THIWS ITP RES ! OD RES ! EVA ! INV ! MV	Truck/Traller or
To Inspect Vehicle No:	Make: BMW 5201 c.c 1997
et Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 0/5/5 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Pallcy No.	CINO: VYBAXGID 700 99 678:
Claims No.	Gen. Cond: Good / Falt / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Indrder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Righ / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	. R:
Remark: The veh had commenced its N/S O/S	BS I DUN / EXNOVA I GY / FS I LIZA / MIG OHTSU / PIR I SUMI /
repair at the time of inspection.	TOYO / YOKO or .
Bal, or Market Value:	Front Rear
IDAC Accident Rport Consistent? : Yes or No	R/Bal, y mm
GIA / PR Seen: Consistent? : Yes or No	LIBAL. U mm
Est Repairs: days Res.: Yes or No	0.0.A. 1911111 AF & Cg/S
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rea / O/S / N/S / U/C / Rooftop or
Venicle: IN 1 Oc	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The DIC I chassis name (cos)
Date / Time Action / Instruction M/- 50 (William)	stimate
- 1/1/2 5 th	
13/10/2022 Finalised L/S \$2,500.00 @ 04 da	ays (Red \$4,331.00/ 63%)
The state of the s	
OsterTime, File Pass to? : Prell. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Tyne, Fils Return to?	Transportation:
Add	Fee:
	: Interview (\$) Photos
Reper Format :	:Tech, Invs (\$) Others
Lump Sum / LE.1: (\$)	: Weel:end (s
	TOTAL