

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBK 4323K Yr Regn: 12/8/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ducati Scrambler c.c. 803Colour: Black A/C: Insured / Std / NI / NASp. Reading: 1700 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 21 MK100AAB B0370

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Bm / STD A/Rim or

Tyre Size: F: 180/80R18R: 180/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 4 mmL/Bal. 4 mmD.O.A. 25/6/17 D.O.I. 25/7/17Survey held at WearnesDes. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MY-18K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



SERVICE ESTIMATE

92357 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Brillet Eric Nicolas
63A Carlisle Road

Singapore
Singapore 219634

Closed by : Tony Alfred Desire D
Svc Consultant : 0988
Remarks : Mr Brillet Eric Nico

Inv.No. ... : D 0 Page 1
Inv.date ... : 22/07/2022
WIP No. ... : 33645
Veh. In/Out:
*Tel.No. ... : Mobile: 94529234
Reg.No. ... : F9K4323K / SCR
Reg.date ... : 12/08/2015
Mileage ... : 19,886
Chassis No.: ZDMK100AAF8003370
Variant... : SCR FullThrott1

Op.No	Description	CCC Mech Qty	Price	Disc%	Pkg	Amount	G
DUCT-A	Accident Damage Assessment		70.00	0	X	70.00	S
NOTES	ACCIDENT REPAIR		0.00	0			S
DUCO-1	To replace damaged parts caus		3600.00	0		3600.00	/
	COVER, EXHAUST (LH) - RM	1.0 EA	192.00			192.00	S
	COVER, EXHAUST (RH) - RM	1.0 EA	189.40			189.40	S
	SCREW - NC	6.0 EA	2.30			13.80	S
	HEAT GUARD (RMK) - RM	1.0 EA	133.00			133.00	S
	WASHER - NC	2.0 EA	0.30			0.60	S
	SPACER - NC	1.0 EA	2.40			2.40	S
	QUICK FASTENING - NC	2.0 EA	1.30			2.60	S
	NUT, SPRING M5 - NC	1.0 EA	4.10			4.10	S
	FINAL SILENCER	2.0 EA	576.10			1152.20	S
	CLAMP	2.0 EA	41.30			82.60	S
	REAR-VIEW MIRROR - BR	1.0 EA	161.60			161.60	S
	PLUG (BANK) - RM	2.0 EA	12.50			25.00	S
	HANDLEBAR - BT	1.0 EA	354.50			354.50	S
	PIPE, EXHAUST C - CUT	1.0 EA	353.80			353.80	S
	SPRING EXHAUST - NC	3.0 EA	25.10			75.30	S
	LEVER, FRONT BR - CUT	1.0 EA	265.10			265.10	S
	REAR WHEEL RIM	1.0 EA	2067.80			2067.80	S
	REAR SWINGING A - CUT	1.0 EA	1893.60			1893.60	S
	SCREW TBEIF M4X - NC	3.0 EA	3.70			11.10	S
	WASHER 4.5X9X0. - NC	3.0 EA	1.50			4.50	S

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930

www.ducati.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- The prices are subject to confirmation
- To do party survey is on a "Without Prejudice" basis
- The damaged location(s) is allowed
- The damaged part(s) must be resurveyed and
- The damaged part(s) must be approved from Insurance Company

Signature of Repairer

Date:

Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X



SERVICE ESTIMATE

92357 - C00018 SL: SERVICE/PARTS SALES - DUCATI
Mr Brillet Eric Nicolas
63A Carlisle Road

Singapore
Singapore 219634

Closed by : Tony Alfred Desire D
Svc Consultant : 0988
Remarks : Mr Brillet Eric Nico

Inv.No. ... : D 0 Page 2
Inv.date ... : 22/07/2022
WIP No. ... : 33645
Veh. In/Out:
*Tel.No. ... : Mobile: 94529234
Reg.No. ... : FBK4323K / SCR
Reg.date ... : 12/08/2015
Mileage ... : 19,886
Chassis No. : ZDMK100AAF8003370
Variant... : SCR FullThrottli

Op.No	Description	CCC	Mech	Qty	Price	Disc%	Pkg	Amount	G
	PLATE / <i>re</i>			2.0 EA	1.60			3.20	S
	PLATE / <i>re</i>			1.0 EA	1.60			1.60	S
	CHAIN SLIDER / <i>re</i>			1.0 EA	25.20			25.20	S
	CHAIN ADJUSTMEN / <i>re</i>			1.0 EA	7.60			7.60	S
	SPRING RING / <i>re</i>			2.0 EA	0.60			1.20	S
	REAR RIGHT FOOT / <i>re</i>			1.0 EA	74.00			74.00	S
	CIRCLIP E-TYPE / <i>re</i>			2.0 EA	1.00			2.00	S
	PLATE / <i>re</i>			2.0 EA	2.10			4.20	S
	FOOTREST PIN / <i>re</i>			1.0 EA	3.70			3.70	S
	HOLDER / <i>re</i> (Foot Rest)			1.0 EA	59.10			59.10	S
	FOOTREST PIN / <i>re</i>			1.0 EA	9.60			9.60	S
	FOOTREST, FRONT / <i>re</i>			1.0 EA	74.00			74.00	S
	SPRING, FOOTRES / <i>re</i>			1.0 EA	3.30			3.30	S
	O-RING / <i>re</i>			2.0 EA	0.40			0.80	S
	NUT M8 / <i>re</i>			1.0 EA	0.60			0.60	S
	DAMPER FOOTREST / <i>re</i>			1.0 EA	30.80			30.80	S
	BALL / <i>re</i>			1.0 EA	0.60			0.60	S
	SPRING / <i>re</i>			1.0 EA	2.20			2.20	S
	BRAKE CONTROL L (step) / <i>re</i>			1.0 EA	133.00			133.00	S
	RH FOOT PEG HOL (Fly bar) / <i>re</i>			1.0 EA	384.00			384.00	S

Steve (LKK)

25/7/22, 11.00 re

m re

3 Lys

PIP, m Bal sm

Labour Total 3,670.00
Parts Total 7,805.70
Package Total 0.00

Amount 11,475.70
Amount 11,475.70
GST @ 7 % 803.30
Total Amount 12,279.00
Less Amt Paid 0.00
Nett Amount 12,279.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
Service Estimates are valid for 10 days from the above date.
This is a computer generated invoice, no signature is required.

DUCATI
SINGAPORE

Wearnes Automotive Pte. Ltd.
45 Leng Kee Road, Singapore 159103 | ducati.enquiries@wearnes.com | +65 6430 4930
www.ducati.com.sg Co. Reg. No.: 199501400R / GST Reg. No.: M28920628X

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/07/2022 13:49 (SGT)
Reported by	Both
Date of Accident	25/06/2022 16:00 (SGT)
Exact Location of Accident	63A Carlisle Rd, Singapore 219634
Additional Location Information	PARKED AT 63A CARLISLE ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBK4323K

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	BRILLET ERIC NICOLAS
NRIC No	SXXXX535J
Email Address	ERIC@EKKKO.COM
Mobile Phone No	(Phone) +65-94529234
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Ducati
Model	SCRAMBLER FULL THROTTLE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	803

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MC/00837398/01

DRIVER

Name of Driver	BRILLET ERIC NICOLAS
NRIC No	SXXXX535J
Date Of Birth	01/02/1971
Occupation	Indoor

Date Of Driving Pass	08/12/1994
Driving experience	27 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65 94529234
Alt. Phone Number	-
Email Address	ERIC@EKKKO.COM
Address	63A CARLISLE ROAD
Address complement	-
Postcode	219634
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER THE SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH2726K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	MOHAMED BASHIR BIN ABDUL RAHIM
NRIC No	SXXXX611I


Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

My moto was parked, at the side of the road next to my house as usual. It had a moto cover as well. At about 4 PM on Saturday 25/06/2022, a FEDEX Delivery Van stopped by the side of the same road (CARLISLE RD) to drop off a delivery then quickly moved off and subsequently hit the rear tyre of my moto and caused it to luffle hard on its right side (exhaust side). He drove immediately stopped and forked a few metres in front to contact me. I was home at the time and witnessed the accident from my balcony window. I came down to inspect the damage after the bike was put upright. Saw the motor was broken on right side, exhaust muffler intact and dented, main footpeg for brake severely dented, right passenger footpeg scratched and right throttle assembly damaged on handle bar. Bike was able to start and ride but throttle very light and right brake very hard to press.

Driver assisted me and gave me all his details:

IC: 51687611L

NAME: MOHAMED BASHIR BIN ABDOUL RAHIM

CAR: FEDEX VAN GBH 2726K

TIME OF ACCIDENT: ~ 4PM SATURDAY 25/06/2022

PLACE OF ACCIDENT: 63A CARLISLE ROAD

MY DETAILS (MOTO OWNER)

IC: 57176535T

NAME: BRILLET ERIC NICOLAS

MOBILE: 9452 9234

EMAIL: ERIC@EKKKO.COM

MOTO: DUCATI SCRAMBLER FULL THROTTLE / FBK 4323K

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel