(08/11/13)	
ASS. REC. BY: CS CTIJJOO:	toto Veys
ASS	IGNMENT .
From: Date:	Veh No: GBF 1893E Yr Regn: Jul / 2016
From: Date:  Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
hand the state of	Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	
To Inspect Vehicle No:	Make: Ssangyong Actyon c.c 1998
at Workshop m/s	Colour White AC: Insured / Std / NI / NA
of	Sp.Reading 48477 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: KPADAIETSGP2717914
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nii) / S/RIm / STD A/Rim or
	Tyre Size: F: 235 75 R16
(Policy Condition)	R:,
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? ; Yes or No	L/Bal. 7 mm L/Bal. 6 mm
Est. Repairs: ) days Res.: Yes or No	CCOC F/2C 1.0.0 CGOC F/81 .A.O.D
Lum Sum: % 3 Val.: Yes or No	Survey held at
04 / PEV / PER / 04/100	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	ols rear
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
29/12 Submit Final Ry \$1075.00 (No	reduction, 02.)
	` `
Date/Time, File Pass to? Preli Report	D 06 D D
. From Report	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
A dal Pro-	Transportation:  Site Insp (\$ )_S+RS,_SI
2) Add Fee	
Report Format: TP	: Interview (\$ ) Photos : Tech. Invs (\$ ) Others
	Name and the same
Lump Sum / (\$ 1075.00)	: Weekend (\$)
	TOTAL



Email: janet.wee@changiairport.com Fax: 6542 5963

Your Ref: SNM22D205047/C02/YP7021M/CHNGPW

Our Ref: LEGAL/C/2022.17

26 July 2022

## CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Attention: Ms Adeline Chng, The Motor Claims Division

Dear Sirs

## CAR ACCIDENT ON 18/07/2022 - THIRD PARTY CLAIM AGAINST YP7021M

On 18/07/2022 at about 1153 hrs at Shell Petrol Station, 1 New Loyang Link, Singapore 506931 your insured driving Vehicle YP7021M crashed at the right side and rear of our vehicle GBF1892E (the "Damaged Property").

We are holding your insured responsible for the costs incurred for the reinstatement of the Damaged Property. The breakdown is as follows:

See a copy of the quotation from Indeco Pte Ltd attached for your easy reference	S\$ 1,075.00
Manpower charges	S\$ 161.25
70/ 007	S\$ 1,236.25
7% GST	<u>S\$ 86.54</u>
TOTAL	S\$ 1,322.79

Please arrange to let us have the said sum of S\$1,322.79 as soon as possible. We look forward to your early payment to avoid further action on our part in this matter. All our rights are expressly reserved.

Yours faithfully Sgd Janet Wee

Janet Wee (Ms)
Assistant Manager
Legal Division
CHANGI AIRPORT GROUP (SINGAPORE) PTE. LTD.

encs

Changi Airport Group (Singapore) Pte Ltd

Office: 60 Airport Boulevard #046-037, Changi Airport Terminal 2, Singapore 819643 Mailing: PO Box 168, Singapore Changi Airport, Singapore 918146 www.changiairportgroup.com

Registration No. 200910817N



## Indeco

INDECO ENGINEERS PTE LTD 7 Abingdon Road, Singapore 499931 Tel: (65) 6542 2146; Fax: (65) 6542 4892

JOB QUOTATION	Page:	of	

то:	CHANGI A	IRPORT GROUP			TEL: 65412961	Ou	Quotation No. :		CAG	1.01/42	51
ATTN:					FAX:	Qu	otation Date :		26-Jul	-2022	
VEH/E	OPT NO.	GBF1892E	Call Sign: -		Job No. :	Co	de No	VE	D/VA/22/CA	G/L4/33	32
VEH / E	OPT MODEL : 88	BANGYONG	***************************************		3						1 119
S/N	SER CODE			SERVICE DE	SCRIPTION		QTY	T	UNIT		TAL
-		TO PROVIDE	MATERIAL A		OR THE FOLLOWING:		+	-	COST (S\$)	cos	T (S\$)
-			***************************************	2 D Di Doort 1	010111111111111111111111111111111111111		-				
1	CM	PANEL BEAT	TNG AND RE	PAIR REAR RHS	FENDER		1 LOT	\$	1,075.00	\$ 1	,075.00
		PUTTY, SANI	DING, MASKI	NG AND SPRA	Y PAINTING OF REAR RHS FEI	NDER	1	<u> </u>		<u> </u>	,070.00
		TOUCH UP O	N REAR RHS	BUMPER			1				-
		REMOVE BRO	OKEN REAR	RHS TAIL LAMI	ASSEMBLY		1	-			
		INSTALL NEV	W REAR RHS	TAIL LAMP AS:	SEMBLY						* * * * * * * * * * * * * * * * * * * *
		CARRY OUT	FUNCTIONAL	L TEST POST CO	OMPLETION OF WORK.						
											-
		,									
_		A									
_	* * * * * * * * * * * * * * * * * * * *										
_											
4											
-											
-											
-											
$\dashv$											
+		NOTE DIDDIEUTE	ACT ON OTHER PROPERTY.	E AVIDUITED IS LODIE							
$\dashv$				E SUBMITTED IF ADDIT	ONAL FAULTS ARE FOUND DURING THE		-				
		COURSE OF REPAIR.					.1				
					Sub-Total:				-	\$1,07	5,00
PROPOS	SED TURNAROU	ND TIME		WEEKS / DAYS	GST 7% :					\$75	.25
TAT: SU	BJECT TO AVAI	LABILITY OF OVERSE	AS SPARES.	-	GRAND TOTAL :				i	\$1,15	0.25
									ı	W1,12	0,23
	QUOTATION P	REPARED BY :		FOR CUSTOMER APP	ROVAL:						
Varne;	Chong Hui I	ong Hui Li		Approving	Approving						
Date:	26-Jul-2022	/		Authority:	CAG / HORTI			Autn	ority Stamp		
Sign:	FL	`		Name :							
	INPUT TO IVMS	BY:		Oot- ·	4						
lame:				Date :							
ale:											
ign:		1.14		Signature ;							

## Indeco

INDECO ENGINEERS PTE LTD 7 Abingdon Road, Singapore 499931 Tel: (65) 6542 2146; Fax: (65) 6542 4892

		JOB Q	UOTATIO	N			Page: 0	f	
		A CONTRACTOR OF THE PARTY OF TH					د.'	270	
o:	CHANGI A	IRPORT GROUP		TEL: 65412961		Our Quotation No. :	* 1 * 0	1.01/4251	
	————	ind out ditoo!		FAX:		Quotation Date :	26-Jul	-2022	
TTN:		GBF1892E Call Sign: -		b No.;		Code No	VED/VA/22/CA	G/L4/332	
	PT NO. :			3.10.1					
EH/EQ	PT MODEL : SS	SANGYONG							
SIN	SER CODE		SERVICE DESC	RIPTION		QTY	UNIT COST (S\$)	TOTAL COST (S\$)	
-		TO PROVIDE MATERIAL A	ND LABOUR FOR	THE FOLLOWING:					
+									
1	СМ	PANEL BEATING AND REP	AIR REAR RHS F	ENDER		1 LOT	\$ 1,075.00	\$ 1,075.00	
十		PUTTY, SANDING, MASKI	NG AND SPRAY F	PAINTING OF REAR RHS	FENDER				
		TOUCH UP ON REAR RHS							
		REMOVE BROKEN REAR F			0				
		INSTALL NEW REAR RHS			Bro			-	
		CARRY OUT FUNCTIONAL	TEST POST CON	APLETION OF WORK.					
_									
_									
-			144						
+									
-				W					
+				- Allendary - Allendary					
-									
$\dashv$									
_									
_									
							-		
		NOTE: SUPPLEMENTARY QUOTE WILL S	BE SUBMITTED IF ADDITIO	NAL FAULTS ARE FOUND DURING TH	iE .				
		COURSE OF REPAIR.						1	
				Sub-Total:				\$1,075.00	
PROPO	SED TURNAR	OUND TIME	WEEKS/DAYS	GST 7%:				\$75.25	
TAT: S	UBJECT TO A	VAILABILITY OF OVERSEAS SPARES.		GRAND TOTAL :				\$1,150.25	
	QUOTATIO	N PREPARED BY :	FOR CUSTOMER APPR	OVAL:		· · · · · · · · · · · · · · · · · · ·			
Name:	Chong H	uí Li	Approving	040 (11007)			Authority Stan	nn	
Dale:	26-Jul-202		Authority:	CAG / HORTI			Authority Stat	''P	
Sign:	F	1.	Name :				7		
	- '		, some .						
<u></u>	INPUT TO !	VMS BY:	Date:						
Name:	-			,					
Dale:			Signature :						
Sign:	1								