



Your Ref: S2M03XKM

Date: 24th Aug 2022

Our Ref: CS3/ASM22003075/Gvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Teo Kitty

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLL 7988Z

INSURED VEHICLE: SLR 6137M

ACCIDENT DATE: 01/04/2022

We thank you for your instruction on 25/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLL 7988Z from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SLL 7988Z and SMT 2470D.
- c) Final Repair Bill of SLL 7988Z from M/s Speedwerkz Pte Ltd.
- d) Colour damaged vehicle photographs of SLL 7988Z.

Pre-Repair Inspection Date : 04/04/2022 at M/s Speedwerkz Pte Ltd, 13 Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLL 7988Z
Make & Model	: Mercedes Benz B 160
Year of Registration	: 2011
Chassis Number	: WDD2452312J735552
Engine Capacity	: 1498 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.