PRS Filed By: GQ REF: CS3/ASM22003075/Gvy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SPEEDWERKZ

of

Insured: SLR 6137M

Policy No.

Claims No. S2M03XKM

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $64k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLL7988Z Yr Regn: 12 Oct/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MERCEDES BENZ / B 160 c.c 1498

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 164880 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2452312J735552 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45ZR17

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or PETLAS

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 1/4/2022 D.O.I. 04-04-2022

Survey held at W/S 3PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$5000 - $6000
	COE Expiry Date : 30 Apr 2031
	Total Rebate Amount $38,336
6/4/22	Submit PRS, repair range $5,000-$6,000

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 6/4/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / UPD: