

ASSIGNMENT

From: PRS Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SH 6818B
 Policy No. _____
 Claims No. S2M047CK
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBP150S Yr Regn: 18/1/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 150
 Make: Yamaha R15 c.c. 150
 Colour: Black A/C: Insured / Std / HI / NA
 Sp. Reading: N/A T/Radio: Insured / Std / HI / NA
 Eng/No: _____
 C/No: MH3RGR / 10KK 09387
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/60ZR17
 R: 160/60ZR17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 247/22 mm L/Bal. 261/22 mm
 D.O.A. R wave D.O.I. 261/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-10K</u> <u>Repair range 1K-3K</u> <u>3 days</u>
<u>27/7/22</u>	<u>Submit PRS, repair range \$2,000-\$3,000</u>

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 27/7/22-typist

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

\$ + RS. \$

Photos

Others

TOTAL