

LKK Auto Consultants Pte Ltd

Date:

26/07/2022

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL CS/AGI22007112/Tqy3 Ref:

(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHO			
		Code:	AGI
	Policy Particulars	s :- THIRD PARTY CLAIN	I
Insured Veh.	SKS 1238U	Veh. Inspected	PC 3337D
Policy No.		Coverage (\$)	0.00
Claim No.	C10016527/CD	Excess (\$)	0.00
Assign From	SALIZAWATI	Assign Date	26/07/2022
	Vehicle Part	iculars & Condition	
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
	Condi	tions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<u> </u>	Descript	tion of Damages	
	Gener	al Information	
Accident Date	22/07/2022	Inspection Date	28/07/2022
Survey held at	SC AUTO INDUSTRIES (S) PT	E LTD	
	51, SENOKO ROAD . SINGAPORE 758133		
		Remarks	
A)THE INSPECTION	ON WAS CONDUCTED ON A"W	ITHOUT PREJUDICE" BASI	S.
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre Accident Date Survey held at	Policy Particulars Insured Veh. SKS 1238U Policy No. Claim No. C10016527/CD Assign From SALIZAWATI Vehicle Part Make & Model Engine No. HIDDEN Chassis No. Odometer - Brakes General Condit Size R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Accident Date 22/07/2022 Survey held at SC AUTO INDUSTRIES (S) PT 51, SENOKO ROAD SINGAPORE 758133	SINGAPORE SHOPPING CENTRESINGAPORE 239924 Code: Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SKS 1238U Veh. Inspected Policy No. Coverage (\$) Claim No. C10016527/CD Excess (\$) Assign From SALIZAWATI Assign Date Vehicle Particulars & Condition Make & Model Cc Engine No. HIDDEN Year of Reg. Chassis No. Colour Odometer Steering Brakes Modification General Conditions of Tyres KIH Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre L/H Rear Tyre Description of Damages General Information Accident Date 22/07/2022 Inspection Date Survey held at SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD .

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.