

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS3/LPC 22005311/Ray3-1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 8815P

at Workshop m/s HWA PENH AUTO

of 38, WINDY RD #06-03

Insured: LPC

Policy No.

Claims No. 22/22/22/VC05/025884

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 8815P

Yr Regn: 10/08/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda SHUTTLE

c.c 1496

Colour

GREY

A/C: Insured / Std / NI / NA

Sp.Reading

093347

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK81005695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

7-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

02/06/22

D.O.I.

02/06/22

Survey held at

HWA PENH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/07/22 Submit PRS.

04/08/22 Submit LS \$2150, 4 days (Red \$1050, 33%)

Date/Time, File Pass to?



: Prell. Report



: Final Report

1) 04/08 Typist

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format : TP

Lump Sum + H.D.I. (\$) 2150