SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 27/07/2022 14:41 (SGT) Reported by Driver Date of Accident 26/07/2022 14:00 (SGT) Exact Location of Accident 99 Dunbar Walk, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Toyota

Vehicle Registration Number SLD3398U

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner ASIA CAR LEASING PTE. LTD. Company Reg No 2XXXXX397C Email Address abc8627e@gmail.com Mobile Phone No (Phone) +65-81834993 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Vellfire Variant Exact purpose for which vehicle was being used at time of accident Private hire Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private hire

Transmission Auto CC 2494

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number SLD3398U

DRIVER

Name of Driver **ZULKIFLI BIN ANWA** NRIC No SXXXX508I Date Of Birth 16/04/1964 Occupation Outdoor

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	17/11/1990 31 YEARS AND 8 MONTHS Male (Phone) +65-91927524 - abc8627e@gmail.com BLK 651 PASIR RIS DR 10 #04-58 510651 No Hirer No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Side Swipe Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	No 2 No - Yes 1 No
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No -
CIRCUMSTANCES OF ACCIDENT	
PLS REFER TO THE ATTACHED STATEMENT.	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver	YN8423R Commercial vehicle -
Contact Number	-

Address	 	_
Address complement	 	_
Postcode		_
Insurance Company Name	 	_
Nature Of Damage		_
Details of property damaged in accident	 	_
No. Of Passenger (Including Driver)		_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date &

Sketch Plan

Driver's Signature (# driver is not the policyholder) / Date

27/07 Witnessed by Reporting Centre

Ueli A. SLD 33984 Leh B: YN 84120

		1000		
4-2-2				
				,
	***			A
				- AV
			- P /	V
			- A6	
			IXI	
			M	
		11		
		Chr.		
	1000 -1	110		
	00			
	10			
	-			
(AN				The second secon
200				
1				
/				

Declaration

IWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

ON THE STATED DATE AND TIME. I, VEHICLE A
(SLD3398U) WAS TRAVELLING STRAIGHT ON DUNBAR
WALK TOWARDS COLDSTREAM AVENUE. THERE'S A
LORRY (YN8423R) STATIONARY IN FRONT, THEREFORE I
CHECK OPPOSITE LANE IF IS CLEAR. I PROCEED TO GO
BY THE OPPOSITE LANE AFTER I CHECK WAS CLEARED,
AFTER I PASSED BY VEHICLE B (YN8423R) SUDDENLY I
FELT A HUGE IMPACT FROM THE FRONT LEFT PORTION
OF MY VEHICLE. AFTER I ALIGHTED I THEN REALISE
THAT VEHICLE B (YN8423R) CUT OUT AND COLLIDED
ONTO MY VEHICLE.

VEHICLE A: SLD3398U

VEHICLE B: YN8423R























