

ASS. REC. BY: TaughtREF: CS/CT122007159/TCYS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S O/S

Bal. or Market Value: \$86K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLV 3423K Yr Regn: 20171 DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot 3008 1.2 c.c 1199Colour: white A/C: Insured / Std / NI / NASp. Reading: 73230 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF304RHNJWHS3/2690Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 28/2/22Survey held at Prompt chain

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

But N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Rep. Format: _____

Lump Sum / I.B.L. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

PROMPT MOTORS PTE.LTD.

BLK 8 KAKI BUKIT AVENUE 4 #02-16

PREMIER @ KAKI BUKIT

SINGAPORE 415875

UEN: 202214492N

Vehicle number: SLV3424K

Repair Estimate

Make & Model: Peugeot 3008

Chassis number: VF3MRHNYWHS312690

<u>No.</u>	<u>Description of spare parts</u>	<u>Qty</u>	<u>Amount S\$</u>
1	Bonnet	1	\$ 1,345.00 X
2	Bonnet RH hinge	1	\$ 112.00 X
3	Bonnet LH hinge	1	\$ 112.00 X
4	Bonnet insulator	1	\$ 231.00 X
5	Bonnet lock	1	\$ 98.00 X
6	Front bumper	1	\$ 1,487.00 de
7	Front bumper LH fog lamp	1	\$ 288.00 X
8	Front bumper LH fog lamp cover	1	\$ 153.00 X
9	Front bumper LH fog lamp cover chrome	1	\$ 99.00 X
10	Front bumper LH grille garnish	1	\$ 296.00 X
11	Front bumper centre lower garnish	1	\$ 366.00 X
12	Front bumper lower grille	1	\$ 467.00 X
13	Front bumper reinforcement	1	\$ 672.00 X
14	Front bumper lower sniffer	1	\$ 302.00 X
15	Front bumper inner sponge	1	\$ 233.00 X
16	Front bumper RH side retainer	1	\$ 98.00 X
17	Front bumper LH side retainer	1	\$ 98.00 de
18	Front bumper inner air guide	1	\$ 178.00 X
19	Front bumper lower under cover	1	\$ 308.00 X
20	Front bumper RH air duct guide	1	\$ 155.00 X
21	Front bumper LH air duct guide	1	\$ 155.00 X
22	Front bumper LH inner side bracket	1	\$ 167.00 X
23	Front bumper LH parking sensor	1	\$ 251.00 X
24	Front chrome grille	1	\$ 553.00 aut
25	Front chrome grille emblem	1	\$ 96.00 X
26	LH headlamp	1	\$ 2,080.00 aut
27	RH headlamp	1	\$ 2,080.00 X
28	Front LH fender	1	\$ 903.00 X
29	Front LH fender quarter garnish	1	\$ 193.00 X
30	Front LH fender arch moulding	1	\$ 488.00 aut
31	Front LH fender splash shield	1	\$ 176.00 X
32	Front LH fender strengthen	1	\$ 118.00 X

33	Front LH fender accoustic seal	1	\$	93.00X
34	Front LH fender bracket	1	\$	139.00X
35	Front LH fender upper garnish	1	\$	195.00X
36	Support panel top	1	\$	498.00 <i>Cur</i>
37	Support panel top garnish cover	1	\$	387.00 X
38	Support panel top inner cover	1	\$	377.00 X
39	Aircon condenser	1	\$	731.00 X
40	Radiator assy	1	\$	875.00X
41	Front LH wheel hub	1	\$	603.00X
42	Front LH knuckle arm	1	\$	1,367.00 X
43	Front LH wheel bearing	1	\$	652.00 X
44	Front LH lower arm ball joint	1	\$	321.00 X
45	Front LH lower arm	1	\$	667.00 X
46	Front LH shock absorber	1	\$	581.00 X
47	Front LH stabilizer bar linkage	1	\$	167.00 X
48	Front LH tie rod end	1	\$	92.00 X
49	Front LH fuse box upper cover	1	\$	159.00 X
50	Front LH fuse box lower cover	1	\$	295.00 X

	\$	22,557.00
Parts - 10%	\$	2,255.70
Total	\$	<u>20,301.30</u>

<u>No.</u>	<u>Special Nett Items</u>		<u>Amount S\$</u>
1	Bonnet insulator clips	1set	\$ 120.00 X
2	Bonnet seal	1	\$ 100.00 X
3	Front bumper clips	1set	\$ 100.00 <i>3 Over</i>
4	Front bumper LH grille garnish	1set	\$ 80.00 X
5	Front bumper centre lower garnish clips	1set	\$ 80.00 X
6	Front LH fender rivets	1set	\$ 90.00 X
7	Front chrome grille clips	1set	\$ 100.00 X
8	Front LH fender arch moulding clips	1set	\$ 100.00 X
9	Front LH fender splash shield clips	1set	\$ 80.00 X
10	Support panel top garnish cover clips	1set	\$ 80.00 X
11	Front LH sport rim	1	\$ 1,550.00 X
12	Front LH tyre	1	\$ 680.00 X
13	Brake fluid	1	\$ 120.00 X
14	Radiator coolant	1	\$ 150.00 X

Special nett total: \$ 3,430.00

<u>No.</u>	<u>Labour and painting</u>	<u>Amount S\$</u>
1	Labour charges on affected areas and panels	\$ 1,600.00 600
2	Spray painting on affected areas and panels	\$ 1,500.00 600
3	Check wiring and lighting system on affected areas	\$ 100.00 30
4	Apply rust coating chemical on affected areas and panels	\$ 120.00 30
5	Remove and replace aircon condenser and pipes to assist repair. To refill aircon gas	\$ 280.00 X
6	Remove and replace radiator assy, pipes and hoses to assist repair. To refill coolant	\$ 280.00 X
7	Refocus and adjust headlamps assy	\$ 100.00 30
8	Test drive and adjust wheel alignment system (before and after)	\$ 180.00 X
9	Remove and replace front undercarriage parts to assist repair	\$ 650.00 X
10	Remove and replace front LH fuse box and transfer wire harness	\$ 450.00 X

Labour and painting: \$ 5,260.00

Spare Parts: \$ 20,301.30

Special Nett: \$ 3,430.00

Labour: \$ 5,260.00

Total Amount: \$ 28,991.30

Tan Kah 97495749
 'WP' 28/7/22 25pm
 L/S Bay after repair
 To check consistency of accident
 To check part price.
 04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	583D
Vehicle Details	
Vehicle No.:	SLV3423K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Jul 2022
Vehicle Make:	PEUGEOT
Vehicle Model:	3008 ACTIVE PURETECH 1.2 EAT6
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	10XTA40859300
Chassis No.:	VF3MRHNYWHS312690
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,788.00
Original Registration Date:	28 Dec 2017
First Registration Date:	28 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$13,904.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2027
PARF Rebate Amount:	\$10,428.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$23,318.00
Total Rebate Amount:	\$33,746.00

The information contained herein is correct as at 20 Jul 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/07/2022 15:59 (SGT)
Reported by	Driver
Date of Accident	15/07/2022 11:46 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Blk 1A Thomson rd
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV3423K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	DAING MUHAMMAD ASHRAF BIN MOHAMED FARHAN
NRIC No	SXXXX583D
Email Address	huishan512@hotmail.com
Mobile Phone No	(Phone) +65-98231464
Alternative Phone No	+65-92971035

VEHICLE PARTICULARS

Manufacturer	Peugeot
Model	T 3008 1
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1199

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	11072426

DRIVER

Name of Driver	NG HUI SHAN, GINNA
NRIC No	SXXXX145Z

Date Of Driving Pass	21/06/2012
Driving experience	10 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-92971035
Alt. Phone Number	-
Email Address	huishan512@hotmail.com
Address	405 Pasir Ris dr 6
Address complement	#09-489
Postcode	510405
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I SLV3423K was reversing to park into the lot, suddenly the 3rd party GBJ1437R reverse back and collided into the front left side of my vehicle . I managed to take some photos and exchange contact details with the 3rd party, no injuries was involved at the scene and I also had an in car camera footage of the scene.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ1437R
Vehicle Manufacturer	Toyota
Vehicle Model	Hiace
Vehicle Variant	-
Vehicle Colour	Gray

Name of Driver	EDEN
Contact Number	(Phone) +65-83880594
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT DIAGRAM

Ver. Jan2022



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Muhammad Sumardi Bin Mohd Affandi
Witnessed by Reporting Centre
Personnel