



Claim	S2M046LS
Reference	CS3/ASM22007162/Tvy3e2 
Loss Date	11 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	14 Jul 2022 8:45:15 AM
Request Date	27 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	FBR1980X
Vehicle	
Registration #	
Make	TPVD YAMAHA
Model	R15 ABS MANUAL

Service Address

, , ,

Primary Contact/Insured

CHAN YEW HUAI, KENNY
51C LENGKONG EMPAT, #02-04 ASTOR, 417660,
Singapore
90047982

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages2 Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2204724.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	1 August 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	1 August 2022

FAQ English (SG) ▼ Elaine Kuan ▼			TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
	Service Requests	...	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	1 August 2022
	 FBR 1980X IA PRS.pdf.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 July 2022
	 S2M046LS EXTERNAL PRE INSPECTION OF FBR1980X (KCS).msg.msg		Letters and Correspondence	Solicitor / Advocate	ANG Yvonne	27 July 2022
	 SMU9004R INS GIA.pdf.pdf		Reports & Statement	GIA Report	KUMAR Shailendra	14 July 2022