

 Service Request Details

Claim	S2M047L6
Reference	CS/ASM22007166/Tcy3m4 
Loss Date	16 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	27 Jul 2022 9:03:21 AM
Request Date	27 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident	FBB8293J
Vehicle	
Registration #	
Make	TPVD- Yamaha
Model	X-1r

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Additional Instructions

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Other	Other	do not reply	
 HSB-LKKInvoice-AC2301501.pdf.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 March 2023
 Immediate Advice.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 March 2023
 INSD GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	27 July 2022
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	27 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL, Akash	27 July 2022