



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22007176/Acy3e2	
			Date: 21/10/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBD 4333T	Veh. Inspected	SKG 9992K
	Policy No.	D22099240	Coverage (\$)	0.00
	Claim No.	D22002283MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	27/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	RU11102728	Colour	WHITE
	Odometer	405477 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	KAPSEN	6 mm
	L/H Front Tyre	215/60 R16	KAPSEN	6 mm
	R/H Rear Tyre	215/60 R16	KAPSEN	6 mm
	L/H Rear Tyre	215/60 R16	KAPSEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/07/2022	Inspection Date	27/07/2022
	Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	