

Steve

CS# SMR22004763/Egy3

ASSIGNMENT

PRS

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. TAX/05/22/2036


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 97K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM253078 Yr Regn: 30/04/2021

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota VIOS c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 56075 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR2B2SF3001720898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 13/5/22 D.O.I. 20/5/22

Survey held at Car Laboratories

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Workshop no. GIA report

ESTIMATE RANGE OF COR \$2000-\$3000.

Date/Time, File Pass to?

☐ : Prel. Report

1) 01/06 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: PRS

Lump Sum / L.B.F. (\$) _____

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)