

ASS. REC. BY:

REF: AIS / CS/AIS22007225/Kqy3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / CP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ City Ado

of _____

Insured: _____

Policy No. _____

Claims No. SVRAISCL2022-00040SL

Sum Insured: _____ Excess: 3800 +3000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 885k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 20 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBL 17563 Yr Regn: 03, 2, 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toyota C.C. 2734

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 58230 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: G0H201: 207833

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: Mil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 6 mm

L/Bal. 2 mm L/Bal. 6 mm

D.O.A. 23/7/2 D.O.I. 29/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

01/08/22 @ 11.17am revert to Sharon Lim via Merimen.

01/08/22 @ 3.08pm Sharon Lim informed C/A via Merimen.

01/08/22 @ 3.38pm Informed Vronica C/A & ex:\$3800 by email.

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$

Transportation:

: Interview (\$

\$ / RS. / SI

: Tech Invs (\$

Fixes

: Weekend (\$

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (Own Damage)
 Policy No: SPMF100000537
 Vehicle Reg. No.: **GBL1756J**
 Driver Age/Info: 37 / MALE
 TP Injury Involved? NO
 Insured/Claimant: SKYLINK VEHICLE RENTALS PTE LTD
 Driver: Muhammad Halim Bin Raimi

Ref. No: ¹
 Date of Loss: 23/07/2022
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: TOYOTA HIACE, 2.8 D DX (A)
 Vehicle Colour: Silver
 Engine No: 1GD8696223
 Odometer: 0 KM

Vehicle Reg. Date: 24/03/2021

Chassis No: GDH2012017833

*Not Authorised
 Repairing By painting
 Ex @ 1300/-*

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 20 ✓

Remarks: VEHICLE IN
 Present Location: CITY AUTO PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		16,126.00
Miscellaneous Items		98.00
Labour		6,080.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		22,304.00
+ GST 7.00% (S\$)		1,561.28
Nett Amount (S\$)		23,865.28

This claim is handled by: VRONICA

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jul 2022)
 Parts: 213 TOYOTA HIACE 2.8 D DX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: City Auto Pte Ltd/GBL1756J/28/07/2022 16:36
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front windscreen glass	0.00	0.00	CM *450.00 F
2	1		*Front windscreen glass moulding	0.00	0.00	M *55.00 F
3	1		*Bonnet	0.00	0.00	R *285.00 F
4	2		*Bonnet hinge	0.00	0.00	AD Di's *50.00 F
5	1		*Bonnet stand	0.00	0.00	Di's *25.00 F
6	1		*Bonnet stand grommet	0.00	0.00	Mi *5.00 F
7	1		*Bonnet stand holder	0.00	0.00	Mi *8.00 F
8	1		*Bonnet lock	0.00	0.00	R *75.00 F
9	2		*Wiper blade	0.00	0.00	CV *44.00 F
10	2		*Wiper arm	0.00	0.00	*140.00 F
11	1		*Wiper linkage	0.00	0.00	*165.00 F
12	1		*Wiper motor	0.00	0.00	*280.00 F
13	1		*Wiper garnish	0.00	0.00	CM *185.00 F
14	2		*Wiper garnish side cover	0.00	0.00	Mi *40.00 F
15	2		*Wiper garnish side moulding	0.00	0.00	Mi *30.00 F
16	1		*Front Lh door	0.00	0.00	R *650.00 F
17	2		*Front Lh door hinge	0.00	0.00	R *90.00 F
18	1		*Front Lh door checker	0.00	0.00	R *65.00 F
19	1		*Front Lh door sticker	0.00	0.00	M *25.00 F
20	1		*Front Lh door lock	0.00	0.00	*195.00 F
21	1		*Front Lh door regulator	0.00	0.00	R *95.00 F
22	1		*Front Lh door regulator motor	0.00	0.00	J *200.00 F
23	1		*Front Lh door glass	0.00	0.00	Photocopy *200.00 F
24	1		*Front Lh door glass channel	0.00	0.00	Di's *95.00 F
25	1		*Front Lh door outer moulding	0.00	0.00	Di's *55.00 F
26	1		*Front Lh door inner moulding	0.00	0.00	R *65.00 F
27	1		*Front Lh door board	0.00	0.00	CM *350.00 F
28	1		*Front Lh door power window switch	0.00	0.00	*58.00 F
29	1		*Front Lh door audio speaker	0.00	0.00	CM *150.00 F
30	1		*Front Lh door outer handle	0.00	0.00	S *70.00 F
31	1		*Front Lh door rubber	0.00	0.00	CV *80.00 F
32	1		*Front Lh door inner handle	0.00	0.00	*45.00 F
33	1		*Front LH door frame garnish	0.00	0.00	R *45.00 F
34	1		*Front LH door plug	0.00	0.00	P *25.00 F
35	2		*Front LH door stopper	0.00	0.00	R *50.00 F
36	1		*Front LH door protector	0.00	0.00	P *115.00 F
37	1		*Front LH door rubber NO. 2	0.00	0.00	Di's *40.00 F
38	1		*Front LH pillar outer	0.00	0.00	R *200.00 F
39	1		*Front LH pillar cowl panel	0.00	0.00	R *55.00 F
40	1		*Front LH pillar step panel	0.00	0.00	*45.00 F
41	1		*Front LH pillar step under panel	0.00	0.00	*65.00 F
42	1		*Front LH pillar retain	0.00	0.00	L *10.00 F
43	1		*Front LH pillar protector	0.00	0.00	R *55.00 F
44	1		*Front LH pillar bracket	0.00	0.00	R *45.00 F
45	1		*Front LH pillar sub panel	0.00	0.00	R *195.00 F
46	1		*Front LH pillar sub reinforce	0.00	0.00	R *185.00 F
47	1		*Front LH pillar inner panel	0.00	0.00	R *115.00 F

Transporter

Resurvey

48	1	*Front LH pillar cowl side panel lower	0.00	0.00	R	*155.00 F	X
49	1	*Wiper panel	0.00	0.00		*340.00 F	?
50	1	*LH corner panel	0.00	0.00	Bu	*80.00 F	
51	1	*LH mirror outer under view	0.00	0.00	CM	*95.00 F	
52	1	*LH mirror outer cover	0.00	0.00	Mi	*35.00 F	
53	1	*LH headlamp	0.00	0.00		*350.00 F	
54	1	*Front bumper	0.00	0.00	CM	*200.00 F	
55	2	*Front bumper retainer	0.00	0.00	CM	*110.00 F	
56	1	*Front bumper lower grille	0.00	0.00	Sm	*80.00 F	X
57	20	*Front bumper clip	0.00	0.00	me	*40.00 F	
58	1	*Washer tank	0.00	0.00		*75.00 F	?
59	2	*Washer motor	0.00	0.00		*170.00 F	?
60	1	*Coolant spare tank	0.00	0.00		*155.00 F	?
61	1	*Ad blue filler pipe	0.00	0.00		*350.00 F	?
62	1	*Front support panel	0.00	0.00	Buc	*160.00 F	
63	1	*Turbo intercooler	0.00	0.00	Sm	*520.00 F	X
64	1	*Turbo intercooler air guide LH	0.00	0.00	CM	*55.00 F	
65	1	*Turbo intercooler air guide RH	0.00	0.00	Sm	*55.00 F	X
66	1	*Firewall insulator	0.00	0.00		*145.00 F	?
67	1	*Dashboard	0.00	0.00	Bu	*550.00 F	
68	1	*Dashboard reinforcement bar	0.00	0.00		*350.00 F	?
69	1	*Dashboard LH air vent	0.00	0.00		*280.00 F	?
70	1	*Dashboard upper instrument box	0.00	0.00		*145.00 F	?
71	1	*Dahboard lower glove box	0.00	0.00		*145.00 F	?
72	1	*Front LH door frame weatherstrip	0.00	0.00	Di	*105.00 F	
73	1	*Front LH pillar garnish	0.00	0.00	Bu	*120.00 F	
74	1	*Roof lining (Front)	0.00	0.00		*450.00 F	?
75	1	*A/c blower with housing	0.00	0.00		*600.00 F	?
76	1	*A/c evaporator with housing	0.00	0.00		*2,100.00 F	?
77	1	*Front LH wheel cover	0.00	0.00	Sm	*85.00 F	X
78	1	*Boonet logo	0.00	0.00	me	*35.00 F	
79	1	*LH wing mirror	0.00	0.00	CM	*320.00 F	
80	1	*LH wing mirror cover	0.00	0.00	Mi	*55.00 F	
81	1	*Front grille assy	0.00	0.00	Mi	*580.00 F	

F=Franchise part.

Sub Total (\$\$)	14,660.00
+ Margin on L,N Items 10.00% (\$\$)	1,466.00
Total Parts (\$\$)	16,126.00

City Auto Pte Ltd/GBL1756J/28/07/2022 16:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Body lettering	60.00
2	1	Front windsceen glass sealant	20.00
3	1	IU bracket	18.00
Sub Total (\$\$)			98.00

25.50

✓
✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	- To remove and refit front windscreen glass	New	150.00
2	- To remove and refit dashboard unit, reinforcement	New	300.00
3	- To remove and refit air con blower and evaporator unit	New	350.00
4	- To remove and refit roof lining	New	180.00
5	- To remove and refit steering column, brake servo, brake pedal, clutch pedal, intercooler	New	250.00
6	- To remove and refit front trims and upholstery	New	90.00
7	- To supply panel sealant and to seal off all weld spot seams and gaps	New	160.00
8	- To knock jackout damaged parts, panel beating, welding, allign, refix and to renew accident parts	New	3,000.00
9	- Spray painting on affected and replace parts	New	1,600.00
Gross Labour Cost (\$\$)			6,080.00

1200

2500

1500

1200

1200

✓

9d

2400

1400

City Auto Pte Ltd/GBL1756J/28/07/2022 16:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/07/2022 12:34 (SGT)
Reported by Driver
Date of Accident 23/07/2022 15:24 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG LENTOR AVE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBL1756J

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SKYLINK VEHICLE RENTALS PTE LTD
Company Reg No 2XXXXX755G
Email Address YVETTE@SKYLINK.COM.SG
Mobile Phone No (Phone) +65-82612118
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Hiace
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Auto
CC 2279

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number SPMF100000537

DRIVER

Name of Driver MUHAMMAD HALIM BIN RAIMI
NRIC No SXXXX190D
Date Of Birth 10/06/1985
Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature, Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

CITY AUTO PTE LTD
 Blk 8 Sin Ming Road
 #01-58/60/62 Sin Ming Ind Est
 Singapore 575643
 Tel: 6453 1235 Fax: 6453 7944

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

