

A.S.S. REC. BY: Toupin

REF: CS/CT122007228/993

**ASSIGNMENT**

CE 2025 July  
Yr Regn: 20101 8 July

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspected Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SLS/4864  
Type: 2 Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Volkswagen Polo 1.4 c.c 1390  
Colour: Red A/C: Insured / Std / NI / NA  
Sp. Reading: 119282 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WV 22261024057287  
Gen. Cond: 2 Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
Mod: Nil / 2 SRim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 185/60R15  
R: 2

N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Wynnho  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 2/8/22 45pm  
Survey held at Bilfret  
Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or  
Ft. o/s, 4C  
The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: 928K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Preli. Report  
1)  : Final Report

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?  
2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS, SI \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL \_\_\_\_\_

Report Format: \_\_\_\_\_  
Lump Sum / E.B. / F: \_\_\_\_\_



No.	Special Nett Items	Qty	Amount S\$
1	Front bumper clips	1set	\$ <del>300</del> 100.00
2	Front RH fender splash shield clips	1set	\$ 1 100.00
3	Front RH tyre	1	\$ x 680.00
4	Radiator coolant	1	\$ x 120.00
5	Front RH door sealant	1	\$ x 120.00
6	Brake fluid	1	\$ x 100.00
Total:			\$ 1,220.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <del>500</del> 1,400.00
2	Spray painting on affected areas and panels	\$ <del>200</del> 1,300.00
3	Check wiring and lighting system on affected areas	\$ <del>X</del> 120.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 100.00
5	Remove and replace front undercarriage parts to assist repair	\$ 150 450.00
6	Test drive and adjust wheel alignment system (before and after)	\$ 80 180.00
7	Remove and replace front RH door inner mechanism to new door	\$ X 180.00
8	Refocus and adjust headlamps assy	\$ X 100.00
9	Bleed brake system and check leakage	\$ x 100.00
Total:		\$ 3,930.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 15,094.80

Special Nett: \$ 1,220.00

Labour: \$ 3,930.00

**Total Amount: \$ 20,244.80**

Tanpin 97495749  
 'WP' 2/8/22 @ 450pm

LB heavy after repair  
 Tanpin @ 1hr 15min  
 off days  
 to check work is fine of accident  
 to check part price.

**LKK Auto Consultants** hereby notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	221J
Vehicle Details	
Vehicle No.:	SLS1486H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jul 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	CGG337944
Chassis No.:	WVWZZZ6RZAU057787
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$15,064.00
Original Registration Date:	06 Jul 2010
First Registration Date:	06 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$15,064.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jul 2025
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,438.00
COE Rebate Amount:	\$9,669.00
<b>Total Rebate Amount:</b>	<b>\$9,669.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jul 2022

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	26/07/2022 15:57 (SGT)
Reported by	Both
Date of Accident	26/07/2022 09:00 (SGT)
Exact Location of Accident	Tampines, Singapore
Additional Location Information	458 TAMPINES CARPARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1486H
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	MOHAMAD FAZIL BIN MUHAYAT
NRIC No	S8741221J
Email Address	fazilmuhayat@gmail.com
Mobile Phone No	(Phone) +65-93621667
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Polo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

## INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10598701R01

## DRIVER

Name of Driver	MOHAMAD FAZIL BIN MUHAYAT
NRIC No	S8741221J
Date Of Birth	23/12/1987
Occupation	Indoor

Date Of Driving Pass	26/06/2018
Driving experience	4 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-93621667
Alt. Phone Number	-
Email Address	fazilmuhayat@gmail.com
Address	BLK 458 TAMPINES STREET 42 #06-304
Address complement	-
Postcode	520458
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

MY VEHICLE IS PARKED IN THE CARPARK WHEN I WENT TO COLLECT MY CAR, I FOUND MY VEHICLE FRONT RIGHT DAMAGED AND A NOTE FROM VEHICLE B DRIVER INDICATING THAT HE HAD COLLIDED ONTO VEHICLE C, CAUSING VEHICLE C TO HIT ONTO MY CAR.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH3037A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SKV7962G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE C
No. Of Passenger (Including Driver)	-

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**6. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

**Sketch Plan**



**Describe Circumstance of the Accident**  
My vehicle is parked in the carport, when I went to  
check my car, I found my vehicle front right damaged -  
and a note from vehicle B driver indicating that he  
had collided into vehicle C, causing vehicle C to hit into  
my car.

**Declaration**

We declare the foregoing particulars are true in every respect

  
Policyholder's Signature (Date) & Time

Driver's Signature (if other is not the policyholder) (Date  
& Time)

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)