

ASS. REC. BY:

REF:

C72 / 22 007231 kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 8916A

Yr Regn:

03, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toyota A175

c.c

1598

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

92778

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104557169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

27/7/22

D.O.I.

29/7/2022

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S + RS. \$

Fixes

Others

TOTAL

Report Format :

ump Sum / I.B.I: (\$

SLL8916A
TP(CHINA)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2022)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL8916A)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	R	0.00	*200.00 F	✓
2	1		*1 PC REAR BUMPER REINFORCEMENT	R	0.00	*115.00 F	✓
3	1		*1 PC REAR BUMPER REINFORCEMNT INNER RETAINER LH	D11	0.00	*40.00 F	✓
4	1		*1 PC REAR BUMPER REINFORCEMNT INNER RETAINER RH	D11	0.00	*40.00 F	✓
5	1		*1 PC REAR BUMPER SIDE RETAINER LH	D11	0.00	*35.00 F	✓
6	1		*1 PC REAR BUMPER SIDE RETAINER RH	D11	0.00	*35.00 F	✓
7	1		*6 PCS REAR BUMPER CLIPS @2/PC	R	0.00	*12.00 F	✓
8	1		*1 PC REAR BUMPER LH BRACKET		0.00	*38.00 F	?
9	1		*1 PC REAR BUMPER RH BRACKET		0.00	*38.00 F	?
10	1		*1 PC REAR SMART KEY SENSOR		0.00	*48.00 F	?
11	1		*1 PC BOOTLID	R	0.00	*320.00 F	✓
12	1		*1 PC BOOTLID INSULATOR	R	0.00	*190.00 F	X
13	1		*6 PCS BOOTLID INSULATOR CLIPS @2/PC	R	0.00	*12.00 F	✓
14	1		*1 PC BOOTLID LOGO	R	0.00	*28.00 F	✓
15	1		*1 PC BOOTLID EMBLEM (COROLLA)	R	0.00	*35.00 F	✓
16	1		*1 PC BOOTLID EMBLEM (ALTIS)	R	0.00	*35.00 F	✓
17	1		*1 PC LH TAILLAMP		0.00	*148.00 F	?
18	1		*1 PC RH TAILLAMP		0.00	*148.00 F	?
19	1		*1 PC REA END PANEL	R	0.00	*230.00 F	✓
20	1		*1 PC REA END PANEL INNER TRIM	mg D11	0.00	*95.00 F	✓
21	1		*3 PCS REAR END PANEL INNER TRIM CLIPS @2/PC	R	0.00	*6.00 F	✓
22	1		*1 PC BOOTLID UPPER LOCK		0.00	*150.00 F	?
23	1		*1 PC BOOTLID WEATHER STRIP	D11/R	0.00	*60.00 F	✓
24	1		*1 PC REAR FLOOR TOP COVER BOARD	cm	0.00	*170.00 F	✓
25	1		*1 PC REAR SPARE TYRE COMPARTMENT	R	0.00	*380.00 F	X
26	1		*1 PC FRT BUMPER		0.00	*210.00 F	?
27	1		*1 PC FRT BUMPER ABSORBER FOAM		0.00	*55.00 F	?
28	1		*1 PC FRT BUMPER REINFORCEMENT		0.00	*160.00 F	?
29	1		*1 PC FRT GRILLE		0.00	*150.00 F	?
30	1		*1 PC FRT BRACE PANEL		0.00	*58.00 F	?
31	1		*1 PC FRT TOP COVER	NSP	0.00	*58.00 F	X
32	1		*1 PC HEADLAMP LH	mg cm	0.00	*600.00 F	✓
33	1		*1 PC HEADLAMP RH	mg cm	0.00	*600.00 F	✓
4	1		*1 PC FRT SUPPORT PANEL	R	0.00	*290.00 F	✓
Total Parts (S\$)						4,789.00	

=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merlmen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	1 PC FRT NUMBER PLATE	35.00 ✓
1	1 SET REVERSE SENSOR	200.00 ✓
Sub Total (S\$)		235.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	X
2	REMOVE & REFIX REAR BUMPER, REAR BOOT & ATTACHMENT, TAIL LAMPS, LOCK ASSY, TO CUT, WELD & RENEW REAR PANEL, REAR COMPARTMENT, KNOCK & REPAIR REAR FENDERS AND REALIGN THE SAME	New	1,100.00	
3	REMOVE & REFIX SEAT, REAR GARNISH, ETC	New	50.00	✓
4	PUTTY & RESPRAY ON REAR BUMPER, REINFORCEMENT, BOOT, HINGES, REAR PANEL, REAR COMPARTMENT, REAR FENDER	New	1,100.00	✓
5	REMOVE & REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, GRILLE, RADIATOR & MOTOR, TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	New	600.00	✓
6	PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT, SUPPORT PANEL, BONNET	New	700.00	✓
7	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	✓
8	REMOVE & REFIX REVERSE CAMERA, SENSOR, SMART KEY SENSOR AND RESET SYSTEM	New	50.00	✓
9	RUSTPROOFING	New	90.00	✓
Gross Labour Cost (\$)			3,890.00	

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/07/2022 19:15 (SGT)
Reported by Both
Date of Accident 27/07/2022 18:50 (SGT)
Exact Location of Accident Singapore
Additional Location Information TAMPINES EXPRESSWAY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL8916A

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LU YU
NRIC No SXXXX720B
Email Address yulu6@yahoo.com
Mobile Phone No (Phone) +65-97911177
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model COROLLA ALTIS 1.6 CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1598

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number SP2000878344-01

DRIVER

Name of Driver LU YU
NRIC No SXXXX720B
Date Of Birth 24/02/1966
Occupation Indoor

Describe Circumstance of the Accident

** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (/) Claim Third party () Reporting Only

() Claim OD/ TP at other workshop ()

Sketch Plan

TPE TWDS CTE (Near Punggol)



A: SLL 8916A

B: SJD 4795Z

Eugene Lim Yuk Chean

S 9209858C

HP: 88583180

C: SLX 7268E

Fong Chee Loo, Bendy

S 8036857G (HP: 93801194)

DOA: 27/7/22 6.50pm

Refer Police Report

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

(43) mg 28/7/22

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)