

ASS. REC. BY:

REF: C72/ 22 007231/Kg93

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 868k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLL 8916AYr Regn: 03, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyC.C. 1598Colour M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading 92778

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NR053REH104557169Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/452R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 7 mmL/Bal. 6 mmL/Bal. 7 mmD.O.A. 27/7/22D.O.A. 29/7/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/8 21 Rm @ 6850k

24/12 11 Pump @ 6400k Car Insured (Red @ 2934, 31%)

Date/Time, File Pass to?

1) 23/12 14:30

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prell. Report☐ : Final ReportDays Of Repair: 10Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL


Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

MER-TP

Lump Sum / I.B.K. (\$)

6400



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(SJD4795Z)
Policy No:		Date of Loss:	27/07/2022
Vehicle Reg. No.:	SLL8916A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LU YU	Driver (Insured):	EUGENE LIM YUK CHEAN
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Vehicle Reg. Date:	15/03/2017
Vehicle Colour:	GREY		
Engine No:	1ZRY324299	Chassis No:	MR053REH104557169
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Remarks:	VEHICLE CURRENTLY LYING YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*NOT WITHIN  
11 Day @ 6850/hr  
Meaning After Pain  
10 days*

## COST OF CLAIMS

	Amount
Parts	4,789.00
Miscellaneous Items	235.00
Labour	3,890.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>8,914.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>623.98</b>
<b>Nett Amount (S\$)</b>	<b>9,537.98</b>

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

SLL 8916 A

TP/CHINA

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2022)  
**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SLL8916A)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	B <sub>1</sub> 0.00	0.00	*200.00 F	✓
2	1		*1 PC REAR BUMPER REINFORCEMENT	B <sub>1</sub> 0.00	0.00	*115.00 F	✓
3	1		*1 PC REAR BUMPER REINFORCEMNT INNER RETAINER LH	D <sub>1</sub> 0.00	0.00	*40.00 F	✓
4	1		*1 PC REAR BUMPER REINFORCEMNT INNER RETAINER RH	D <sub>1</sub> 0.00	0.00	*40.00 F	✓
5	1		*1 PC REAR BUMPER SIDE RETAINER LH	D <sub>1</sub> 0.00	0.00	*35.00 F	✓
6	1		*1 PC REAR BUMPER SIDE RETAINER RH	D <sub>1</sub> 0.00	0.00	*35.00 F	✓
7	1		*6 PCS REAR BUMPER CLIPS @2/PC	na 0.00	0.00	*12.00 F	✓
8	1		*1 PC REAR BUMPER LH BRACKET	B <sub>1</sub> 0.00	0.00	*38.00 F	✓
9	1		*1 PC REAR BUMPER RH BRACKET	B <sub>1</sub> 0.00	0.00	*38.00 F	✓
10	1		*1 PC REAR SMART KEY SENSOR	CM 0.00	0.00	*48.00 F	✓
11	1		*1 PC BOOTLID	R <sub>1</sub> 0.00	0.00	*320.00 F	✓
12	1		*1 PC BOOTLID INSULATOR	Sn 0.00	0.00	*190.00 F	X
13	1		*6 PCS BOOTLID INSULATOR CLIPS @2/PC	na 0.00	0.00	*12.00 F	✓
14	1		*1 PC BOOTLID LOGO	na 0.00	0.00	*28.00 F	✓
15	1		*1 PC BOOTLID EMBLEM (COROLLA)	na 0.00	0.00	*35.00 F	✓
16	1		*1 PC BOOTLID EMBLEM (ALTIS)	na 0.00	0.00	*35.00 F	✓
17	1		*1 PC LH TAILLAMP	Sn 0.00	0.00	*148.00 F	X
18	1		*1 PC RH TAILLAMP	my CM 0.00	0.00	*148.00 F	✓
19	1		*1 PC REA END PANEL	B <sub>1</sub> 0.00	0.00	*230.00 F	✓
20	1		*1 PC REA END PANEL INNER TRIM	my D <sub>1</sub> 0.00	0.00	*95.00 F	✓
21	1		*3 PCS REAR END PANEL INNER TRIM CLIPS @2/PC	na 0.00	0.00	*6.00 F	✓
22	1		*1 PC BOOTLID UPPER LOCK	na 0.00	0.00	*150.00 F	✓
23	1		*1 PC BOOTLID WEATHER STRIP	Dis/na 0.00	0.00	*60.00 F	✓
24	1		*1 PC REAR FLOOR TOP COVER BOARD	Sn CM 0.00	0.00	*170.00 F	X
25	1		*1 PC REAR SPARE TYRE COMPARTMENT	R 0.00	0.00	*380.00 F	X
26	1		*1 PC FRT BUMPER	CM 0.00	0.00	*210.00 F	✓
27	1		*1 PC FRT BUMPER ABSORBER FOAM	Sn 0.00	0.00	*55.00 F	X
28	1		*1 PC FRT BUMPER REINFORCEMENT	R 0.00	0.00	*160.00 F	X
29	1		*1 PC FRT GRILLE	CM 0.00	0.00	*150.00 F	✓
30	1		*1 PC FRT BRACE PANEL	B <sub>1</sub> 0.00	0.00	*58.00 F	✓
31	1		*1 PC FRT TOP COVER	NTP 0.00	0.00	*58.00 F	X
32	1		*1 PC HEADLAMP LH	my CM 0.00	0.00	*600.00 F	✓
33	1		*1 PC HEADLAMP RH	my CM 0.00	0.00	*600.00 F	✓
34	1		*1 PC FRT SUPPORT PANEL	B <sub>1</sub> 0.00	0.00	*290.00 F	✓

F=Franchise part.

Air-con condense

R<sub>1</sub>

420.00 ✓

Total Parts (\$\$)

4,789.00

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	1 PC FRT NUMBER PLATE	35.00 ✓
2	1	1 SET REVERSE SENSOR	200.00 ✓
Sub Total (\$\$)			235.00

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00 X
2	REMOVE & REFIX REAR BUMPER,REAR BOOT & ATTACHMENT,TAILLAMPS,LOCK ASSY,TO CUT,WELD & RENEW REAR PANEL,REAR COMPARTMENT,KNOCK & REPAIR REAR FENDERS AND REALIGN THE SAME	New	1,100.00
3	REMOVE & REFIX SEAT,REAR GARNISH,ETC	New	50.00 ✓
4	PUTTY & RESPRAY ON REAR BUMPER,REINFORCEMENT,BOOT,HINGES,REAR PANEL,REAR COMPARTMENT,REAR FENDER	New	1,100.00
5	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,GRILLE,RADIATOR & MOTOR,TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	New	600.00
6	PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,SUPPORT PANEL,BONNET	New	700.00
7	REMOVE & REFIX AIRCON,CHECK,VACUUM & REFILL GAS	New	100.00 ✓
8	REMOVE & REFIX REVERSE CAMERA,SENSOR,SMART KEY SENSOR AND RESET SYSTEM	New	50.00 ✓
9	RUSTPROOFING	New	90.00 ✓
Gross Labour Cost (\$\$)			3,890.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supp 1

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Aug 2022)

**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Cheng Hoe Motor Pte Ltd/SLL8916A/19/08/2022 13:56

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC AIRCON CONDENSOR	0.00	0.00	<i>Per</i> *420.00 F ✓
			Total Parts (S\$)			420.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SLL8916A/19/08/2022 13:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SLL8916A/19/08/2022 13:56. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	720B
<b>Vehicle Details</b>	
Vehicle No.:	SLL8916A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY324299
Chassis No.:	MR053REH104557169
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	15 Mar 2017
First Registration Date:	15 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$19,990.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2027
PARF Rebate Amount:	\$13,993.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$22,841.00
<b>Total Rebate Amount:</b>	<b>\$36,834.00</b>

The information contained herein is correct as at 28 Jul 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	28/07/2022 19:15 (SGT)
Reported by	Both
Date of Accident	27/07/2022 18:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TAMPINES EXPRESSWAY
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL8916A

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LU YU
NRIC No	SXXXX720B
Email Address	yulu6@yahoo.com
Mobile Phone No	(Phone) +65-97911177
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	COROLLA ALTIS 1.6 CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

#### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2000878344-01

#### DRIVER

Name of Driver	LU YU
NRIC No	SXXXX720B
Date Of Birth	24/02/1966
Occupation	Indoor

Date Of Driving Pass	13/06/2009
Driving experience	13 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-97911177
Alt. Phone Number	-
Email Address	yulu6@yahoo.com
Address	318C YISHUN AVE 9 #05-142
Address complement	-
Postcode	763318
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER POLICE REPORT

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD4795Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	EUGENE LIM YUK CHEAN
NRIC No	SXXXX858C
Contact Number	(Phone) +65-88583180
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLX7268E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	FONG CHEE LUP, BENDY
NRIC No	SXXXX857G
Contact Number	(Phone) +65-93801194
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	LU YU
Gender	Male
Phone No	(Phone) +65-97911177
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	FEEL DIZZY AND NECK PAIN
Injured person in which vehicle?	SLL8916A
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

VEH NO : SLL 8916A  
INSURER : Allianz  
DATE OF ACC : 27/7/22 18:50

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) ng 28/7/22  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**



Describe Circumstance of the Accident

\*\* NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

( ) Claim Own Policy ( / ) Claim Third party ( ) Reporting Only

( ) Claim OD/ TP at other workshop ( )

Sketch Plan

Sketch Plan

(Near Punggol)

TPE TWDS CTE

A: SLL 8916A

B: SJD 47952

Eugene Lim Yuk Chean

S 9209858C

HP: 88583180

C: SLX 7268E

Fong Chee Lup, Bendy

S 8036857G (HP: 93801194)

DOA: 27/7/22 6.50pm

Refer Police Report

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) eng 28/7/22  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20220728/7013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 28/07/2022 10:54		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LU YU			Address: 318C YISHUN AVENUE 9 #05-142 SINGAPORE 763318		
ID Type / ID No.: NRIC NO / S2643720B			Contact No.: Home/Office: Mobile: 97911177		
Nationality: SINGAPORE CITIZEN			Email: YULU6@YAHOO.COM		
Sex: Male	Age: 56	Date of Birth: 24/02/1966	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 3A Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 27/07/2022 18:50	Type of Location: Straight Road
Location:  TAMPINES EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SJD4795Z	Car	KIA		Red		0
SLL8916A	Car	TOYOTA	Altis	Blue		0
SLX7268E	Car	HONDA	Shuttle	White		0



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	EUGENE LIM YUK CHEAN	ID No.	S9209858C
Related Vehicle	SJD4795Z (Car)	Contact No.	88583180
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
<b>Driver</b>			
Name	FONG CHEE LUP, BENDY	ID No.	S8036857G
Related Vehicle	SLX7268E (Car)	Contact No.	93801194
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
<b>Vehicle Owner</b>			
Name	LU YU	ID No.	S2643720B
Related Vehicle	NIL	Contact No.	97911177
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3A Date of Expiry: NIL
Date	27/07/2022	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Slight

**Brief Details.**

On 27July, around 6:50pm, I was driving on the right lane on TPE towards CTE near punggol , when the car in front of me (Honda Shuttle SLX7268E) brake and stop, I (Toyota Altis SLL8916A) also brake and stop with distance. meanwhile the car behind me (KIA SJD4795Z) fail to stop and collide the back of my car. The huge impact push me to hit the car in front of me. After the accident, all drivers exchange IC and driving license, phone number. Photo and video is taken in the accident place. After I went back home, I feel dizzy and neck pain, about 8:30pm, I went to GP to see doctor, doctor do check up and prescribed medicine for me, gave me 3 days MC.



**SINGAPORE  
POLICE FORCE**



T/20220728/7013

3 of 4

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No. T/20220728/7013

**CONTINUATION OF REPORT**



**SINGAPORE  
POLICE FORCE**



T/20220728/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20220728/7013

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MOHAMAD ZULFAZDLI BIN ABDULLAH  
Contact No.: 65476204

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
28/07/2022 10:54

Classification Of Case: