

ComfortDelGro Engineering Pte Ltd

59 Loyang Drive Singapore 508969

\cap	ır	R	ρſ

305524758

Via Fax

EMEGC -

Date

: 28-7-22

Your Insured

EU 39831

Time of Fax

Date of Acc

Date of Acc

Attn: Motor Claims Department

ALMANIZ

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH



Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Lim Kwok Eng
 Jumani Bin Masudin
 Lim Tien Siong
 Tel: 6214 8355 or HP: 9824 0811
 Tel: 6214 8315 or HP: 9635 5305
 Tel: 6214 8398 or HP: 9635 8546

jumanibm@cdge.com.sg Fax no. 6546 8156

♦ Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Tax Accident Repair



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 28.07.2022 13:40

Page: 1

m:

ARC Repair TP(CLSO)1

JOB CARDSales Order:

JC NG05524758

MILEAGE

FUEL

OMER

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO. 7010045
RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

DUNT CARD NO.

MODEL I-40 28.07.2022 10:10

YR OF MANU. 21.07.2016

REGN NO.: SHD3361Y

MAKE: HYUNDAI

TARGET DATE

E......F

CHASSIS CODE KMHLB41UMGU092206

COMPLETION DATE/TIME:

JOB DESCRIPTION


:ident Date: 27.07.2022 'URE: 3P 27.07.22/C

urned to Service Reception upon collection

10

LABOR CODE

DESCRIPTION



			*		
KED & PASSED OUT BY:					
SERVICE ADVISOR			CUSTOMER'S SIGNATURE		
edgement Slip		Exit Pass	12	×	2
JU SHD3361Y JU	ALLI AN Z	Vehicle No.:	SHD3361Y		
Service Advisor	Signature/Date	Name of Service Ad	visor	Date	

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.07.2022 Time: 13:47:48

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO 305524758 **CUSTOMER: 7010045** REGN NO SHD3361Y ADDRESS: COMFORT TRANSPORTATION PTE LTD MILEAGE : 0000000000

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

: HYUNDAI MAKE MODEL : I-40

DATE OF REGN : 21.07.2016 DATE/TIME IN : 28.07.2022 10:10

ACCIDENT DATE : 27.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER FRT COVER+ 1 1,052.20 25.00 789.15

0002 04-01-0103-0781-A LAMP ASSY-HEAD LH#

1 1,388.00 25.00 1,041.00

0003 04-01-0103-0574-A PANEL-FENDER LH+

1 663.00 25.00 497.25

0004 04-01-0103-0639-G BRACKET-FR BUMPER SIDE LH 1 44.80 25.00 33.60

0005 04-01-0101-0111-G BUMPER COVER CLIP FRT 10 L 22.00 25.00 16.50

SUB-TOTAL : 2,377.50

JOB NATURE

0000 PB PANEL BEATING 600.00

0001 SP

SPRAYPAINT CHARGE

600.00

0002 17-01

CHECK ALL LIGHTING

50.00

0003 20-00

TUFF COAT ON AFFECTED PARTS.

50.00

SUB-TOTAL : 1,300.00

COMFORTDELGRO ENGINEERING PTE LTD

SURVEYOR NAME & SIGNATURE

Date: 28.07.2022 Time: 13:47:48

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO

: 305524758 : SHD3361Y

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL

: I-40

DATE OF REGN DATE/TIME IN

: 21.07.2016

: 28.07.2022 10:1

ACCIDENT DATE 27.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,677.50

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

DATE:

DATE: