

ALLIANZ (4sum)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.07.2022

REPAIR ESTIMATE

Time: 13:47:48

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305524758
REGN NO : SHD3361Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 28.07.2022 10:10
ACCIDENT DATE : 27.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	BUMPER FRT COVER+	1	1,052.20	25.00	789.15	de ✓
0002 04-01-0103-0781-A	LAMP ASSY-HEAD LH#	1	1,388.00	25.00	1,041.00	mer ✓
0003 04-01-0103-0574-A	PANEL-FENDER LH+	1	663.00	25.00	497.25	ht ✓
0004 04-01-0103-0639-G	BRACKET-FR BUMPER SIDE LH	1	44.80	25.00	33.60	de ✓
0005 04-01-0101-0111-G	BUMPER COVER CLIP FRT	10 L	22.00	25.00	16.50	mer ✓

SUB-TOTAL : 2,377.50

JOB NATURE

0000 PB	PANEL BEATING	600.00	350
0001 SP	SPRAYPAINT CHARGE	600.00	500.
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30

SUB-TOTAL : 1,300.00

Tanpin 97495744
wp' 28/7/22 24pm
L/S Resurvey after repair
Tanpin @ Lkh auto-wor
2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.07.2022

REPAIR ESTIMATE

Time: 13:47:48

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305524758
REGN NO : SHD3361Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 21.07.2016
DATE/TIME IN : 28.07.2022 10:1
ACCIDENT DATE : 27.07.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,677.50

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

m: ARC Repair TP(CLSO)1

JOB CARD Sales Order:


JC NO 305524758

OMER	REGN NO: SHD3361Y	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD 7010045	MAKE: HYUNDAI	FUEL E.....1/2.....F
OMER NO. 383 SIN MING DRIVE	MODEL I-40	DATE/TIME IN 28.07.2022 10:10
LESS Singapore SINGAPORE 575717	YR OF MANU. 21.07.2016	TARGET DATE
(R) 65508755 (O)	CHASSIS CODE KMHLB41UMGU092206	COMPLETION DATE/TIME:
(P)		
DUNT CARD NO.		

Ident Date: 27.07.2022
URE: 3P 27.07.22/C

JOB DESCRIPTION

TO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SHD3361Y

JU ALLIANZ

Vehicle No.:

SHD3361Y

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard