



## Case Details

Case Reference Number : TAX/07/22/2071  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB144M

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-18920-ID  
 Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
 Accident Date and Time : 23/07/2022 08:30 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	R
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	R
One Time Key In	Main			PLATE, REAR WHEEL HOUSE, FRONT LH	1	26.80	26.80	25.00	20.10	Replace	0	0	Not Give	Xan
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	R
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	Xan
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xan
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	R

Total Spare Part Cost 4,662.07

Surveyor Total 0.00

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,729.66

Final Sur Total 0.00

## Case Details

Case Reference Number : TAX/07/22/2071  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB144M

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-18920-ID  
 Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
 Accident Date and Time : 23/07/2022 08:30 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	R
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	R
One Time Key In	Main			PLATE, REAR WHEEL HOUSE, FRONT LH	1	26.80	26.80	25.00	20.10	Replace	0	0	Not Give	Xan
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair	R
One Time Key In	Main			LINER, REAR FENDER, LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	Xan
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	Xan
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	R

Total Spare Part Cost 4,662.07

Surveyor Total 0.00

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,729.66

Final Sur Total 0.00

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Give	Xan
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	Xan
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	Xan
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	0	0	Not Give	Xan
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	R
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Give	Xan
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	0	0	Not Give	Xan
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	Xan
<b>Total Spare Part Cost</b>									<b>4,662.07</b>	<b>Surveyor Total</b>		<b>0.00</b>		
<b>Lump Sum Discount (%)</b>									<b>20.00</b>	<b>Lump Sum Dis (%)</b>		<b>20</b>		
<b>Final Spare Part Cost</b>									<b>3,729.66</b>	<b>Final Sur Total</b>		<b>0.00</b>		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	845.00	300	
<b>Total:</b>			<b>845.00</b>	<b>300.00</b>	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESRAY REAR DOOR LH	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING LH	180.00	100	
3	Main	TO RESPRAY REAR FENDER LH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	0 <i>Xm</i>	
5	Main	TO RESPRAY REAR BUMPER	378.00	200	
6	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
<b>Total:</b>			<b>1,674.00</b>	<b>780.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0 <i>Xm</i>	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0 <i>Xm</i>	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0 <i>Xm</i>	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 <i>Xm</i>	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	120.00	0 <i>Xm</i>	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xm</i>	
7	Main	TO WASH AND VACUUM	60.00	0 <i>Xm</i>	
<b>Total:</b>			<b>700.00</b>	<b>0.00</b>	

**Summary**

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,729.66	0.00
Total Labour Cost	845.00	300.00
Total Spray Painting	1,674.00	780.00
Other	700.00	0.00
Overall Total	6,948.66	1,080.00
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Total	6,950.00	1,100.00
Surveyor Approved Amount		1,100.00
No of Repair Days*	7	3
Remarks	-	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO.
Surveyor Name		Rasul
Signature		
Survey Date	28/07/2022	

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
 Signature:  
 Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	26/07/2022 10:26 (SGT)
Reported by	Driver
Date of Accident	23/07/2022 16:30 (SGT)
Exact Location of Accident	Nanson Rd, Singapore
Additional Location Information	NANSON ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB144M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

## DRIVER

Name of Driver	MOHD SHARIFF BIN OMAR
NRIC No	SXXXX654I
Date Of Birth	14/02/1964
Occupation	Outdoor

Date Of Driving Pass	01/08/2000
Driving experience	21 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	FAHMI
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Woodlands East Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007679999
Police Station Address	3 Woodlands Drive 63 Singapore 737890
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT - T/20220723/2109

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFK63P
-----------------------------	--------


Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Private car  
Name of Driver ..... -  
Contact Number ..... -  
Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

**WITNESS DETAILS**

WITNESS 1

Name ..... FAHMI  
Phone ..... -  
Email ..... -

SKETCH PLAN



A large rectangular area with horizontal lines, intended for a written declaration or notes.

Declaration

We declare the foregoing particulars are true in every respect.



Print Name & Qualifying Position & Title

*[Signature]* 25/7/2002

Driver's Signature (if there is not this policy holder) Date & Time

*[Signature]* 25.7.2002

Witness (If Required) Complete (Name & Address) (Not to be used for No. C11-1000)





**SINGAPORE  
POLICE FORCE**



T/20220723/2109

1 of 3

Report No. T/20220723/2109

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/07/2022 19:16	Video Report No.:	Station Diary No.: 118
--	-------------------	---------------------------

**Informant's Particulars**

Name of Informant: MOHD SHARIFF BIN OMAR		Address: APT BLK 682D WOODLANDS DRIVE 73 #12-231 SINGAPORE 734682	
ID Type / ID No.: NRIC NO / S16466541		Contact No.:	Mobile: 96442726
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 58	Date of Birth: 14/02/1964	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class:	Date of Expiry:

**General Information of the Accident**

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 23/07/2022 16:30	Type of Location: T-Junction
Location: NANSON ROAD			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFK63P	Car	HONDA			Slightly Damaged	0
SHB144M	Car	TOYOTA			Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE  
POLICE FORCE**



T/20220723/2109

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

2 of 3

Report No. T/20220723/2109

## CONTINUATION OF REPORT

Driver			
Name	MOHD SHARIFF BIN OMAR	ID No.	S16466541
Related Vehicle	SHB144M (Car)	Contact No.	96442726
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	FAHMI	ID No.	NIL
Related Vehicle	SHB144M (Car)	Contact No.	88778954
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 23/07/2022 at about 1630hrs, I was sending my passenger to Intercontinental hotel along Nanson Road with a speed of less than 40km/h. There is a vehicle SFK63P came out from the drop/pick up point of the building The Quayside and hit into my vehicle rear left side, the car then drove off without stopping the car.

My vehicle has some scratches on the left rear passenger seat close to the rear tyre.

I did not manage to see the plat number of the vehicle, and my passenger passed me the vehicle plate number of the vehicle.

No one was injured and no police or paramedic attended to us.

I am lodging this report for company record purpose.



**SINGAPORE  
POLICE FORCE**



T/20220723/2109

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3  
Report No. T/20220723/2109

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: L / SCCPL XIE SIBIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/07/2022 19:16
Officer In Charge Of Case: TP / HRT / STAFF SGT SUFIYAN BIN KHAIRI Contact No: 65476148	Classification Of Case:

NP162

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 369K

### Vehicle Details

Vehicle No.: SHB144M  
Vehicle to be Exported: No  
Intended Deregistration Date: 31 Jul 2022  
Vehicle Make: TOYOTA  
Vehicle Model: PRIUS HYBRID 1.8 CVT  
Primary Colour: Maroon  
Manufacturing Year: 2017  
Engine No.: 2ZR5105065  
Chassis No.: JTDKB3FU403574436  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$29,007.00  
Original Registration Date: 28 Nov 2017  
First Registration Date: 28 Nov 2017  
Transfer Count: 0  
Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Nov 2025  
PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 27 Nov 2025  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 8  
PQP Paid: \$33,596.00  
COE Rebate Amount: \$13,963.00  
Total Rebate Amount: \$17,713.00

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Jul 2022