

ASS. REC. BY: Taufiq

REF: CS/CT122007271/T9C

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMD4185Z Yr Regn: 2018, Aug  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Elantra C.C. 1591  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 50958 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KM H0841 (M) \* J4 725926  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: 195/65R15  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 975K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS WP  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 18/22  
 Survey held at Prompt Motors  
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Rep. Format : \_\_\_\_\_  
 Lump Sum / I.B.I. (%) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

## Prompt Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : SMD 4185Z  
Made : Hyundai  
Model : Elantra  
Chassis No : \_\_\_\_\_

### \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper	1	\$ 459.40	\$ <i>del</i> 459.40
2	Rear Bumper Lower	1	\$ 251.00	\$ <i>del</i> 251.00
3	Rear Bumper Side Retainer RH	1	\$ 45.00	\$ <i>au</i> 45.00
4	Rear Bumper Side Retainer LH	1	\$ 45.00	\$ <i>ua</i> 45.00
5	Rear Bumper Number Plate Lamp RH	1	\$ 18.00	\$ <i>x</i> 18.00
6	Rear Bumper Number Plate Lamp LH	1	\$ 18.00	\$ <i>x</i> 18.00
7	Rear Bumper Side Guard RH	1	\$ 15.00	\$ <i>x</i> 15.00
8	Rear Bumper Under Cover LH	1	\$ 37.20	\$ <i>tm</i> 37.20
9	Rear Bumper Reflector RH	1	\$ 40.80	\$ <i>cu</i> 40.80
10	Rear Bumper Reflector LH	1	\$ 40.80	\$ <i>ut</i> 40.80
11	Rear Bumper Upper Bracket	2	\$ 6.00	\$ <i>x</i> 12.00
12	Rear Bumper Reinforcement	1	\$ 294.80	\$ <i>bt</i> 294.80
13	Rear Bootlid	1	\$ 1,782.40	\$ <i>bt</i> 1,782.40
14	Rear Bootlid Hinge RH	1	\$ 94.30	\$ <i>x</i> 94.30
15	Rear Bootlid Hinge LH	1	\$ 94.30	\$ <i>x</i> 94.30
16	Rear Bootlid Inner Trim	1	\$ 146.80	\$ <i>x</i> 146.80
17	Rear Bootlid Lock	1	\$ 116.20	\$ <i>bt</i> 116.20
18	Rear Bootlid Lock Catch	1	\$ 20.00	\$ <i>x</i> 20.00
19	Rear Bootlid Weatherstrip	1	\$ 92.50	\$ <i>tm</i> 92.50
20	Rear Bootlid Reflector Lamp RH	1	\$ 664.20	\$ <i>x</i> 664.20
21	Rear Bootlid Reflector Lamp LH	1	\$ 664.20	\$ <i>x</i> 664.20
22	Rear Bootlid Emblem	1	\$ 82.00	\$ <i>nel</i> 82.00
23	Rear Bootlid "Elantra" Emblem	1	\$ 88.00	\$ <i>nel</i> 88.00
24	Rear Bootlid "S" Emblem	1	\$ 78.00	\$ <i>nel</i> 78.00
25	Smart Key Antenna	1	\$ 40.50	\$ <i>x</i> 40.50
26	Rear Taillamp Assembly RH	1	\$ 876.80	\$ <i>au</i> 876.80
27	Rear Taillamp Assembly LH	1	\$ 876.80	\$ <i>ua</i> 876.80
28	Rear Taillamp Panel RH	1	\$ 193.10	\$ <i>g</i> 193.10
29	Rear Taillamp Panel LH	1	\$ 193.10	\$ <i>x</i> 193.10
30	Rear Fender RH	1	\$ 1,892.00	\$ <i>x</i> 1,892.00
31	Rear Fender LH	1	\$ 1,892.00	\$ <i>x</i> 1,892.00
32	Rear Fender Air Vent RH	1	\$ 75.20	\$ <i>x</i> 75.20

33	Rear Fender Air Vent LH	1	\$	75.20	\$ X	75.20
34	Rear Fender Stone Protective Sticker RH	1	\$	37.02	\$ X	37.02
35	Rear Fender Stone Protective Sticker LH	1	\$	37.02	\$ X	37.02
36	Rear Fender Inner Trim RH	1	\$	208.00	\$ X <i>h</i>	208.00
37	Rear Fender Inner Trim LH	1	\$	208.00	\$ X <i>h</i>	208.00
38	Rear Fender Inner Shield RH	1	\$	60.40	\$ X	60.40
39	Rear Fender Inner Shield LH	1	\$	60.40	\$ X	60.40
40	Rear Windscreen Glass Moulding	1	\$	129.80	\$ X	129.80
41	Rear End Panel	1	\$	454.60	\$ <i>bt</i>	454.60
42	Rear End Panel Top Garnish	1	\$	60.00	\$ <i>de</i>	60.00
43	Rear Floor Panel	1	\$	640.80	\$ <i>h</i>	640.80
44	Rear Floor Side Panel RH	1	\$	246.50	\$ X	246.50
45	Rear Floor Side Panel LH	1	\$	246.50	\$ X	246.50
46	Rear Floor Panel Centre Member	1	\$	1,188.70	\$ X	1,188.70
47	Rear Floor Panel Top Board	1	\$	220.00	\$ X	220.00
48	Spare Tyre Lock Screw	1	\$	27.50	\$ X	27.50
49	Rear Exhaust Pipe	1	\$	856.00	\$ X	856.00
50	Rear Exhaust Pipe Heat Shield	1	\$	258.80	\$ X	258.80
51	Rear Exhaust Pipe Mounting	2	\$	32.00	\$ X	64.00
52	Front Bumper	1	\$	474.40	\$ <i>de</i>	474.40
53	Front Bumper Number Plate Garnish	1	\$	110.00	\$ X	110.00
54	Front Bumper Lower Lip	1	\$	251.00	\$ X	251.00
55	Front Bumper Side Air Duct RH	1	\$	125.00	\$ X	125.00
56	Front Bumper Fog Lamp RH	1	\$	294.00	\$ X	294.00
57	Front Bumper Fog Lamp Garnish RH	1	\$	78.00	\$ X	78.00
58	Front Bumper Side Air Duct LH	1	\$	125.00	\$ X	125.00
59	Front Bumper Fog Lamp LH	1	\$	294.00	\$ X	294.00
60	Front Bumper Fog Lamp Garnish LH	1	\$	78.00	\$ X	78.00
61	Front Bumper Lower Beam	1	\$	199.00	\$ X	199.00
62	Front Bumper Side Retainer RH	1	\$	38.00	\$ X	38.00
63	Front Bumper Side Retainer LH	1	\$	38.00	\$ X	38.00
64	Front Bumper Sponge	1	\$	110.70	\$ <i>h</i>	110.70
65	Front Bumper Reinforcement	1	\$	695.80	\$ X	695.80
66	Front Headlamp Assembly RH	1	\$	1,198.80	\$ <i>ow</i>	1,198.80
67	Front Headlamp Assembly LH	1	\$	1,198.80	\$ <i>ow</i>	1,198.80
68	Front Headlamp Lower Bracket RH	1	\$	89.20	\$ X	89.20
69	Front Headlamp Lower Bracket LH	1	\$	89.20	\$ X	89.20
70	Front Grille Assembly	1	\$	529.20	\$ <i>ow</i>	529.20
71	Front Grille Emblem	1	\$	68.00	\$ <i>ow</i>	68.00
72	Front Bonnet	1	\$	1,970.70	\$ X	1,970.70
73	Front Bonnet Lock	1	\$	129.70	\$ X	129.70
74	Front Support Panel	1	\$	949.30	\$ <i>ow</i>	949.30
75	Aircon Condenser	1	\$	987.10	\$ X	987.10
76	Radiator	1	\$	996.80	\$ X	996.80
77	Aircon Condenser Side Garnish RH	1	\$	59.80	\$ X	59.80

78	Aircon Condenser Side Garnish LH	1	\$	59.80	\$ X	59.80
79	Front Fender RH	1	\$	521.60	\$ X	521.60
80	Front Fender Inner Shield RH	1	\$	140.70	\$ X	140.70
81	Front Fender Mudguard RH	1	\$	68.80	\$ X	68.80
82	Front Fender LH	1	\$	521.60	\$ X	521.60
83	Front Fender Inner Shield LH	1	\$	140.70	\$ X	140.70
84	Front Fender Mudguard LH	1	\$	68.80	\$ X	68.80
					Parts Sub Total :	\$ 29,018.14
					20% Discount	\$ 5,803.63
					<b>PARTS TOTAL :</b>	<b>\$ 23,214.51</b>

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Rear Number Plate	1	\$ 50.00	\$ X 50.00	
2	Front Number Plate	1	\$ 50.00	\$ cut ✓ 50.00	
3	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30w ✓ 50.00	
4	Rear Taillamp Assembly Clips - Set	1	\$ 50.00	\$ X 50.00	
5	Rear Bootlid Reflector Lamp Clips - Set	1	\$ 50.00	\$ X 50.00	
6	Rear Bootlid Inner Trim Clips - Set	1	\$ 40.00	\$ X 40.00	
7	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 20w ✓ 50.00	
8	Rear Fender Inner Trim Clips - Set	1	\$ 80.00	\$ X 80.00	
9	Rear Fender Inner Shield Clips - Set	1	\$ 40.00	\$ X 40.00	
10	Front Bumper Clips - Set	1	\$ 50.00	\$ 30w ✓ 50.00	
11	Front Grille Assembly Clips - Set	1	\$ 50.00	\$ X 50.00	
12	Front Bonnet Insulator Clips - Set	1	\$ 40.00	\$ X 40.00	
13	Front Fender Inner Shield Clips - Set	1	\$ 40.00	\$ X 40.00	
14	Rear Bootlid Sealant	1	\$ 150.00	\$ X 150.00	
15	Rear End Panel Sealant	1	\$ 120.00	\$ 40w ✓ 120.00	
16	Rear Floor Panel Sealant	1	\$ 150.00	\$ X 150.00	
17	Rear Fender RH Sealant	1	\$ 150.00	\$ X 150.00	
18	Rear Fender LH Sealant	1	\$ 150.00	\$ X 150.00	
19	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ X 150.00	
20	Front Bonnet Sealant	1	\$ 150.00	\$ X 150.00	
21	Front Fender RH Sealant	1	\$ 150.00	\$ X 150.00	
22	Front Fender LH Sealant	1	\$ 150.00	\$ X 150.00	
23	Radiator Coolant	1	\$ 60.00	\$ X 60.00	
24	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 200w ✓ 250.00	
25	Rear Bootlid Outer Handle c/w Camera	1	\$ 450.00	\$ X 450.00	
<b>SPECIAL NETT TOTAL :</b>					<b>\$ 2,720.00</b>

Nos.	LABOUR	S\$
1	To Panel Beat, Remove & Refix Parts ( Front )	\$ 400, 1,600.00
2	To Spray Paint Affected Areas ( Front )	\$ 200, 1,600.00
3	To Panel Beat, Remove & Refix Parts ( Rear )	\$ 800, 2,600.00
4	To Spray Paint Affected Areas ( Rear )	\$ 800, 2,200.00
5	Wiring & Bulb Check ( Front )	\$ 30, 100.00

6	Wiring & Bulb Check ( Rear )	\$ 30	100.00
7	To Remove & Refix Rear Windscreen Glass	\$ X	150.00
8	To Transfer Rear Bootlid Mechanism	\$ 60	150.00
9	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30	120.00
10	To Remove & Refix Rear Bootlid Reverse Camera	\$ 30	150.00
11	To Remove & Refix Rear Exhaust Pipe	\$ X	120.00
12	To Remove & Refix Fuel Tank	\$ X	250.00
13	To apply anti rust on affected parts	\$ 30	250.00
14	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60	150.00
15	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X	150.00
16	To Remove & Refix Radiator and Pressure Test	\$ X	150.00
17	To Conduct Water Leak Test	\$ X	100.00
18	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
<b>LABOUR TOTAL :</b>		<b>\$</b>	<b>10,420.00</b>

PARTS TOTAL : \$ 23,214.51

SPECIAL NETT TOTAL : \$ 2,720.00

LABOUR TOTAL : \$ 10,420.00

**GRAND TOTAL : \$ 36,354.51**

Taufik 97495749  
 WP' 1/8/22 @ 1145  
 4/5 Resurvey after repair  
 Taufik @ lkh auto.com  
 to check consistency of accident  
 to check part prices  
 9 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Motorist Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	066I
Vehicle Details	
Vehicle No.:	SMD4185Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Jul 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4FGJU232519
Chassis No.:	KMHD841CMJU725926
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,477.00
Original Registration Date:	20 Aug 2018
First Registration Date:	20 Aug 2018
Transfer Count:	1
Actual ARF Paid:	\$12,477.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Aug 2028
PARF Rebate Amount:	\$9,357.00
Intended COE Rebate Details	
COE Expiry Date:	19 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,893.00
COE Rebate Amount:	\$20,524.00
Total Rebate Amount:	\$29,881.00

The information contained herein is correct as at 23 Jul 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 25/07/2022 16:16 (SGT)  
Reported by ..... Both  
Date of Accident ..... 22/07/2022 18:30 (SGT)  
Exact Location of Accident ..... KPE, Singapore  
Additional Location Information ..... -  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMD4185Z

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... MUHAMED IRSHATH S/O LIAKATH ALI  
NRIC No ..... S9449066I  
Email Address ..... muhamedirshath1994@gmail.com  
Mobile Phone No ..... (Phone) +65-90059737  
Alternative Phone No ..... -

#### VEHICLE PARTICULARS

Manufacturer ..... Hyundai  
Model ..... Elantra  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1591

#### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Policy Number / Cover Note Number ..... 5122872543

#### DRIVER

Name of Driver ..... MUHAMED IRSHATH S/O LIAKATH ALI  
NRIC No ..... S9449066I  
Date Of Birth ..... 17/12/1994  
Occupation ..... Outdoor

Date Of Driving Pass .....	11/03/2014
Driving experience .....	8 YEARS AND 4 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-90059737
Alt. Phone Number .....	-
Email Address .....	muhamedirshath1994@gmail.com
Address .....	BLK 207B COMPASSVALE LANE
Address complement .....	#03-28
Postcode .....	543207
Is the driver the policyholder? .....	Yes
If No, Relationship of the Driver with the Insured .....	-
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Chain Collision
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	3
Was anybody injured in the Accident? .....	Yes
Was any injured conveyed to hospital by ambulance? .....	No
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Paya Lebar Neighbourhood Police Post
Police Station Address .....	Blk 114 Hougang Avenue 1 #01-1270 Singapore 530114
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT ATTACHED.

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SJL8901C
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Private car

Name of Driver ..... -  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number ..... SMC5045T  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Private car  
 Name of Driver ..... -  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person ..... MUHAMED IRSHATH S/O LIAKATH ALI  
 Gender ..... Male  
 Phone No ..... -  
 Address ..... -  
 Address Complement ..... -  
 Post Code ..... -  
 Approximate Age Years Old ..... -  
 Injuries Sustained ..... 5 DAYS OF MEDICAL LEAVE  
 Injured person in which vehicle? ..... SMD4185Z  
 Were seat belts worn? ..... -  
 Was this injured conveyed to hospital by ambulance? ..... -

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes


  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NR-CID card)



**Sketch Plan**



A) SMD4185Z  
B) SMC5045T  
C) SJE8901C



**SINGAPORE  
POLICE FORCE**



T/20220723/2075

1 of 3

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

Report No. T/20220723/2075

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/07/2022 15:27	Vide Report No.:	Station Diary No.: 25
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: MUHAMED IRSHATH S/O LIAKATH ALI		Address: APT BLK 207B COMPASSVALE LANE #03-28 SINGAPORE 543207	
ID Type / ID No.: NRIC NO / S94490661		Contact No.: Home/Office:                      Mobile: 90059737	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 27	Date of Birth: 17/12/1994	Type of Informant: Driver
Race: Indian		Language:	Institution / School Name:
Occupation: PROJECT ENGINEER		Driving Licence Information: Class: 3                      Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/07/2022 18:30	Type of Location: tunnel
Location:  KALLANG PAYA LEBAR EXPRESSWAY				
Weather: inside tunnel		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJE8901C	Car				Seriously Damaged	0
SMC5045T	Car				No Damage	2
SMD4185Z	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT (AMS)	Red	Seriously Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20220723/2075

2 of 3

Report No. T/20220723/2075

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMD4185Z	NTUC Income Insurance Co-Operative Limited	5122872543	09/07/2021	19/09/2022

**Brief Details.**

On 22/07/2022 at about 1830hrs, I met with an accident along KPE TPE airport rd tunnel. My vehicle, number: SMD4185Z, was hit by another vehicle, number: SJE8901C, from the rear, causing my vehicle to accidentally hit the vehicle Infront of me, number: SMC5045T. Road marshall arrived to assess the situation. No ambulance was required on that day.

I did not receive any visible injury on that day nor did the other 2 party.

I started to feel pain at night and decided to go to a general practitioner to be examined. I received five days medical leave.

I am making a police report for insurance claiming purposes.



**SINGAPORE  
POLICE FORCE**



T/20220723/2075

Police Station Of Origin:  
Paya Lebar NPP  
114 Hougang Avenue 1 #01-1270  
SINGAPORE 530114  
Tel No: 1800-2899999

3 of 3  
Report No. T/20220723/2075

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: F / SGT 1 MUHAMMAD RAFIQUE <i>Rafique</i> BIN ROSLAN	Signature Of Informant: <i>Info</i>
Signature Of Interpreter: Not applicable	Date/Time: 23/07/2022 15:27
Officer In Charge Of Case: TP / AEIT / SSI TAY CHUN KEEN Contact No.: 65476436	Classification Of Case:

NP168