



## Service Request Details

Claim

S2M047VS

Reference

None 

Loss Date

29 July 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

1 Aug 2022 9:01:52 AM

Request Date

1 August 2022

Due Date

8 August 2022

Services

Pre-Repair Survey

### Actions

---

Next Step

Agree to perform service

Accept Work

## Vehicle Information

---

Incident Vehicle Registration #

SMC4670U

Make

TPVD

Model

Honda

## Service Address

---

'''

## Primary Contact/Insured

---

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

## Claim Handler

---

HO Winnie

winnie.ho@axa.com.sg

## Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

---

 Document SubType

 Upload Documents

### Already Attached

NAME	 REPLY FROM TP.msg.msg
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE UPLOADED	1 August 2022

---

NAME	 INS GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KUMAR Shailendra
DATE UPLOADED	1 August 2022

---

NAME	 PRS TP.pdf.pdf
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	KUMAR Shailendra
DATE UPLOADED	1 August 2022

---

NAME	 PRI TP EMAIL.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	KUMAR Shailendra
DATE UPLOADED	1 August 2022

---

SUBTYPE Workshop  
AUTHOR KUMAR Shailendra  
DATE UPLOADED 1 August 2022

---

NAME  SMC4670U TP GIA.pdf.pdf  
TYPE Reports & Statement  
SUBTYPE GIA Report  
AUTHOR KUMAR Shailendra  
DATE UPLOADED 1 August 2022

---