

CS 4 / 1CS22007372 / 7vy3

ASSIGNMENT

Veh No: Yr Regn: 2017 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz .C200. 1991 1991

Colour White A/C: Insured / Std / NI / NA

Sp. Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2050422K*11F05

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R18

R: 4 4

X	
N/S	O/S

PS / DIUN / EYNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm

L/Bal. (mm L/Bal. 6 mm

D.O.A. D.O.I. 2/8/72 @ 3:15 pm

Survey held at Jewell photo

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report

Final Report

Days Of Repair: .

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

Letter Series / I.E.L. (7)

☐ : Interview (\$

Tech Invs (\$)

Weekend (\$

Survey Fee:

Transportation:

$$) \quad \underline{\hspace{1cm}} S + RS, \underline{\hspace{1cm}} SI$$

1) Photos

1) Others

TOTAL

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No:200311009C)

Blk 6 Woodlands Road 399F,, Yew Tee Ind Estate

Singapore 678006

Tel: 67622081 Fax: 67604895 Email: utauto@singnet.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	YTKB/OD/2208/003
Policy No:	MPC21P0019500	Date of Loss:	31/07/2022
Vehicle Reg. No.:	SMD9920K	Driveable?	NO
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SONG JUN YANG, SIMON	Contact No:	+6592261188
Driver:	SONG JUN YANG, SIMON		
Make/Model:	MERCEDES-BENZ C200, 2.0 AMG (A)	Vehicle Reg. Date:	03/05/2017
Vehicle Colour:	WHITE/PEARL	Gen Condition:	POOR
Engine No:	27492030612914	Chassis No:	WDD2050422R171783
Odometer:	0 KM		
Paint Type:	METALLIC 2K		
Total Loss?	YES		
Est. Duration of Repair (day)	180		

Present Location: **YEW TEE AUTOMOBILE TECH PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$)	0.00
- Excess (\$)	500.00
Nett Amount (\$)	-500.00

This claim is handled by: **TOH TZE CHANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
Not Authorise
Revert Ex \$500
2/8/22 @ 3:5 pm

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2022)**Parts:** 192 MERCEDES-BENZ C200 2.0 AMG (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMD9920K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air cleaner	0.00	0.00	-
2	1		Air cleaner air flow duct	0.00	0.00	-
3	1		Air cleaner air flow sensor	0.00	0.00	-
4	1		Air cleaner cover	0.00	0.00	-
5	1		Air cleaner element	0.00	0.00	-
6	1		Air cleaner heater duct	0.00	0.00	-
7	1		Air cleaner hose	0.00	0.00	-
8	1		Air cleaner housing	0.00	0.00	-
9	1		Air-cond compressor	0.00	0.00	-
10	1		Air-cond compressor V belt	0.00	0.00	-
11	1		Air-cond condenser	0.00	0.00	-
12	1		Air-cond discharge hose	0.00	0.00	-
13	1		Air-cond fan blade	0.00	0.00	-
14	1		Air-cond fan motor	0.00	0.00	-
15	1		Battery bracket	0.00	0.00	-
16	1		Battery cable	0.00	0.00	-
17	1		Battery cable [+]	0.00	0.00	-
18	1		Battery cable [-]	0.00	0.00	-
19	1		Battery clamp	0.00	0.00	-
20	1		Battery earth cable	0.00	0.00	-
21	1		Battery panel	0.00	0.00	-
22	1		Battery tray	0.00	0.00	-
23	1		Bonnet	0.00	0.00	-
24	1		Bonnet adjustable stopper LH	0.00	0.00	-
25	1		Bonnet adjustable stopper RH	0.00	0.00	-
26	1		Bonnet cable	0.00	0.00	-
27	1		Bonnet hinge LH	0.00	0.00	-
28	1		Bonnet hinge RH	0.00	0.00	-
29	1		Bonnet insulator	0.00	0.00	-
30	1		Bonnet insulator clips	0.00	0.00	-
31	1		Bonnet lock	0.00	0.00	-
32	1		Bonnet rubber	0.00	0.00	-
33	1		Bonnet rubber clip	0.00	0.00	-
34	1		Bonnet rubber inner	0.00	0.00	-
35	1		Bonnet rubber inner clip	0.00	0.00	-
36	1		Bonnet rubber LH	0.00	0.00	-
37	1		Bumper air grille center, front	0.00	0.00	-
38	1		Bumper clip, front	0.00	0.00	-
39	1		Fender LH, front	0.00	0.00	-
40	1		Fender moulding LH, front	0.00	0.00	-
41	1		Fender shield clip LH, front	0.00	0.00	-
42	1		Fender shield LH, front	0.00	0.00	-
43	1		Fuse box	0.00	0.00	-
44	1		Fuse box cover	0.00	0.00	-
45	1		Headlamp bulb LH	0.00	0.00	-

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		Headlamp LH	0.00	0.00	-
47	1		Radiator	0.00	0.00	-
48	1		Radiator fan blade	0.00	0.00	-
49	1		Radiator fan motor	0.00	0.00	-
50	1		Radiator grille	0.00	0.00	-
51	1		Radiator lower hose	0.00	0.00	-
52	1		Radiator mounting lower	0.00	0.00	-
53	1		Radiator mounting upper	0.00	0.00	-
54	1		Radiator panel	0.00	0.00	-
55	1		Radiator upper hose	0.00	0.00	-
56	1		Relay, air-cond	0.00	0.00	-
57	1		Relay, battery	0.00	0.00	-
58	1		Relay, box main body	0.00	0.00	-
59	1		Relay, headlamp	0.00	0.00	-
60	1		W/screen glass, front	0.00	0.00	-
61	1		Wheelhouse LH, front	0.00	0.00	-
62	1		Wiper air grille	0.00	0.00	-
63	1		Wiper air grille clips	0.00	0.00	-
64	1		Wiper arm cover LH, front	0.00	0.00	-
65	1		Wiper arm cover RH, front	0.00	0.00	-
66	1		Wiper arm LH, front	0.00	0.00	-
67	1		Wiper arm RH, front	0.00	0.00	-
68	1		Wiper blade LH, front	0.00	0.00	-
69	1		Wiper blade RH, front	0.00	0.00	-
70	1		Wiper blade rubber LH, front	0.00	0.00	-
71	1		Wiper blade rubber RH, front	0.00	0.00	-
72	1		Wiper link, front	0.00	0.00	-
73	1		Wiper motor, front	0.00	0.00	-
74	1		Wiper nozzle LH, front	0.00	0.00	-
75	1		Wiper panel	0.00	0.00	-
76	1		Wiper tank motor, front	0.00	0.00	-
77	1		Wiper tank, front	0.00	0.00	-
78	1		Wiper tube Y joint	0.00	0.00	-
79	1		Alternator	0.00	0.00	-
80	1		Alternator & water pump V belt	0.00	0.00	-
81	1		Engine	0.00	0.00	-
82	1		Engine cylinder head	0.00	0.00	-
83	1		Engine cylinder head gasket	0.00	0.00	-
84	1		Engine electronic control relay	0.00	0.00	-
85	1		Engine electronic control unit	0.00	0.00	-
86	1		Engine mounting LH	0.00	0.00	-
87	1		Engine mounting RH	0.00	0.00	-
88	1		Engine oil filter	0.00	0.00	-
89	1		Engine oil filter casing	0.00	0.00	-
90	1		Engine oil filter casing gasket	0.00	0.00	-
91	1		Engine oil intercooler pipe	0.00	0.00	-
92	1		Engine oil pressure switch	0.00	0.00	-
93	1		Engine rocker cover	0.00	0.00	-
94	1		Engine water pump	0.00	0.00	-
95	1		Intercooler, turbo charger	0.00	0.00	-
96	1		Spark plug cable no. 1	0.00	0.00	-
97	1		Spark plug cable no. 2	0.00	0.00	-
98	1		Spark plug cable no. 3	0.00	0.00	-
99	1		Spark plug cable no. 4	0.00	0.00	-
100	1		Absorber bush LH, front	0.00	0.00	-
101	1		Absorber LH, front	0.00	0.00	-
102	1		Air-cond blower	0.00	0.00	-
103	1		Air-cond cooling coil	0.00	0.00	-
104	1		Dashboard	0.00	0.00	-

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						0.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**