

ASS. REC. BY: Taufik

REF:

INC NS/INC22007326/Tqc

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: ms lake

Vehicle: IN / OUT

Veh No: SHD 6876J Yr Regn: 2022 March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prio c.c 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 42515 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STD PCB3FY 903093811
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: NI / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wan Hui
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 27/6/22
 Survey held at Comfort Lodge
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt + N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP-INC-9865916P

Taufikh finalised final fig \$1056.13, 2 days. (Red \$218.07, 17%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 2

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

Transportation:

2)

Add Fee:

☐ : Site Insp (\$

S + RS. SI

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Others

☐ : Weekend (\$

TOTAL

Report Format: TP

Lump Sum / L.B.R. 1056.13

REPAIR ESTIMATE

Model : Prius

MVA: MS. LOKE YY

Taughin 9749549
WP' 27/6/77 2430
R/R P/R Romy before paint
02 days
taughin C. E. Hunt on

Acknowledged by Repairer
Signature: _____
Date: _____

Date/Time: 27.06.2022 15:35

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299710


JC NO 305521309

STOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 .. (R) 65508755 (O) (P) COUNT CARD NO.	REGN NO: SHD6876J	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4A27)	DATE/TIME IN 06.2022 12:05
	YR OF MANU. 24.03.2022	TARGET DATE
	CHASSIS CODE JTDKB3FU903093811	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.06.2022
NATURE: 3P 27.06.2022

3/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ement Slip

Exit Pass

SHD6876J

YY

Vehicle No.:

SHD6876J

vice Advisor

Signature/Date

Name of Service Advisor

Date

rd to Service Reception upon collection

To be kept by Security Guard