

ASS. REC. BY: Taufik

REF:

INC NS/INC22007330/Tqc

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SM 96864 Yr Regn: 2017 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 794297 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STDURBSF4305561466
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 2 -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wipac
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 1/8/22
 Survey held at Comfort Agency
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear of
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S
	<input checked="" type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS up
 Date: _____ Person Contacted: Awang Vehicle: IN / OUT

Date / Time	Action / Instruction
	Taufikh finalised LS \$2400, 2 days. (Red \$2220.32, 48%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Rep. Format: TP
 Lump Sum (A.B.): 2400

Days Of Repair: 2
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH9686U

31.07.2022

MAKE REG 19.07.2017

CHIANG/ NTUC

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER		all \$503.04
1	REAR BUMPER SIDE RETAINER RH		net \$112.70
1	REAR BUMPER LOWER COVER		cut \$654.96
1	REAR BUMPER UNDER SIDE RH		? \$232.00
1	REAR BUMPER REINFORCEMENT		X \$378.32
10	REAR BUMPER CLIPS	\$2.20	net \$22.00
1	TAIL LAMP RH UPP		net \$557.90
1	TAIL LAMP RH LOW		cut \$570.00
	SUB TOTAL		\$3,030.92
	25.00%		\$757.73
	DISCOUNTED TOTAL		\$2,273.19
1	REAR REVERSE SENSOR		X \$135.70
1	REAR BUMPER MAT		net \$50.00
1	REAR BUMPER ADVERTISEMENT		net \$50.00
2	REAR FENDER ADVERTISEMENT	\$100.00	net \$200.00
1	BOOTLID COMFORT APP		X \$40.00
1	BOOTLID COMFORT/TEL NO STICKER		X \$60.00
			\$462.13
	Labour Charge		
	Panel Beating		350 \$850.00
	Spray Painting Charge		500 \$600.00
	Remove/Refix Upholstery rear		X \$60.00
	Tuff Kote		X \$60.00
	Check Lighting		30 \$60.00
	TOTAL LABOUR		\$1,885.00
	ESTIMATE TOTAL		\$4,620.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495749
 in 18/7/2022
 2 days
 1/2 hrs app upon
 hand of Mr. C. K. auto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4493791

JC No: 905525035

STOMER

MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

DRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

COUNT CARD NO.

REGN NO.:

SH 9686U

MILEAGE

MAKE :

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)01.08.2022 09:30

DATE/TIME IN

YR OF MANU.

19.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU303561466

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 31.07.2022

NATURE: 3P 31.07.2022

NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SH 9686U

CHIANG

Vehicle No.:

SH 9686U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard