Our Job R Date	04.08.2022	ENGINEERING  ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
	TION FORM		Fax: 6546 8156		
To : _	LKK	-1	Fax:		
Attn :	TAUFIKH	_			
Vehicle Re	g No. : SH 9839X	Date of Acc	ident: 29.07.2022		
The survey	and estimates of the repairs of the above	-mentioned vehicle a	are as follows:-		
1. The	repair job shall bill to:	TUC	SLA8808L		
2. The	finalized amount shall be:				
(a)	Spare Parts after List discount		: =		
(b)	Labour Charges (include advertisemen	nt stickers etc,if any)			
	Total for Part-By-Part Repair Cost		-		
(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less Final Lumpsum Repair cost	s: 20%	\$800.00 \$800.00		
	nated normal period for repairs:shall treat the above amount as Correct	2 working da			
	in 7 working days				
5. Than	nk you for your assistance.	We confirm finalized an	n the estimates and nount		
Sign Nam Tel	ature : e : LIM T S : 62148398	Signature : Name :	TAUFIKH 26/9/22		
Fax	65468156		9		

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid	, earth	N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00	Υ		
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks	i.			