

ASS. REC. BY:

REF: C12/ 22 007351/KC

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S/C 9421B Yr Regn: 05.16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1498Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 121306 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R41 1117506Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Rotalla

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 26/7/22D.O.I. 29/7/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/8 21km @ 56501 Ckm and 8 days (Red \$4,066.00 / 42%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

S + RS. \$

Fees


Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

**TP INSURER:** China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(YN8563U)
Policy No:		Date of Loss:	26/07/2022
Vehicle Reg. No.:	SLC9421B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOW POH NYUK	Driver (Insured):	CHUA PEI XIN

Make/Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Vehicle Reg. Date:	30/05/2016
Vehicle Colour:	BLUE		
Engine No:	L15B4037508	Chassis No:	RU11117505
Odometer:	0 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	0

*NOT WITHHELD  
11 Days @  
Resuming After Paint  
8 days*

Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	5,211.00
Miscellaneous Items	1,415.00
Labour	3,090.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>9,716.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>680.12</b>
<b>Nett Amount (S\$)</b>	<b>10,396.12</b>

**This claim is handled by: SHARON CHIONG BENG CHOON**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 29 Jul 2022)

Parts: M1-SUV

HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC9421B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

SLC9421B

TP/CHINA

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	0.00	0.00	*180.00 F	C
2	1		*1 PC REAR BUMPER LOWER UNDER COVER	0.00	0.00	*75.00 F	X
3	1		*6 PCS REAR BUMPER LOWER UNDER COVER CLIPS @2/PC	0.00	0.00	*12.00 F	X
4	1		*1 PC REAR BUMPER LH SIDE PAD	0.00	0.00	*68.00 F	C
5	1		*1 PC REAR BUMPER LH RETAINER	0.00	0.00	*12.00 F	C
6	1		*1 PC REAR BUMPER LH REFLECTOR	0.00	0.00	*40.00 F	2
7	1		*1 PC REAR BUMPER RH REFLECTOR	0.00	0.00	*40.00 F	X
8	1		*1 PC REAR RH FENDER WHEEL ARCH TRIM	0.00	0.00	*55.00 F	X
9	1		*1 PC TAILGATE	0.00	0.00	*570.00 F	C
10	1		*2 PCS TAILGATE DAMPER STRUT @90/PC	0.00	0.00	*180.00 F	X
11	1		*1 PC TAILGATE EMBLEM (VEZEL)	0.00	0.00	*35.00 F	C
12	1		*1 PC TAILGATE OUTER GARNISH	0.00	0.00	*125.00 F	C
13	1		*1 PC TAILGATE OUTER GARNISH EMBLEM (H)	0.00	0.00	*15.00 F	C
14	1		*1 PC TAILGATE REFLECTOR LH	0.00	0.00	*138.00 F	C
15	1		*1 PC TAILGATE REFLECTOR RH	0.00	0.00	*138.00 F	C
16	1		*1 PC TAILGATE INNER TRIM BOARD	0.00	0.00	*105.00 F	C
17	1		*1 PC TAILGATE INNER TRIM BOARD LH UPPER	0.00	0.00	*25.00 F	X
18	1		*1 PC TAILGATE INNER TRIM BOARD RH UPPER	0.00	0.00	*25.00 F	X
19	1		*1 PC TAILGATE INNER PULL POCKET	0.00	0.00	*20.00 F	C
20	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	*75.00 F	C
21	1		*1 PC LH TAILLAMP	0.00	0.00	*270.00 F	C
22	1		*1 PC RH TAILLAMP	0.00	0.00	*270.00 F	C
23	1		*1 PC 3RD BRAKE LAMP	0.00	0.00	*130.00 F	X
24	1		*1 PC REAR NUMBER PLATE LAMP	0.00	0.00	*20.00 F	X
25	1		*1 PC SPARE TYRE PANEL	0.00	0.00	*490.00 F	X
26	1		*1 PC SPARE TYRE TOP COVER BOARD	0.00	0.00	*155.00 F	X
27	1		*1 PC REAR FENDER INNER TRIM LH	0.00	0.00	*185.00 F	X
28	1		*1 PC REAR FENDER INNER TRIM RH	0.00	0.00	*185.00 F	X
29	1		*10 PCS REAR FENDER INNER TRIM CLIPS @2/PC	0.00	0.00	*20.00 F	X
30	1		*1 PC REAR END PANEL	0.00	0.00	*290.00 F	C
31	1		*1 PC REAR END PANEL INNER TRIM	0.00	0.00	*55.00 F	C
32	1		*1 PC REAR WIPER ARM	0.00	0.00	*45.00 F	C
33	1		*1 PC REAR WIPER ARM COVER	0.00	0.00	*8.00 F	C
34	1		*1 PC REAR WIPER BLADE	0.00	0.00	*42.00 F	C
35	1		*1 PC REAR WIPER MOTOR	0.00	0.00	*115.00 F	C
36	1		*1 PC REAR EXHAUST MUFFLER	0.00	0.00	*370.00 F	X
37	1		*1 PC REAR EXHAUST MOUNTING	0.00	0.00	*13.00 F	X
38	1		*1 PC REAR TOOL BOX TRAY	0.00	0.00	*105.00 F	X
39	1		*1 PC REAR WINDSCREEN GLASS	0.00	0.00	*450.00 F	C
40	1		*1 SET REAR WINDSCREEN GLASS MOULDING	0.00	0.00	*60.00 F	C

F=Franchise part.

Total Parts (S\$)

5,211.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	1 PC REAR BUMPER LOWER SKIRT EXTENSION	250.00
2	1	1 PC REAR CAMERA	320.00
3	1	1 PC REAR FLOOR RUBBER TRAY	220.00
4	1	1 PC REAR NUMBER PLATE	35.00
5	1	1 PC REAR WINDSCREEN GLASS SEALANT	40.00

No	Qty	Particulars	Amount
6	1	1 SET REVERSE CAMERA	350.00 ✓
7	1	1 SET REVERSE SENSOR	200.00 ✓
Sub Total (\$\$)			1,415.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING	New	50.00 ✓
2	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00 ✓
3	REMOVE & REFIX SEAT ASSY,CARPET,GARNISH, TOP ROOF LINING AND WASH CUSHION	New	120.00 100d
4	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER ASSY, LOCK ASSY, TOP SPOILER, LOWER SKIRT, TO CUT, WELD & RENEW REAR END PANEL, REAR COMPARTMENT, TO STRAIGHTEN, KNOCK & REPAIR REAR BOTH CHASSIS, REAR BOTH FENDERS AND REALIGN THE SAME	New	1,300.00 7 100d
5	REMOVE & REFIX REAR EXHAUST AND CHECK SYSTEM	New	60.00 ✓
6	PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL, REAR BOTH FENDERS, TAILGATE, REAR COMPARTMENT	New	1,300.00 100d
7	REMOVE & REFIX REAR SENSORS, REVERSE CAMERA, CCTV CAMERA, SMART KEY AND RESET SYSTEM	New	50.00 ✓
8	RUSTPROOFING	New	90.00 60d
Gross Labour Cost (\$\$)			3,090.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7018  
5614.40

6578  
3662.40

6277.40

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 226J

### Vehicle Details

Vehicle No.: SLC9421B  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 26 Jul 2022  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X CVT  
Primary Colour: Blue  
Manufacturing Year: 2016  
Engine No.: L15B4037508  
Chassis No.: RU11117505  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$20,662.00  
Original Registration Date: 30 May 2016  
First Registration Date: 30 May 2016  
Transfer Count: 2  
Actual ARF Paid: \$10,927.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 May 2026  
PARF Rebate Amount: \$7,102.00

### Intended COE Rebate Details

COE Expiry Date: 29 May 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$47,889.00  
COE Rebate Amount: \$18,396.00  
**Total Rebate Amount: \$25,498.00**

The information contained herein is correct as at 26 Jul 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	27/07/2022 18:16 (SGT)
Reported by	Both
Date of Accident	26/07/2022 09:15 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	MIDDLE ROAD /BENCOOLEN STREET
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC9421B
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YEONG KIM WENG
NRIC No	SXXXX226J
Email Address	sandyow469@gmail.com
Mobile Phone No	(Phone) +65-96411979
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

#### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number	5122748873-01

#### DRIVER

Name of Driver	LOW POH NYUK
NRIC No	SXXXX595F
Date Of Birth	02/10/1966
Occupation	Outdoor

Date Of Driving Pass	08/07/1989
Driving experience	33 YEARS
Gender	Female
Mobile Number	(Phone) +65-90401228
Alt. Phone Number	-
Email Address	sandyLOW469@gmail.com
Address	BLK 476A YISHUN ST. 44
Address complement	09-30
Postcode	761476
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	DRIZZLING
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Woodlands Division Headquarters
Police Station Phone No	(Phone) +65-18004660000
Police Station Address	1 Woodlands St 12 Singapore 738622
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER POLICE REPORT ATTACH

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	SD CARD WITH TRAFFIC POLICE

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8563U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	Yellow
Vehicle Category	Commercial vehicle
Name of Driver	CHUA PEI XIN
NRIC No	SXXXX502D
Contact Number	(Phone) +65-94516845
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT
Details of property damaged in accident	FRONT
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	LOW POH NYUK
Gender	Female
Phone No	(Phone) +65-90401228
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK/ CHEST/ HEAD
Injured person in which vehicle?	SLC9421B
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes


MT/118 1928

Describe Circumstance of the Accident

\*\* NOTE PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

( ) Claim Own Policy ( ☒ ) Claim Third party ( ) Reporting Only  
( ) Claim OD/ TP at other workshop ( )

Sketch Plan



Pls refer Police Report

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

27/7/22

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

YS

### SKETCH PLAN

VEH NO: SLC9471B  
INSURER: N7ue  
DATE OF ACC: 26/7/22 @ 9.15am

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

### Sketch Plan

PLEASE  
TURN  
OVER



**SINGAPORE  
POLICE FORCE**



L/20220726/7045

1 of 2

**POLICE REPORT (NP299)**

Report No. L/20220726/7045

Police Station Of Origin  
Woodlands Division HQ  
1 Woodlands Street 12 SINGAPORE 738622  
Tel No:1800-4660000

Date/Time Report Made 26/07/2022 19:23	Vide Report No.	Station Diary No.
Name Of Informant LOW POH NYUK	Address 476A YISHUN STREET 44 #09-30 SINGAPORE 761476	
ID Type / ID No. NRIC NO / S1752595F	Contact No. Home/Office: 90401228	Mobile: 90401228
Nationality SINGAPORE CITIZEN	Email Address SANDYLOW469@GMAIL.COM	
Occupation Customer service officer/clerk	Sex Female	Age 55
Institution/School Name	Date of Birth 02/10/1966	Race Chinese
Date/Time Of Incident 26/07/2022 09:10 - 26/07/2022 09:15	Location Of Incident 476A YISHUN STREET 44 #09-30 SINGAPORE 761476	

**Brief details.**

On 26 July 2022, at about 9.15am, I was driving my vehicle bearing vehicle registration number SLC9421B at MIDDLE ROAD. As I was approaching the traffic light, it turned from amber to red, I then came to a complete stop.

While I was waiting for the traffic light to turn green, suddenly a vehicle came from behind and slammed into the rear of my car. I felt a great impact and I was thrown forward despite wearing my seat belt. I hit my head and I lost consciousness. After I regain conscious. I felt extreme pain in my neck, chest and my head felt very heavy. I was then conveyed to Raffles Hospital and currently warded in Raffles Hospital ICU.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/07/2022 19:23
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE  
POLICE FORCE**



L/20220726/7045

2 of 2

**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

**Report No. L/20220726/7045**

\*There is an in-car camera in my vehicle and traffic police already taken the footage.

This is the first time such an incident happened, I am reporting this incident as I am a victim of a traffic accident and for my insurance claim.

Subjects Involved			
Victim			
Person Name	LOW POH NYUK		
ID Type	NRIC NO	ID No	S1752595F
Gender	Female	Age	55
Race	Chinese	Language	English
Occupation	Customer service officer/clerk	Address	476A YISHUN STREET 44 #09-30 SINGAPORE 761476
Mobile No	90401228	Is Informant A Victim?	Yes
Person Name	LOW POH NYUK (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/07/2022 19:23
Officer In-Charge Of Case:	Classification Of Case:



24 Hours Towing Services

# Efficient Towing Services

402B Fernvale Lane #22-229 Singapore 792402

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

bizSAFE<sub>3</sub>

NO. 105569

## CASH SALE / JOB ORDER

Date: 26/7/22

Messrs: CHEN HOF  
车牌 SLC 9421B 车型 HONDA  
Vehicle No. SLC 9421B Model No. HONDA  
时间 (日/夜) 1140 联络号码 96411979  
Time (day/night): 1140 Contact No: 96411979  
由 MIDDLE RD  
Location: MIDDLE RD  
到 1019 YISHUN #01-374  
To: 1019 YISHUN #01-374  
银额 501 其他   
Cash \$ 501 Others:   
经手人 DENIA Tow Truck 730  
Authorised By: DENIA Driver Name: 730

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.