




# Service Request Details

Claim

S2M043CZ

Reference

None 

Loss Date

2 June 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

7 Jun 2022 8:36:20 AM

Request Date

2 August 2022

Due Date

10 August 2022

Services

Pre-Repair Survey

## Actions

---

Next Step

Agree to perform service

Accept Work

### Vehicle Information

Incident Vehicle Registration #  
FBN8385P

Make  
TPVD Sym

Model  
VF3I

### Service Address

, , ,

### Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

### Claim Handler

HO Winnie  
  
winnie.ho@axa.com.sg

### Additional Instructions

TYPE



SENT

2/8/22 3:39 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

THANK YOU FOR THE ASSIGNMENT

BODY

DEAR WINNIE, THANK YOU FOR THE ASSIGNMENT

