

ASS. REC. BY:

REF: AIS/Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

Cheng Hoe

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Good

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: R 71K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 1.01 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SKW8560XYr Regn: 11, 15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: ToyC.C. 1986Colour: h. Black

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: 91077

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ESU600056728Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 235/60R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 29/7/22D.O.I. 2/8/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt wheel, wheel pillar, bonnet beam

The U/C / Chassis frame / Body Structure affected due to collision.

damage at the time of inspection. The cause of  
damage due to fallen tree trunk

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trlp: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

Tech Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)



SKW 8560X

OD/Allianz

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT WINDSCREEN GLASS WITH MOULDING	CM 0.00	0.00	*700.00 F ✓
2	1		*1 PC LH DOOR SIDE MIRROR	0.00	0.00	*320.00 F 7
3	1		*1 PC LH DOOR SIDE MIRROR COVER	0.00	0.00	*45.00 F 7
4	1		*1 PC DASHBOARD	0.00	0.00	*750.00 F 7
Sub Total (\$)						1,815.00
+ Margin on L,N Items 10.00% (\$)						181.50
Total Parts (\$)						1,996.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC ERP BRACKET	26.00 ✓
2	1	1 PC FRT WINDSCREEN GLASS SEALANT	40.00 ✓
Sub Total (\$)			66.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE & REFIX FRT WINDSCREEN GLASS	New	100.00 ✓
2	REPAIR LH FRONT W/SCREEN PILLAR,BONNET,LH FRONT FENDER AND REALIGN THE SAME	New	550 650.00
3	PUTTY & RESPRAY ON BINNET,FRT LH FENDER,SIDE MIRROR,COVER,LH W/SCREEN PILLAR, TOP ROOF PANEL	New	850 980.00
4	REMOVE & REFIX DASHBOARD	New	250 280.00
5	TO VACUUM & CLEAN UP GLASS SPLINTERS	New	50 80.00
Gross Labour Cost (\$)			2,090.00

Cheng Hoe Motor Pte Ltd/SKW8560X/02/08/2022 11:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Allianz Insurance Singapore Pte. Ltd. (HQ)

## DETAILS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2001875801-01	Date of Loss:	29/07/2022
Vehicle Reg. No.:	SKW8560X	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIM CHUN WEI		
Driver:	SIM CHUN WEI		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	18/11/2015
Vehicle Colour:	BLACK		
Engine No:	3ZRB633915	Chassis No:	ZSU600056728
Odometer:	0 KM		

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 0

*NOT Authorized  
Repair After Repair  
Ex @ 600h*

Remarks: VEHICLE CURRENTLY LYING YISHUN WORKSHOP.  
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

*5 days*

## COST OF CLAIMS

	Amount
Parts	1,996.50
Miscellaneous Items	66.00
Labour	2,090.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>4,152.50</b>
<b>+ GST 7.00% (\$)</b>	<b>290.68</b>
<b>Nett Amount (\$)</b>	<b>4,443.18</b>

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 486F

### Vehicle Details

Vehicle No.: SKW8560X  
Vehicle to be Exported: No  
Intended Deregistration Date: 01 Aug 2022  
Vehicle Make: TOYOTA  
Vehicle Model: HARRIER ELEGANCE 2.0 A  
Primary Colour: Black  
Manufacturing Year: 2015  
Engine No.: 3ZRB633915  
Chassis No.: ZSU600056728  
Maximum Power Output: 111.0 kW (148 bhp)  
Open Market Value: \$27,305.00  
Original Registration Date: 18 Nov 2015  
First Registration Date: 18 Nov 2015  
Transfer Count: 3  
Actual ARF Paid: \$25,227.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 17 Nov 2025  
PARF Rebate Amount: \$16,397.00

### Intended COE Rebate Details

COE Expiry Date: 17 Nov 2025  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$57,501.00  
COE Rebate Amount: \$18,943.00  
Total Rebate Amount: \$35,340.00

The information contained herein is correct as at 01 Aug 2022

OK



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	01/08/2022 17:36 (SGT)
Reported by	Both
Date of Accident	29/07/2022 19:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	NORTH BRIDGE RD BLK 467 OPEN CAR PARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8560X
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIM CHUN WEI
NRIC No	SXXXX486F
Email Address	junnweii18@gmail.com
Mobile Phone No	(Phone) +65-90676948
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	HARRIER ELEGANCE 2.0 A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1986

### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2001875801-01

### DRIVER

Name of Driver	SIM CHUN WEI
NRIC No	SXXXX486F
Date Of Birth	15/02/1996
Occupation	Indoor



# SINGAPORE POLICE FORCE

## POLICE REPORT (NP299)

Police Station Of Origin  
Bedok Division HQ  
30 Bedok North Road SINGAPORE 469676  
Tel No:1800-2440000



G/20220801/7050

1 of 2

Report No. G/20220801/7050

Date/Time Report Made 01/08/2022 16:18		Vide Report No.		Station Diary No.	
Name Of Informant SIM CHUN WEI		Address 334A YISHUN STREET 31 #08-93 SINGAPORE 761334			
ID Type / ID No. NRIC NO / S9605486F		Contact No. Home/Office: Mobile: 90676948			
Nationality SINGAPORE CITIZEN		Email Address JUNNWEI18@GMAIL.COM			
Occupation IT support technician		Sex Male	Age 26	Date of Birth 15/02/1996	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 29/07/2022 09:00 - 29/07/2022 19:00		Location Of Incident 334A YISHUN STREET 31 #08-93 SINGAPORE 761334			

### Brief details.

A thick tree trunk fell on Friday 29july 2022 while I was not around when the car was parked nearby ica my usual spot when I'm working with ica. Upon returning, I realised the windscreen was damage along with a tree trunk right infront of my car. It was raining heavily at that point in time.

Subjects Involved			
Victim			
Person Name	SIM CHUN WEI		
ID Type	NRIC NO	ID No	S9605486F

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
01/08/2022 16:18

Classification Of Case: